BENCH MARK DESCRIPTIONS AND ELEVATIONS STEUBEN COUNTY

Angola East Quadrangle

ELEVATION FEET (M.S.L.)

DNR TBM SLK 52 1977 Berlien Ditch Pigeon Creek

In Steuben County, in the SE ¼ Sec. 28, T. 37 N., R. 14 E., 2nd PM, about 0.5 mile west of Ellis; 0.5 mile west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road north (350 East Road); set in the southwest side of utility pole #92 in the northeast quarter of the junction, 48.5 feet north from the center line of the highway, 47.5 feet east from the center line of the T-road north, 0.6 foot above the ground; a railroad spike.

Destroyed 5-82-2 R.W.W. 1007.127

DNR TBM SLK 304 1978 Cedar Lake

In Steuben County, in the <u>SW ¼ Sec. 24, T. 38 N., R. 14 E., 2nd PM</u>, about 2.75 miles east of <u>Fremont</u>; 2.8 miles east along State Road 120 from its intersection with State road 827 in Fremont to a north-south crossroad (600 East Road); set in the south side of an 8-inch trunk of a twin-trunk tree, 103 feet north from the center line of the highway, 19.9 feet east from the center line of the road, 0.4 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 304".

1072.931

DNR TBM SLK 305 1978 Cedar Lake

In Steuben County, in the NE ½ Sec. 27, T. 36 N., R. 14 E., 2nd PM, about 1.7 miles east of Fremont; 1.7 miles east along State Road 120 from its intersection with State Road 827 in Fremont to an east-southeast Y-junction and a private drive south; set in the north side of power pole #494/986, 42.5 feet south from the center line of the highway, 36.8 feet west from the center line of the private drive, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 305 1978".

USC&GS RM No. 2 Clear 1946 Cedar Lake

In Steuben County, in the SW 1/4 Sec. 22, T. 38 N., R. 14 E., 2nd PM, about 1.05 miles east of Fremont; 1.05 miles east along State Road 120 from its intersection with State Road 827 in Fremont to a driveway north; set in the top of a concrete post in the northwest quarter of the junction, 262 feet west from the center line of the drive, 53 feet north from the center line of the highway, 48 feet northwest from power pole #481-003, 6.0 feet above the highway, 1.8 feet southeast from power pole #481-003, 6.0 feet above the highway, 1.8 feet southeast from a steel witness post, 0.1 foot above the ground; a U.S. Coast and Geodetic Survey reference mark tablet, stamped "CLEAR No. 2 1946".

1077.420

USC&GS BM X21 1934 Cedar Lake

In Steuben County, in the N½ Sec. 22, T. 38 N., R. 14 E., 2nd PM, about 1.55 miles northeast of Fremont; 0.5 mile east along State Road 120 from its intersection with State Road 827 in Fremont to a northeast-southwest railroad (New York Central Railroad), thence 1.15 miles northeast to an east-west field road; set in the top of a concrete post in the southwest quarter of the intersection, at the northeast end of a railroad cut, 90 feet north from an east-west fence line, 15.5 feet northwest from the northwest rail, 11.0 feet southwest from the center line of the road, 1.2 feet below the tracks, 0.7 foot above the ground; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "X21 1934".

1077.174

DNR TBM SLK 65 1978 Cemetery Lake

In Steuben County, in the SW ½ Sec. 28, T. 38 N., R. 14 E., 2nd PM, about 0.5 mile south of Fremont; 0.52 mile south along State Road 827 from its intersection with State Road 120 in Fremont to a T-road west (550 North Road); set in the southwest side of a 24-inch cottonwood tree in the southwest quarter of the junction, 114 feet west from the center line of the highway, 44.0 feet south from the center line of the T-road, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DRN TBM SLK 65 1978".

DNR BM STE 36 1977 Cemetery Lake

In Steuben County, in the NE ¼ Sec. 32, T. 38 N., R. 14 E., 2nd PM, about 1.27 miles south of Fremont; 1.3 mile south along State Road 827 from its intersection with State Road 120 in Fremont to a 25-foot concrete bridge over the outlet channel for Cemetery Lake; set in the top of the south end of the west channel for Cemetery Lake; set in the top of the south end of the west headwall of the bridge, 17.1 feet west from the center line of the highway, 0.7 foot north from the south end of the headwall, 0.7 foot above the highway; a Department of Natural Resources brass control station tablet, stamped "STE 36 1977".

USC&GS BM Z 21 1934 Cemetery Lake

In Steuben County, in the NE ¼ Sec. 6, T. 37 N., R. 14 E., 2nd PM, about 2.4 miles southwest of Fremont; 2.3 miles generally south along State Road 827 from its intersection with State Road 120 in Fremont to a T-road west (400 North Road), thence 0.2 mile west to a northeast-southwest railroad (New York Central Railroad); set in the top of a concrete post in the southeast quarter of the intersection, 47.0 feet south from the center line of the road, 45.4 feet southeast from the southeast rail, 2.0 feet northwest from a fence, 1.6 feet below the tracks, 0.6 foot above the ground; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "Z 21 1934".

DNR TBM OL 2 Center Lake

In Steuben County, in the S $\frac{1}{2}$ Sec. 14, T. 37 N., R. 13 E., 2^{nd} PM, about 1.55 miles north of Angola; 1.55 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road); set in the top at the center of the north concrete headwall of a culvert under the road in the northeast quarter of the intersection, 45.0 feet east from the center line of the highway, 16 feet north from the center line of the T-road west; a chiseled triangle.

DNR TBM SLK 703 1977 Crooked Lake

In Steuben County, in the <u>NW ¼ Sec. 13, T. 37 N., R. 13 E., 2nd PM,</u> about 2.7 miles north-northeast of <u>Angola</u>; 2.55 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (200 North Road), thence 0.9 mile east to a northeast-southwest railroad crossing (New York Central Railroad); set in the north side of a utility pole in the southwest quarter of the intersection, 67 feet northwest from the northwest rail, 21.2 feet south from the center line of the road, 1.0 foot above the ground; a railroad spike.

DNR TBM OL 1 Crooked Lake

In Steuben County, in the S $\frac{1}{2}$ Sec. 11, T. 37 N., R. 13 E., 2^{nd} PM, about 2.55 miles north of Angola; 2.55 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (200 North Road); set in the south side of power pole #485/182 in the northwest quarter of the intersection, 45.0 feet north from the center line of the road, 45.0 feet west from the center line of the highway, 0.3 foot above the ground; a 60d nail.

DNR TBM SLK 64 1978 Eaton Lake

In Steuben County, in the <u>SW ½ Sec. 29, T. 38 N., R. 14 E., 2nd PM</u>, about 1.0 mile west-southwest of <u>Fremont</u>; 0.52 mile south along State Road 827 from its intersection with State Road 120 in the Fremont to a T-road west (550 North Road), thence 0.8 mile west to a lone tree on the south side of the road; set in the north side of an 18-inch hickory tree, 103 feet southeast from power pole #495/076, 18.5 feet south from the center line of the road, 0.7 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 64 1978".

DNR BM STE 37 1977 Eaton Lake

In Steuben County, in the <u>SE ¼ Sec. 30, T. 38 N., R. 14 E., 2nd PM,</u> about 1.44 miles west-southwest of <u>Fremont</u>; 0.52 mile south along State Road 827 from its intersection with State Road 120 in Fremont to a T-road west (550 North Road), thence 1.18 miles west to a turn south, thence 0.2 mile south to a culvert under the road; set in the top of a concrete post, 98 feet north from the center line of the culvert, 15.4 feet west from the center line of the road, 1.9 feet south from power pole #495/245, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 37 1977".

DNR TBM SLK 63 1978 Eaton Lake

In Steuben County, in the SE ¼ Sec. 30, T. 38 N., R. 14 E., 2nd PM, about 1.52 miles southwest of Fremont; 0.52 mile south along State Road 827 from its intersection with State Road 120 in Fremont to a T-road west (550 North Road), thence 1.18 miles west to a turn south, thence 0.38 mile south to an overpass bridge (Indiana Toll Road); set in the top of the north end of the west concrete guardrail base, 14.0 feet west from the center line of the road, 2.3 feet above the roadway, 0.1 foot south from the north end of the guardrail, 0.1 foot west from the east face of the guardrail; a chiseled triangle.

1033.591

DNR TBM SLK 62 1977 Eaton Lake Marsh Lake

In Steuben County, in the <u>SE ½ Sec. 30, T. 38 N, R. 14 E., 2nd PM</u>, about 1.73 miles southwest of <u>Fremont</u>; 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (100 East Road), thence 1.0 mile south to an east-west crossroad (500 North Road), thence 0.57 mile east to a 3-foot steel pipe culvert under the road; set in the south side of a 12-inch ash tree on the north side of the road, 50.0 feet west from the center line of the culvert, 18.7 feet north from the center line of the road, 2.4 feet below the roadway, 0.7 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 62 1977".

DNR TBM SLK 701 1977 Eaton Lake Cemetery Lake

In Steuben County, in the NE ½ Sec. 32, T. 38 N., R. 14 E., 2nd PM, about 1.4 miles southwest of Fremont; 1.5 miles generally south along State Road 827 from its intersection with State Road 120 in Fremont to a private farm lane northwest, thence 0.24 mile northwest to twin highway bridges over the New York Central Railroad from the Indiana East-West Toll Road; set in the south side of NIPSCO power pole #481/499, 86 feet northwest from the northwest face of the northwestern-most bridge pier, 47.4 feet northwest from the northwest rail, 7.5 feet southwest from the center line of the farm lane, 0.3 foot above the ground; a railroad spike.

DNR TBM SLK 67 1978 Fish Lake

In Steuben County, in the NW ¼ Sec. 21, T. 38 N., R. 14 E., 2nd PM, about 1.01 mile north of Fremont; 1.02 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road west (700 North Road); set in the west side of a 14-inch walnut tree in the southwest quarter of the junction, 48.0 feet south from the center line of the T-road west, 19.8 feet west from the center line of the north-south road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 67 1978".

USGS RM Gaging Station Fish Lake

In Steuben County, in the NW ¼ Sec. 21, T. 38 N., R. 14 E., 2nd PM, about 1.01 miles north of Fremont; 1.02 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road west, (700 North Road); set in the top of a concrete fence corner post in the southeast quarter of the junction, 23.6 feet south from the extended center line of the T-road west, 20.5 feet east from the center line of the north-south road, 3.5 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped .

USGS RM Gaging Station Fish Lake

In Steuben County, in the <u>SW ½ Sec. 16, T. 38 N., R. 14 E., 2nd PM</u>, about 1.01 miles north of <u>Fremont</u>; 1.02 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road west (700 North Road); set in the top of a concrete right-of-way marker in the northeast quarter of the junction, 25.0 feet north from the extended center line of the T-road west, 20.5 feet east from the center line of the north-south road, 1.6 feet above the ground, 0.1 foot north from a wooden fence corner post; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 75 1978 Fish Lake

In Steuben County, in the NE ¼ Sec. 20, T. 38 N., R. 14 E., 2nd PM, about 1.05 miles north-northwest of Fremont; 1.03 miles north along Wayne Street (State Road 827) from its intersection with State Road 120 in Fremont to a T-road west (700 North Road), thence 0.35 mile west to a north-south crossroad (Blackman Road); set in the north side of a 44-inch oak tree in the southwest quarter of the intersection, 37.6 feet west from the center line of the north-south road, 18.8 feet south from the center line of the east-west road, 0.9 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 75 1978".

DNR TBM SLK 66 1978 Fish Lake

In Steuben County, in the <u>SW ¼ Sec. 21, T. 38 N., R. 14 E., 2nd PM</u>, in <u>Fremont</u>; 0.21 mile north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road west (Michael Street); set in the east side of a power pole in the northeast quarter of the junction, 130 feet north from the extended center line of the T-road west, 16.5 feet east from the center line of the road, 1.0 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 66 1978".

DNR BM STE 80 1978 Green Lake

In Steuben County, in the NW ¼ Sec. 26, T. 38 N., R. 13 E., 2nd PM, about 1.85 miles southeast of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (old U.S. Highway 27), thence 1.5 miles south to an 18-inch steel pipe culvert under the highway in the outlet for Green Lake; set in the top of the north end of the east concrete guardrail of the north bound Interstate 69 bridge over Green Lake on the east side of the highway, 21.3 feet east from the center line of the north bound bridge, 1.9 feet above the bridge surface, 0.5 feet south from the north end of the guardrail; a Department of Natural Resources brass control station tablet, stamped "STE 80 1978".

DNR TBM SLK 702 1977 Lake Charles

In Steuben County, in the NW ¼ Sec. 7, T. 37 N., R. 14 E., 2nd PM, about 3.9 miles north-northeast of Angola; 3.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road east (300 North Road), thence 1.52 miles east to a northeast-southwest railroad crossing (New York Central Railroad); set in the northeast side of NIPSCO power pole #490/661 in the southwest quarter of the intersection, 81 feet west from the northwest rail, 15.1 feet south from the center line of the road, 0.7 foot above the ground; a railroad spike.

DNR TBM SLK 57 1977 Little Center Lake

In Steuben County, in the SW ¼ Sec. 24, T. 37 N., R. 13 E., 2nd PM, about 1.0 mile northeast of Angola; 1.5 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (100 East Road), thence 0.7 mile north to an east-west crossroad (20 North Road), thence 0.77 mile west to a T-road (Eastland Drive); set in the north side of a utility pole, 162 feet east from a utility pole, 19.8 feet north from the center line of the east-west road, 0.8 foot above the ground; a railroad spike.

DNR TBM SLK 704 1977 Little Center Lake Middle Center Lake In Steuben County, in the NW ¼ Sec. 36, T. 37 N., R. 13 E., 2nd PM, in Angola; 0.75 mile north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a northeast-southwest railroad crossing (New York Central Railroad); set in the east side of a utility pole, 346 feet southwest from the intersecting center lines of the road and railroad, 49.5 feet northwest from the northwest rail, 0.8 foot above the ground; a railroad spike.

DNR BM STE 41A 1977 Marsh Lake

In Steuben County, in the <u>SE ¼ Sec. 25, T. 38 N., R. 13 E., 2nd PM</u>, about 2.3 miles west-southwest of <u>Fremont</u>; 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (100 East Road), thence 1.0 mile south to an east-west crossroad (500 North Road); set in the top of a concrete post in the northwest quarter of the intersection, 405 feet west from the center line of the north-south road, 21.0 feet north from the center line of the east-west road, 2.0 feet above the roadway, 1.3 feet east from a power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 41A 1977".

DNR TBM SLK 61 1977 Marsh Lake

In Steuben County, in the NE ¼ Sec. 36, T. 38 N., R. 13 E., 2nd PM, about 2.4 miles west-southwest of Fremont; 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (100 East Road), thence 1.0 mile south to an east-west road (500 North Road), thence 0.22 mile generally west to a T-road south; set in the north side of a 16-inch walnut tree in the northwest quarter of the junction, 29.6 feet north from the center line of the road, 28.5 feet west from the extended center line of the T-road, 2.5 feet below the roadway, 0.6 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 61 1977".

DNR TBM SLK 59 1977 Marsh Lake Seven Sisters Lake

In Steuben County, in the <u>SE ½ Sec. 26, T. 38 N., R. 13 E., 2nd PM,</u> about 3.36 miles southwest of <u>Fremont</u>; 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (100 East Road), thence 1.0 mile south to an east-west crossroad (500 North Road), thence 1.4 miles generally west to a dirt T-road northeast leading to Wetlands Conservation Area; set in the south side of a 15-inch twin trunk oak tree in the northwest quarter of the junction, 72 feet northwest from the center line of the T-road northeast, 22.7 feet northeast from the center line of the road, 2.3 feet above the roadway, 0.6 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 59 1977".

DNR TBM SLK 51 1977 Pigeon Creek

In Steuben County, in the NE ½ Sec. 33, T. 37 N., R. 14 E., 2nd PM, about 0.25 mile south of Ellis; 0.25 mile south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to a steel pipe culvert under the road in a field drainage ditch; set in the top of the southwest end of the culvert, 34.2 feet west from the center line of the highway, 7.0 feet northeast from the southwest end of the culvert, 0.3 foot below the roadway; the center of two filed notches.

DNR TBM SLK 53 1977 Pigeon Creek Pigeon Lake

In Steuben County, in the SE ¼ Sec. 29, T. 37 N., R. 14 E., 2nd PM, about 3.2 miles east of Angola; 3.3 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a concrete bridge over Pigeon Creek; set in the top of the northeast wingwall of the bridge, 22.3 feet north form the center line of the highway, 0.5 foot above the roadway, 0.4 foot southeast from the streamward side of the wingwall; a chiseled star of David.

ISHC BM F 8 STUBN Pigeon Creek Pigeon Lake

In Steuben County, in the <u>SE ¼ Sec. 29, T. 37 N., R. 14 E., 2nd PM,</u> about 1.15 miles west of <u>Ellis</u>; 1.15 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a concrete bridge over <u>Pigeon Creek</u>; set in the top of the north end of the west bridge abutment, 21.9 feet north from the center line of the highway, 0.7 foot west from the east face of the abutment, 0.6 foot above the highway; an Indiana State Highway Commission bench mark tablet, stamped "F 8 STUBN".

DNR TBM SLK 54 1977 Pigeon Lake

In Steuben County, in the SW ¼ Sec. 29, T. 37 N., R. 14 E., 2nd PM, about 2.3 miles east of Angola; 2.3 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 to a north-south crossroad (200 East Road); set in the top of a steel pipe culvert headwall in the northeast quarter of the intersection, 20.5 feet north from the center line of the highway, 17.5 feet east from the center line of the road, 0.5 foot south from the north edge of the headwall, 0.4 foot west from the east edge of the headwall, 0.1 foot below the roadway; a chiseled diamond.

DNR BM STE 39 1977 Pigeon Lake

In Steuben County, in the NW ¼ Sec. 29, T. 37 N., R. 14 E., 2nd PM, about 2.35 miles east of Angola; 2.3 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 East Road), thence 0.6 mile north to a T-road east leading to a public fishing site for Pigeon Lake; set in the top of a concrete post in the northeast quarter of the junction, 43.6 feet north from a wooden property corner post, 19.1 feet north from the center line of the T-road east, 18.7 feet east from the center line of the north-south road, 0.2 foot above the ground; a Department of Natural Resources brass central station tablet, stamped "STE 39 1977."

USGS RM No. 4 Gaging Station Pigeon Lake

In Steuben County, in the <u>SE ¼ Sec. 29, T. 37 N., R. 14 E., 2nd PM,</u> about 1.9 miles west-northwest of <u>Ellis</u>; 2.0 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a north-south crossroad (200 East Road), thence 0.5 mile north to a T-road east leading to a Public Fishing Site for Pigeon Creek, thence 0.15 mile east to a concrete boat ramp; set in the top of a concrete lake level monument in the northwest quarter of the site, 104 feet west from the west end of the boat ramp, 37.6 feet south from the center line of the road, 5.0 feet east from a hedge row, 1.1 feet above the ground; a U.S. Geological gaging station tablet, stamped not stamped.

DNR TBM SLK 55 1977 Pigeon Lake

In Steuben County, in the SE ¼ Sec. 19, T. 37 N., R. 14 E., 2nd PM, about 2.4 miles east-northeast of Angola; 2.3 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 East Road), thence 0.85 mile north to an east-west crossroad (20 North Road), thence 0.1 mile west to a 15-inch elm tree on the north side of the road; set in the south side of the tree, 16.3 feet north from the center line of the road, 0.6 foot above the ground; a railroad spike.

DNR TBM SLK 56 1977 Pigeon Lake

In Steuben County, in the SE ¼ Sec. 24, T. 37 N., R. 13 E., 2nd PM, about 1.65 miles northeast of Angola; 1.5 miles east along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (100 East Road), thence 0.7 mile north to an east-west crossroad (20 North Road); set in the north side of a Co-op power pole in the northwest quarter of the intersection, 34.3 feet north from the center line of the east-west road, 21.5 feet west from the center line of the north-south road, 0.7 foot above the ground; a railroad spike.

DNR BM STE 38 1977 Seven Sisters Lakes Marsh Lake

In Steuben County, in the NW ¼ Sec. 36, T. 38 N., R. 13 E., 2nd PM, about 2.97 miles west-southwest of Fremont; 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (100 East Road), thence 0.9 mile generally west to a curve in the road; set in the top of a concrete post on the north side of the road, 19.7 feet north from the center line of the road, 1.6 feet east from a power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 38 1977."

DNR TBM SLK 60 1977 Seven Sisters Lakes

In Steuben County, in the NE ¼ Sec. 35, T. 38 N., R. 13 E., 2nd PM, about 3.2 miles west-southwest of Fremont, 2.0 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (500 North Road), thence 1.1 miles generally west to a private drive southwest; set in the top of a concrete base of a fence post in the southwest quarter of the junction, 20.6 feet west from the center line of the drive, 16.8 feet south from the center line of the road, 0.4 foot northeast from the northeast corner of the concrete fence corner post; a chiseled triangle.

976.406

DNR TBM SLK 76 1978 Walters Lake

In Steuben County, in the SE ¼ Sec. 18, T. 38 N., R. 14 E., 2nd PM, about 1.6 miles northwest of Fremont; 1.03 miles north along Wayne Street (State Road 827) from its intersection with State Road 120 in Fremont to a T-road west (700 North Road), thence 1.35 mile west to a north-south crossroad (200 East Road, Walters Road); set in the north side of a 14-inch hickory tree in the northwest quarter of the junction, 44.1 feet north from the extended center line of the east-west road, 19.7 feet west from the center line of the north-south road, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 76 1978."

DNR TBM SLK 78 1978 Walters Lake

In Steuben County, in the NE ¼ Sec. 19, T. 38 N., R. 14 E., 2nd PM, about 1.4 miles west-northwest of Fremont; 1.4 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road north (Walters Road, 200 East Road), thence 0.61 mile north to a T-road west, (660 North Road); set in the south side of a power pole in the northwest quarter of the junction, 103 feet west from the center line of the road, 26.4 feet north from the center line of the T-road west, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR SLK 78 1978."

1046.259

DNR TBM SLK 79 1978 Walters Lake

In Steuben County, in the NE ¼ Sec. T. 38 N., R. 13 E., 2nd PM, about 2.4 miles west-northwest of Fremont; 2.2 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road northwest (Van Guilder Road), thence 0.75 mile northwest and north to an east-west crossroad (660 North Road), thence 0.15 mile east to a 16-inch walnut tree on the west bank of a small drain on the north side of the road; set in the south side of the tree, 21.4 feet north from the center line of the road, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 79 1978."

DNR TBM SLK 80 1978 Walters Lake

In Steuben County, in the NE ¼ Sec. 38 N., R. 13 E., 2nd PM, about 2.6 miles west-northwest of Fremont; 2.2 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road northwest (Van Guilder Road), thence 0.87 mile northwest and north to a culvert under the road in the outlet channel for Walters Lake; set in the southwest side of a 52-inch cottonwood tree, 32.3 feet east from the center line of the road, 14.5 feet south from the center line of the culvert, 3.0 feet below the roadway, 1.2 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 80 1978."

DNR TBM SLK 81 1978 Walters Lake

In Steuben County, in the NW ¼ Sec. 24, T. 38 N., R. 13 E., 2nd PM, about 2.95 miles west-northwest of Fremont; 2.2 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road northwest (Van Guilder Road), thence 0.77 mile northwest and north to an east-west crossroad (660 North Road), thence 0.4 mile east to a concrete culvert under the road; set in the top of the east end of the south concrete guardrail of the culvert, 11.0 feet south from the center line of the road, 2.2 feet above the roadway, 1.0 feet west from the east end of the guardrail; a hollowed out chiseled triangle.

USC&GS Azimuth StationCLEAR 1946 unnamed lake

In Steuben County, in the NW ¼ Sec. 27, T. 38 N., R. 14 E., 2nd PM, 0.75 mile east of Fremont; 0.75 mile east along State Road 120 from its intersection with State Road 827 in Fremont to a driveway north; set in the top of a concrete post in the southwest quarter of the junction, 73 feet west from the extended center line of the drive, 51 feet south from the center line of the highway, 4.6 feet east from a power pole, 4.0 feet east from a fence corner post, 1.0 foot north from a fence line, flush with the ground; a U.S. Coast and Geodetic Survey azimuth mark tablet, stamped "CLEAR 1946."

DNR TBM SLK 700 1977 unnamed lake

In Steuben County, in the <u>SE ¹/₄ Sec. 21, T. 38 N., R. 14 E., 2nd PM, in Fremont;</u> 0.5 mile east along State Road 120 from its intersection with State Road 827 in Fremont to a northeast-southwest railroad crossing (New York Central Railroad); set in the southwest side of NIPSCO power pole #480/503, 53 feet southeast from the southeast rail, 29.2 feet north form the center line of the highway, 3.5 feet below the roadway; a railroad spike.

1056.811

Angola West Quadrangle

USGS RM No. 11 Gaging Station Bass Lake

In Steuben County, in the <u>NW ¼ Sec. 25, T. 37 N., R. 12 E., 2nd PM,</u> about 4.9 miles west of <u>Angola</u>; 4.9 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a group of three house trailers on the north side of the road and south shore of Bass Lake; set in the top of a concrete lake level monument in the back yard of the trailer court, 158 feet north from the center line of the highway, 110 feet north from power pole #481/102, 21.0 feet northeast from a 42-inch willow tree, 9.3 feet south from the south edge of the lake, 0.9 foot above the ground; a U.S. Geological Survey gaging station tablet, stamped not stamped.

Found Good Condition J.C.S. 1/15/87 982.647

DNR TBM SLK 109 1978 Bass Lake Destroyed 5-82 R.W.W.

In Steuben County, in the W½ Sec. 25, T. 37 N., R. 12 E., 2nd PM, about 5.3 miles west of Angola, 5.45 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road); set in the north side of guy wire pole #469/644 in the northeast quarter of the intersection, 49.2 feet north from the center line of the highway, 47.5 feet east from the center line of the road, 0.8 foot above the ground; a railroad spike drive thru an aluminum tag, stamped "DNR TBM SLK 109 1978."

DNR TBM SLK 110 1978 Bass Lake Could not locate J.C.S. 1/15/87 In Steuben County, in the NE ¼ Sec. 26, T. 37 N., R. 12 E., 2nd PM, 5.35 miles west of Angola; 5.3 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road), thence 0.5 mile north to a driveway east; set in the east side of power pole #469/654 in the northwest quarter of the junction, 78 feet north from the extended center line of the drive, 20.0 feet west from the center line of the road, 1.0 foot below the road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 110 1978."

1014.583

DNR TBM SLK 111 1978 Bass Lake Found Tree But No Mark J.C.S. 1/15/87 In Steuben County, in the SW ¼ Sec. 24, T. 37 N., R. 12 E., 2nd PM, about 5.4 miles west of Angola; 5.3 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road), thence 0.85 mile north to a T-road east (30 North Road); set in the west side of a 30-inch cottonwood tree in the northeast quarter of the junction, 74 feet north from the center line of T-road, 14.7 feet east from the center line of the road, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 111 1978."

Found Tree But no mark J.C.S. 1/15/87 1037.756

DNR TBM JL 6 1972 Bell Lake Found OK J.C.S. 1/15/87 In Steuben County, in the NE ¼ Sec. 36, T. 38 N., R. 12 E., 2nd PM, about 1.1 miles south-southwest of Nevada Mills; 0.10 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 0.28 mile generally east to a turn south (450 West Road), thence 0.77 mile south to a T-road west-southwest (Binkley Road), thence 0.6 mile generally west to a turn south (525 West Road); set in the north side of a 23-inch maple tree in the southeast quarter of the turn, 75 feet east from the north-south center line tangent, 18.5 feet south from the east-west center line tangent, 0.7 foot above the ground; a boat spike driven thru an aluminum tag, stamped "DNR TBM JL 6 1972."

DNR TBM JL 7 1972 Bell Lake

In Steuben County, in the NW ¼ Sec. 31, T. 38 N., R. 12 E., 2nd PM, about 1.0 mile south-southeast of Nevada Mills; 0.10 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 0.28 mile generally east to a turn south (450 West Road), thence 0.77 mile south to a T-road west-southwest (Binkley Road); set in the north side of a 10-inch walnut tree in the northwest quarter of the junction, 104 feet west-southwest from the center line of the road, 23.5 feet north-northwest from the center line of the road, 23.5 feet north-northwest from the center line of the roadway, 0.5 foot above the ground; a boat spike driven thru an aluminum tag, stamped "DNR TBM JL 7 1972."

DNR TBM SLK 100 1977 Bell Lake Ditch Crooked Creek Destroyed J.C.S. 1/15/87 In Steuben County, in the NW ¼ Sec. 25, T. 38 N., R 12 E., 2nd PM, about 1.1 miles west of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.15 miles west to a T-road north (600 West Road); set in the southwest side of a power pole in the northeast quarter of the junction, 48.0 feet east from the center line of the east-west road; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 100 1977."

DNR TBM SLK 100 RESET 1987-New Power @ same location 1.0 foot above ground pole 975.438

DNR TBM SLK 101 1977 Bell Lake Ditch Found OK J.C.S. 1/15/87 In Steuben County, in the E½ Sec. 26, T. 38 N., R. 13 E., 2nd PM, about 1.75 mile west of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles west to a north-south crossroad (675 West Road); set in the top of a eastern most 2.5 foot square concrete gate post in the southeast quarter of the intersection, 50 feet east from the center line of the north-south road, 20.0 feet south from the center line of the east-west road, 5.0 feet above the ground; a painted chiseled triangle.

DNR TBM SLK 15 1976 Big Otter Lake Could Not Locate Assumed Destroyed J.C.S. 1/15/87

In Steuben County, in the <u>NW ¼ Sec. 26, T. 38 N., R. 13 E., 2nd PM</u>, about 1.6 miles south-southeast of <u>Jamestown</u>, 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 1.25 miles south to an east-west crossroad (State Road 120), thence 0.15 mile west to a 4-foot steel pipe culvert under a paralleling dirt road on the south side of the highway, set in the top of the north end of the culvert, 53 feet south from the center line of the highway, 21.6 feet north from the center of two filed notches.

DNR TBM SLK 16 1976 Big Otter Lake Snow Lake

In Steuben County, in the N½ Sec. 27, T. 38 N., R. 13 E., 2^{nd} PM, about 1.4 miles south of <u>Jamestown</u>; 0.4 mile south along 150 West Road from its junction with Lake George at Jamestown to an east-west crossroad (700 North Road), thence 0.6 mile west to a northwest-southeast crossroad (State Road 120), thence 1.36 miles southeast and east to a 2-foot steel pipe culvert under the highway; set in the top of the south end of the culvert, 23.2 feet south from the center line of the highway, 2.0 feet below the highway; the center of two filed notches.

DNR BM STE 48 1977 Booth Lake *Found Ole J.C.S. 1/15/87*In Steuben County, in the NW ¼ Sec. 27, T. 37 N., R. 13 E., 2nd PM, about 1.28 miles west of Angola; 1.3 miles west along U.S. Highway 27 in Angola to a north-south crossroad; set in the top of a 48.2 feet north from the center line of the highway, 14.0 feet west from the center line of the road, 9.8 feet east from power pole #496/668, 1.1 feet south from the south post of an Angola Conservation Sign, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 48 1977."

DNR TBM SLK 83 1978 Booth Lake *Destroyed J.C.S. 1/15/87*In Steuben County, in the NW ¼ Sec. 27, T. 37 N., R. 13 E., 2nd PM, about 1.28 miles west of Angola; 1.3 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad; set in the south side of a power pole in the northwest quarter of the intersection, 50.4 feet north from the center line of the highway, 23.3 feet west from the center line of the highway, 23.3 feet west from the center line of the road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 83 1978."

DNR TBM SLK 104 1978 Buck Lake Could not Locate Assumed Destroyed J.C.S. 1/15/87

In Steuben County, in the <u>SW ½ Sec. 21, T. 37 N., R. 13 E., 2nd PM,</u> about 2.5 miles west-northwest of <u>Angola</u>; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Interstate 69), thence 0.75 mile north to a 55 mile-per-hour speed limit sign on the east side of the north bound lane of the Interstate; set in the top of the concrete base of the east leg of the sign, 28.4 feet east from the center line of the north bound lane, 2.0 feet below the interstate, 0.3 foot east from the east leg of the sign; a chiseled triangle.

DNR TBM SLK 116 1978 Center Lake

In Steuben County, in the NE ¼ Sec. 22, T. 37 N., R. 13 E., 2nd PM, about 1.5 miles north-northwest of Angola; 1.55 miles north along State Road 127 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (100 North Road), thence 0.75 mile west to a dirt T-road south leading to Center Lake, thence 0.25 mile south to the north edge of the lake; set in the west side of power pole #498/490, 325 feet north from the north edge of the lake, 16.0 feet east from the center line of the road, 0.2 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 116 1978."

DNR TBM SLK 117 1978 Center Lake

In Steuben County, in the NE ¼ Sec. 22, T. 37 N., R. 13 E., 2nd PM, about 1.5 miles north-northwest of Angola; 1.55 miles north along State Road 127 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (100 North Road), thence 0.75 mile west to a dirt T-road north leading to Center Lake, thence 0.25 mile south to the north edge of the lake; set in the north side of a 42-inch willow tree, 58 feet east from the extended center line of the road, 18 feet north from the north edge of the lake, 0.3 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 117 1978."

STEUBEN CO. Surv. DEPT. RP 19+69 Center Lake Crooked Lake In Steuben County, in the NW ¼ Sec. 22, T. 37 N., R. 13 E., 2nd PM, about 2.1 miles northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 1.5 miles west to a north-south crossroad (200 West Road); set in the top of a concrete post in the southeast quarter of the intersection, 60 feet south from the center line of the east-west road, 18.0 feet east from the center line of the north-south road; a Steuben County Survey Department reference point tablet, stamped "STEUBEN CO. SURV. DEPT. 16+69 REFERENCE POINT."

Steuben CO. SURV. DEPT. SEC COR 1969 Center Lake Crooked Lake In Steuben County, in the NW ¼ Sec. 22, T. 37 N., R. 13 E., 2nd PM, about 2.1 miles northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), 1.5 miles west to a north-south crossroad (200 West Road); set in the top of the roadway, 3.3 feet west from the center line of the north-south road, 2.3 feet north from the center line of the east-west road, level with the roadway; a brass plate, stamped STEUBEN CO SURV DEPT SECTION CORNER 19+69."

DNR BM STE 77 1978 Cheeseboro Lake

In Steuben County, in the <u>SW ¼ Sec. 19, T. 37 N., R. 13 E., 2nd PM</u>, about 4.3 miles west of <u>Angola</u>; 3.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road north to a T-road north (425 West Road), thence 0.95 mile north to an east-west crossroad (30 North Road), thence 0.25 mile west to a north-south crossroad (450 West Road), thence 0.33 mile south and southwest to a private farm drive southeast; set in the top of a concrete post in the southeast quarter of the junction, 181 feet northeast from the center line of the road, 9.0 feet southwest from power pole #469/685, 1.0 foot above the roadway, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 77 1977."

1026,477

DNR TBM SLK 113 1978 Cheeseboro Lake

In Steuben County, in the SW ¼ Sec. 19, T. 37 N., R. 13 E., 2nd PM, about 4.3 miles west of Angola; 3.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road north (425 West Road), thence 0.95 mile north to an east-west crossroad (30 North Road), thence 0.25 mile west to a north-south crossroad (450 West Road), thence 0.3 mile south and southwest to a field entrance gate: set in the south side of a 14-inch trunk of a twin trunk maple tree, 97 feet southwest from the center line of the field entrance gate, 19.5 feet northwest from the center line of the road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 113 1978."

DNR TBM OL 5 1969 Cheeseboro Lake Grass Lake

In Steuben County, in the N½ Sec. 19, T. 37 N., R. 13 E., 2^{nd} PM, about 4.25 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road); thence 4.0 miles west to a north-south crossroad (450 West Road); set in the north side of a power pole in the southeast quarter of the intersection, 27.0 feet east from the center line of the north-south road, 24.0 feet south from the center line of the east-west road; a 60 d nail.

1026.264

DNR TBM SLK 84 1978 Crockett Lake

In Steuben County, in the <u>SE ¼ Sec. 28, T. 37 N., R. 13 E., 2nd PM</u>, about 1.8 miles west of <u>Angola</u>, 1.8 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to an 18-inch steel pipe culvert under the highway in the inlet channel for Crockett Lake; set in the top of the south end of the culvert, 115 feet southeast and across the highway from power pole #469/654, 33.8 feet south from the center line of the highway, 2.8 feet below the highway; the center of two filed notches.

1031.212

DNR TBM SLK 85 1978 Crockett Lake

In Steuben County, in the <u>SW ¼ Sec. 38, T. 37 N., R. 13 E., 2nd PM</u>, about 2.1 miles west of <u>Angola</u>; 2.1 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a driveway north; set in the north side of a 54-inch triple-trunk boxelder tree in the southwest quarter of the junction, 625 feet west from the extended center line of the driveway north, 75 feet south and across the highway from power pole #496/647, 37.8 feet south from the center line of the highway, 3.0 feet below the highway; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 85 1978."

DNR TBM SLK 207 1977 Crooked Creek

In Steuben County, in the SW ¼ Sec. 23, T. 38 N., R. 13 E., 2nd PM, about 2.8 miles east of Orland; 2.9 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (675 West Road), thence 0.45 mile south to a bridge over Crooked Creek set in the top of the south end of the west concrete curb of the bridge, 15.1 feet west from the center line of the road, 0.7 foot above the roadway, 0.1 foot north from the south end of the curb; a chiseled square.

DNR BM STE 60 1977 Crooked Creek

In Steuben County, in the <u>SW ½ Sec. 23, T. 38 N., 13 E., 2nd PM</u>, about 2.8 miles east of <u>Orland</u>; 2.9 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (675 West Road), thence 0.45 mile south to a bridge over <u>Crooked Creek</u>; set in the top of the north end of the east concrete curb of the bridge, 14.4 feet east from the center line of the road, 0.7 foot above the roadway, 0.5 foot south from the north end of the curb; a Department of Natural Resources brass control station tablet, stamped "STE 60, 1977."

DNR BM STE 40 1977 Crooked Creek Recovered 1/29/87 J.C.S.

In Steuben County, in the <u>NW ¼ Sec. 24, T. 38 N., R. 13 E., 2nd PM,</u> about 3.6 miles east of <u>Orland</u>, 3.67 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (600 West Road), thence 0.2 mile south to a triple 8-foot pipe culverts in <u>Crooked Creek</u>; set in the top of a concrete post on the east side of the road, 40.5 feet north from the center line of the middle culvert, 17.6 feet east from the center line of the road, 2.4 feet south from a power pole, 0.2 foot above the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 40 1977."

DNR BM STE 62 1977 Crooked Creek Snow Lake

In Steuben County, in the SW ¼ Sec. 22, T. 38 N., R. 13 E., 2nd PM, about 4.9 miles west of Fremont; 5.2 miles west and north along State Road 120 from its intersection with State Road 827 in Fremont to an 18-foot concrete bridge over Crooked Creek; set in the top of the northeast wingwall of the bridge, 23.5 feet east from the center line of the road, 1.0 foot southeast from the northeast corner of the east concrete guardrail, 0.8 foot northwest from the southeast face of the wingwall, 0.8 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 62 1977."

Found 9-8-99 BL 971.222

DNR TBM SLK 207A 1977 Crooked Creek Snow Lake

In Steuben County, in the SW ¼ Sec. 22, T. 38 N., R. 13 E., 2nd PM, about 4.9 miles west of Fremont; 5.2 miles west and north along State Road 120 from its intersection with State Road 827 in Fremont to an 18-foot concrete bridge over Crooked Creek; set in the top of the southeast wingwall of the bridge, 24.4 feet east from the center line of the road, 1.2 feet northeast from the southeast corner of the east concrete guardrail, 0.9 foot southwest from the northeast face of the wingwall, 0.8 foot below the roadway; a chiseled-out square.

DNR BM STE 63 1977 Crooked Creek

In Steuben County, in the NW ¼ Sec. 22, T. 38 N., R. 13 E., 2nd PM, about 4.8 miles west of Fremont; 4.8 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road north (175 West Road), thence 0.55 mile north to a 15-foot concrete bridge over Crooked Creek; set in the top of the southwest bridge wingwall, 14.1 feet west from the center line of the road, 0.5 foot north from the south end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 63 1977."

DNR TBM SLK 208A 1977 Crooked Creek Mud Lake

In Steuben County, in the NW ¼ Sec. 22, T. 38 N., R. 13 E., 2nd PM, about 0.4 mile south-southwest of <u>Jamestown</u>; 0.4 mile south along 150 West Road from its junction with Lake George Road at Jamestown to an east-west crossroad (700 North Road), thence 0.15 mile west to a 10-foot steel pipe culvert in <u>Crooked Creek</u>; set in the top of the south end of the culvert, 114 feet west from the center line of a private drive south, 29.0 feet south from the center line of the road, 2.3 feet below the roadway; the center of two filled notches.

DNR BM STE 64 1977 Crooked Creek Mud Lake

In Steuben County, in the NW ¼ Sec. 22, T. 38 N., R. 13 E., 2nd PM, about 0.4 mile south-southwest of Jamestown; 0.4 mile south along 150 West Road from its junction with Lake George Road at Jamestown to an east-west crossroad (700 North Road), thence 0.1 mile west to a private drive south; set in the north end of the west headwall of a 2-foot pipe culvert under the driveway, 51 feet south from the center line of the road, 21.0 feet west from the center line of the drive south, 2.0 feet below the driveway, 1.2 feet south from the north end of the headwall; a Department of Natural Resources brass control station tablet, stamped "STE 64 1977."

DNR TBM SLK 209 1977 Crooked Creek

In Steuben County, in the <u>SE ¼ Sec. 15, T. 38 N., R. 13 E., 2nd PM</u>, about 0.27 mile south of <u>Jamestown</u>; 0.27 mile south along 150 West Road from its junction with Lake George Road at Jamestown to a 10-foot steel pipe culvert in Crooked Creek; set in the top of the east end of the culvert, 25.0 feet east from the center line of the road, 1.6 feet below the roadway; the center of two filed notches.

DNR TBM JL 4 1972 Crooked Lake

In Steuben County, in the NW ¼ Sec. 1, T. 37 N., R. 12 E., 2nd PM, about 6.5 miles northwest of Angola; 5.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road), thence 3.5 miles north to an east-west crossroad (300 North Road), thence 0.5 mile east to a T-road north (550 West Road), thence 0.75 mile north to an east-west crossroad (350 North Road); set in the west side of a 12-inch walnut tree in the northwest quarter of the intersection, 161 feet north from the center line of the east-west road, 19.5 fee west from the center line of the north-south road, 0.3 foot above the ground; a boat spike driven thru an aluminum tag, stamped "DNR TBM JL 4 1972."

DNR TBM JL 5 1972 Crooked Lake (Third Basin) 306.700 1004.336 In Steuben County, in the SE ¼ Sec. 36, T. 38 N., R. 12 E., 2nd PM, about 1.75 miles south of Nevada Mills; 0.10 mile south along a paved road from its junction with Nevada Mills Roads at Nevada Mills to an east-west crossroad (Bachelor Road), thence 0.28 mile generally east to a turn south (450 West Road), thence 0.77 mile south to a T-road west-southwest (Binkley Road), thence 0.6 mile generally west to a turn south (525 West Road), thence 0.65 mile south to an east-west crossroad (400 North Road); set in the north side of a 15-inch walnut tree in the northwest quarter of the junction, 61 feet north from the center line of the east-west road, 23 feet west from the center line of the north-south road, 0.6 foot above the ground; a boat spike driven thru an aluminum tag, stamped "DNR TBM JL 5 1972."

USGS RM No. 15 Gaging Station Crooked Lake (Third Basin) *Recovered SGM 1.17.91*

In Steuben County, in the NE ¼ Sec. 1, T. 37 N., R. 12 E., 2nd PM, about 2.1 miles west-southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 2.2 miles west and northwest to a Y-junction (Kimball Road). thence 0.12 mile west to a dam in the outlet channel for Crooked Lake (Third Basin) in a farm pasture on the south side of the road; set in the top of the north abutment of the dam, 3.0 feet northwest from the north edge of an adjustable gate; a U.S. Geological Survey gaging station tablet, not stamped.

USGS RM No. 16 Crooked Lake (Third Basin) *Recovered* But unstable SGM 1-17-91 In Steuben County, in the NE ¼ Sec. 1, T. 37 N., R. 12 E., 2nd PM, about 2.1 miles west-southwest of <u>Lake James</u>; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 2.2 miles west and northwest to a Y-junction (Kimball Road), thence 0.12 mile west to a dam in the outlet channel of Crooked Lake (Third Basin) in a farm pasture on the south side of the road; set in the top of the frame for the adjustable control gate on the north abutment; a chiseled square.

USGS BM W 45 TTT 1937 Crooked Lake (Third Basin)

In Steuben County, in the NW ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 1.4 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road); set in the top of a concrete post in the southeast quarter of the junction, 36.0 feet south from the center line of the road, 27.0 feet east from the center line of the T-road south; a U.S. Geological Survey bench mark tablet, stamped "W 45 T T T 1937."

USGS RM No. 17 Gaging Station (Third Basin) (Second Basin)
In Steuben County, in the SW ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 1.9 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road), thence 0.7 mile south to a T-road east (Sycamore Beach Road); set in the west side of a 36-inch pinoak tree in the northeast quarter of the junction, 168 feet north from the center line of the T-road east; a 3/8-inch carriage bolt.

Destroyed 8-14-90 RN* 1008.985

USGS RM No. 20 Gaging Station Crooked Lake (Third Basin) (Second Basin) In Steuben County, in the SW ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 1.93 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road), thence 0.7 mile south to a T-road east (Sycamore Beach Road); set in the top of a concrete post in the northeast quarter of the junction, 3.5 feet east from a utility pole, flush with the ground; a U.S. Geological Survey gaging station tablet, not stamped.

Recovered SCM & LDP 1-17-91 100.313**

USGS RP No. 8 Gaging Station Crooked Lake (Second Basin) (Third Basin) In Steuben County, in the SW ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 2.05 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road), thence 0.85 mile south to a metal pipe culvert under the road in the channel between Crooked Lake (Second and Third Basins); set in the top of the east end of the culvert, a filed notch.

DESTROYED 8-14090 RH 990.152**

USGS RM 18 Gaging Station Crooked Lake (Second Basin) (Third Basin) In Steuben County, in the SW 1/4 Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 2.05 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road), thence 0.85 mile south to a metal pipe culvert under the road in the channel between Crooked Lake (Second and Third Basins); set in the top of the eighth from the left large hex-nut on the east end of the culvert; a filed A. *Destroyed 8-14-90 RTJ* 991.668

USGS RM No. 19 Gaging Station Crooked Lake (Third Basin) (Second Basin) In Steuben County, in the SE ¼ Sec. 7, T. 37 N., R. 13 E., 2nd PM, about 2.05 miles southwest of Lake James; 0.95 mile south along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road), thence 0.99 mile west to a T-road south (400 West Road), thence 0.85 mile south to a metal pipe culvert under the road in the channel between Crooked Lake (Second and Third Basins); set in the top of the tenth from the right large hex-nut on the west end of the culvert; a filed triangle.

Destroyed 8-14-90 RTJ 992.474

DNR TBM JL 15 1972 Crooked Lake

In Steuben County, in the NE ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 0.95 mile south of Lake James; 0.95 mile south along 300 West Road from a bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad (Orland Road); set in the west side of a 32-inch cottonwood tree in the southwest quarter of the intersection, 103 feet south from the center line of the east-west road, 16.0 feet west from the center line of the north-south road, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "TBM JL 15 1972." 1038.648

DNR TBM JL 16 1972 Crooked Lake (First Basin)

In Steuben County, in the NE ¼ Sec. 8, T. 37 N., R. 13 E., 2nd PM, about 1.3 miles south of Lake James; 1.3 miles south along 300 West Road from a bride over the channel between Jimmerson Lake and Lake James at Lake James to a turn east; set in the south side of a 23-inch oak tree in the northwest quarter of the turn, 370 feet north from the east-west center line tangent of the turn, 24.5 feet west from the north-south center line tangent of the turn, 0.7 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "TBM JL 16 1972."

DNR TBM JL 17 1972 Crooked Lake (First Basin) Lake James (Lower Basin) In Steuben County, in the SE ¼ Sec. 9, T. 37 N., R. 13 E., 2nd PM, about 3.4 miles northnorthwest of Angola; 1.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 West Road), thence 3.0 miles north to a T-road west (275 North Road); set in the top of a headwall of a 12-inch culvert under the T-road in the southwest quarter of the junction, 42.0 feet south from the center line of the east-west road, 36.5 feet west from the center line of the south bound lane of the north-south road, 5.0 feet below the roadway; a chiseled triangle.

DNR TBM JL 18 1972 Crooked Lake (First Basin)

In Steuben County, in the NE ¼ Sec. 16, T. 37 N., R. 13 E., 2nd PM, about 2.95 miles northwest of Angola; 1.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 West Road), thence 2.5 miles north to an east-west crossroad (200 North Road); set in the top of the center of the south headwall of a 1-foot pipe culvert under the east-west road in the southwest quarter of the intersection, 60.5 feet west from the center line of the median of the north-south road, 41.5 feet south from the center line of the east-west road, 5.0 feet below the roadway; a chiseled triangle.

DNR TBM SLK 8 1976 Crooked Lake (First Basin)

In Steuben County, in the NE ¼ Sec. 15, T. 37 N., R. 13 E., 2nd PM, about 2.63 miles north-northwest of Angola; 2.6 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (200 North Road), thence 0.75 mile west to a yard entrance south; set in the top of the east end of a 12-inch steel pipe culvert under the yard entrance, 22.4 feet northeast from an end wooden fence corner post, 17.1 feet south from the center line of the road, 0.5 foot below the roadway; the center of two filed notches.

DNR TBM JL 19 1972 Crooked Lake (First Basin)

In Steuben County, in the SE ¼ Sec. 16, T. 37 N., R. 13 E., 2nd PM, about 2.3 miles northwest of Angola; 1.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 West Road), thence 1.75 miles north to a 50-inch catalpa on the west side of the road; set in the south side of the tree about 0.2 mile south of an Interstate 69 overpass, 65 feet northwest from power pole #491/089, 22.0 feet west from the center line of the road, 1.0 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 19 1972."

1017.381

DNR TBM JL 19 1972 Crooked Lake (First Basin)

In Steuben County, in the <u>SE ½ Sec. 16, T. 37 N., R. 13 E., 2nd PM</u>, about 2.3 miles northwest of <u>Angola</u>; 1.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (200 West Road), thence 1.75 miles north to a 50-inch catalpa on the west side of the road; set in the south side of the tree about 0.2 mile south of an Interstate 69 overpass, 65 feet northwest from power pole #491/089, 22.0 feet west from the center line of the road, 1.0 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 19 1972."

1017.381

ISHC BM F 24 STEU

In Steuben County, in the <u>SW ½ Sec. 35, T. 38 N., R. 13 E., 2nd PM</u>, about 4.65 miles north of <u>Angola</u>; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Interstate 69), thence 6.15 miles north to a twin bridges over State Road 127; set in the top of the southwest wingwall of the south bound bridge, 24.7 feet west from the center line of the south bound lane, 1.0 foot above the interstate, 0.6 foot north from the south end of the wingwall; an Indiana State Highway Commission bench mark tablet, stamped "F 24 STEU."

DNR BM STE 66 1977 Follette Creek Big Brother Lake

In Steuben County, in the NW ¼ Sec. 27, T. 38 N., R. 13 E., 2nd PM, about 4.7 miles west of Fremont; 4.6 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (150 West Road), thence 0.32 mile south to a 50-foot bridge over Follette Creek; set in the top of the northwest bridge wingwall, 15.0 feet northwest from the center line of the road, 8.5 feet southwest from the northeast end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 66 1977."

DNR TBM SLK 17 1976 Follette Creek Big Otter Lake

In Steuben County, in the <u>NW ¼ Sec. 27, T. 38 N., R. 13 E., 2nd PM</u>, about 4.7 miles west of <u>Fremont</u>; 4.6 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road south (150 West Road), thence 0.32 mile south to a 50-foot bridge over <u>Follette Creek</u>; set in the top of the southwest end of the northeast bridge wingwall, 15.2 feet southeast from the center line of the road, 0.3 foot northeast from the southwest face of the wingwall, level with the roadway; a chiseled triangle.

972.514

DNR TBM SLK 114 1978 Grass Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 13, T. 37 N., R. 12 E., 2nd PM</u>, about 4.95 miles west-northwest of <u>Angola</u>; 1.6 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (100 North Road), thence 4.65 miles west to a private entrance road north leading to a gravel pit; set in the south side of an 18-inch cottonwood tree in the northeast quarter of the junction, 564 feet east from the center line of the road, 17.5 feet north from the center line of the road, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 114 1978."

DNR BM STE 78 1977 Grass Lake

In Steuben County, in the NE ¼ Sec. 24, T. 37 N., R. 12 E., 2nd PM, about 4.9 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 4.7 miles west to a private drive north leading to a gravel pit; set in the top of a concrete post in the southwest quarter of the junction, 66 feet west from the extended center line of the drive north, 16.2 feet northeast from a 28-inch oak tree, 15.1 feet south from the center line of the roads, 0.1 foot above the ground, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 78 1978."

DNR TBM OL 6 Grass Lake Cheeseboro Lake

In Steuben County, in the NE ¼ Sec. 23, T. 37 N., R. 12 E., 2nd PM, about 5.5 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.3 miles west to a north-south crossroad (600 West Road); set in the east side of a power pole in the southwest quarter of the intersection, 75 feet south from the center line of the eastwest road, 20 feet west from the center line of the north-south road, 0.5 foot above the ground; a 60 d nail.

DNR TBM SLK 14 1976 Green Lake

In Steuben County, in the NW ¼ Sec. 26, T. 38 N., R. 13 E., 2nd PM, about 1.85 miles southeast of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 1.5 miles south to an 18-inch steel pipe culvert under the highway; set in the top of the east end of the culvert, 200 feet west from the center of the median of Interstate 69, 41.1 feet east from the center line of the highway, 2.5 feet below the highway; the center of two filed notches.

DNR TBM SLK 20 1977 Hogback Lake

In Steuben County, in the E½ Sec. 25, T. 37 N., R. 12 E., 2^{nd} PM, about 4.4 miles west of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road); set in the north side of power pole #468/099 in the southwest quarter of the junction, 78 feet south from the center line of the highway, 27.3 feet west from the center line of the T-road south, 0.4 foot above the ground; a boat spike.

DNR TBM SLK 21 1977 Hogback Lake

In Steuben County, in the NE ¼ Sec. 36, T. 36 N., R. 12 E., 2nd PM, about 4.6 miles west of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.4 mile south to a T-road east; set in the top of the west end of a 1-foot steel pipe culvert under the road in the southwest quarter of the junction, 118 feet south from the extended center line of the T-road east, 15.8 feet west from the center line of the north-south road, 2.5 feet below the roadway; the center of two filed notches.

USGS RM No. 2 Gaging Station Howard Lake

In Steuben County, in the NE ¼ Sec. 25, T. 37 N., R. 12 E., 2nd PM, about 4.65 miles west of Angola; 4.85 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road north (550 West Road), thence 0.1 mile north to a dirt T-road east, thence 0.1 mile east to a turn north, thence 0.3 mile generally north to the south end of Howard Lake; set in the top of the west bolt of a trash gate for an 18-inch steel outlet pipe, 45.0 feet north from the center line of the dirt road, 18.0 feet west from a 4-foot vertical steel post, 1.5 feet below the roadway; a chiseled cross.

USGS RM No. 5 Gaging Station Howard Lake

In Steuben County, in the NE ¼ Sec. 25, T. 37 N., R. 12 E., 2nd PM, about 4.65 miles west of Angola; 4.85 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road north (550 West Road), thence 0.1 mile north to a dirt T-road east, thence 0.1 mile east to a turn north, thence 0.3 mile generally north to the south end of Howard Lake; set in the top of a concrete lake level monument, 150 feet northwest from the east steel airport aerial tower, 42.0 feet north from the center line of the dirt road, 8.0 feet south from a 4-foot vertical steel pipe, 2.0 feet above the ground, 0.5 foot south from the south edge of the lake; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 112 1978 Howard Lake

In Steuben County, in the SE ¼ Sec. 24, T. 37 N., R. 12 E., 2nd PM, about 4.65 miles west of Angola; 3.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road north, thence 1.0 mile north to an east-west crossroad (50 North Road), thence 0.25 mile west to a north-south crossroad (450 West Road), thence 0.7 mile south and west to a driveway south; set in the north side of a 26-inch cottonwood tree in the southeast quarter of the junction, 100 feet southeast from the center line of the driveway, 14.5 feet southwest from the center line of the road, 1.0 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 112 1978."

USGS RM No. 4 Gaging Station Jimmerson Lake Crooked Creek In Steuben County, in the NW ½ Sec. 30, T. 38 N., R. 13 E., 2nd PM, at Nevada Mills; at the bridge over the outlet structure for Jimmerson Lake at Nevada Mills; set in the top of the south foundation wall of an old mill and power plant on the north bank of Crooked Creek west of the bridge, 20.0 feet west from the center line of the road, 5.0 feet below the roadway; a U.S. Geological Survey gaging station tablet, not stamped.

964.929

USGS RM No. 7 Gaging Station Jimmerson Lake Crooked Creek In Steuben County, in the NW ¼ Sec. 30 T. 38 N., R. 13 E., 2nd PM, at Nevada Mills; at the bridge over the outlet structure for Jimmerson Lake at Nevada Mills; set in the top of a lake level monument on the top of the east foundation wall of an old mill and power plant on the north bank of Crooked Creek west of the bridge, 20.0 feet south from the north end of the bridge, 15.0 feet west from the center line of the road, 3.0 feet above the roadway; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM JL 8 1972 Jimmerson Lake

In Steuben County, in the NE ¼ Sec. 30, T. 38 N., R. 13 E., 2nd PM, about 0.5 mile east of Nevada Mills; 0.5 mile east along Nevada Mills road from its junction with a north-south paved road at Nevada Mills to a T-road north (425 West Road); set in the north side of a 24-inch catalpa tree in the southwest quarter of the junction, 122 feet west from the center line of the T-road, 16.0 feet south from the center line of the road, 1.0 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 8 1972."

DNR TBM JL 9 1972 Jimmerson Lake

In Steuben County, in the SW ¼ Sec. 29, T. 38 N., R. 13 E., 2nd PM, about 1.0 mile east-southeast of Nevada Mills; 1.15 miles east of and south along Nevada Mills Road from its junction with a north-south paved road at Nevada Mills to a T-road west leading to Collinswood Trailer Court; set in the north side of a 6-inch ash tree in the northwest quarter of the junction, 60 feet west from the center line of the road, 20.5 feet north from the center line of the T-road, 1.1 feet above the ground, a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 9 1972."

DNR TBM JL 10 1972 Jimmerson Lake

In Steuben County, in the N½ Sec. 32, T. 38 N., R. 13 E., 2nd PM about 1.45 miles southeast of Nevada Mills; 1.85 miles east and south along Nevada Mills Road from its junction with a north-south paved road at Nevada Mills to a turn east and a field entrance road west; set in the west side of a 24-inch oak tree, 62 feet south from the center line of the field road, 2.5 feet above the ground, on the extended center line of the field road, 2.5 feet above the ground, 0n the extended north-south center line tangent of the turn; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 10 1972."

DESTOYED 1009.948

DNR TBM JL 11 1972 Jimmerson Lake

In Steuben County, in the NW ¼ Sec. 32, T. 38 N., R. 13 E., 2nd PM, about 1.7 miles southeast of Nevada Mills; 1.85 miles east and south along Nevada Mills Road from its junction with a north-south paved road at Nevada Mills to a turn east and a field entrance road west, thence 0.55 mile west and south along the dirt field road to a corrugated tin barn; set in the north side of a 20-inch oak tree, 250 feet northwest from the tin barn, 200 feet north from the left edge of the lake, 0.9 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 11 1972."

DNR TBM JL 12 1972 Jimmerson Lake

In Steuben County, in the NW ¼ Sec. 32, T. 38 N., R. 13 E., 2nd PM, about 1.7 miles southeast of Nevada Mills; 1.85 miles east and south along Nevada Mills Road from its junction with a north-south paved road at Nevada Mills to a turn east and a field entrance road west, thence 0.55 mile west and south along the dirt field road to a corrugated tin barn; set in the east side of a 39-inch twin-trunk oak tree, 225 feet northwest from the tin building, 180 feet north from the left edge of the lake, 1.2 feet above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM JL 12 1972."

968.699

DNR TBM SLK 10A 1976 Jimmerson Lake Lake James (Middle Basin) In Steuben County, in the SW ¼ Sec. 33, T. 38 N., R. 13 E., 2nd PM, at Lake James; 0.38 mile north along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to a T-road east; set in the north side of an 18-inch willow tree, 81 feet south from the center line of the T-road east, 46.2 feet east from the center line of the road, 0.6 foot above the ground; a boat spike.

Grown Over Destroyed 9-8-99 BC 968.645

DNR TBM SLK 10 1976 Jimmerson Lake Lake James

In Steuben County, in the <u>SW ½ Sec. 33, T. 38 N., R. 13 E., 2nd PM,</u> at <u>Lake James</u>; 0.55 mile north along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad; set in the west side of a 24-inch walnut tree, 23.3 feet south from the center line of the east-west road, 17.3 feet east from the center line of the north-south road, 1.0 foot above the ground; a boat spike.

Destroyed 9-8-99 BC 996.793

DNR TBM JL 14 1972 Jimmerson Lake Lake James (Middle Basin)
In Steuben County, in the SW ¼ Sec. 33, T. 38 N., R. 13 E., 2nd PM, at Lake James; 0.38 mile north along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at James Lake to a T-road east; set in the north side of a 15-inch cottonwood tree in the northeast quarter of the junction, 68 feet east from the center line of the road, 17.0 feet north from the center line of the T-road east, 2.0 feet above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM JL 14 1972."

Grown Over Destroyed 9-8-99 BC 968.422

DNR TBM SLK 11A 1976 Lake Charles

In Steuben County, in the NW ¼ Sec. 2, T. 37 N., R. 13 E., 2nd PM, about 4.45 miles north of Angola; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Interstate 69), thence 5.6 miles north to twin bridges over Lake Charles; set in the top of the south end of the east concrete guardrail of the south-bound bridge, 21.8 feet east from the center line of the south bound highway, 0.8 foot above the highway, 0.2 foot north from the south end of the guardrail; a chiseled triangle.

DNR TBM SLK 12A 1976 Lake Charles

In Steuben County, in the NE ¼ Sec. 2, T. 37 N., R. 13 E., 2nd PM, about 4.55 miles north of Angola; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Interstate 69), thence 5.6 miles north to a twin bridge over Lake Charles; set in the top of the north end of the west concrete guardrail of the north-bound bridge, 21.1 feet west from the center line of the north-bound lane, 0.7 foot above the interstate, 0.2 foot south from the north end of the guardrail; a chiseled triangle.

DNR BM STE 61 1977 Lake Gage Lime Lake

In Steuben County, in the NW ¼ Sec. 35, T. 38 N., R. 12 E., 2nd PM, about 2.0 miles southwest of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles generally west to a north-south crossroad (675 West Road), thence 0.7 mile south to a northwest-southeast crossroad (Orland Road), thence 0.3 mile southeast to a Troad south-southwest, thence 0.1 mile south-southwest to a bridge over the outlet channel for Lake Gage; set in the top of the northeast corner of the bridge floor, 11.8 feet east from the center line of the road, 1.2 feet southwest from the northwest corner of the east stone guardrail, 0.8 foot south from the north end of the bridge, a Department of Natural Resources brass control station tablet, stamped "STE 61 1977."

USGS RM No. Gaging StationLake Gage Lime Lake In Steuben County, in the NW 1/4 Sec. 25, T. 38 N., R. 12 E., 2nd PM, about 2.0 miles southwest of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles generally west to a north-south crossroad (675 West Road), thence 0.7 mile south to a northwest-southeast crossroad (Orland Road), thence 0.3 mile southeast to a Troad south-southwest, thence 0.1 mile south-southwest to a bridge over the outlet channel for Lake Gage; set in the top of the south end of the east stone guardrail, 11.7 feet west from the center line of the road, 3.2 feet above the roadway, 0.7 foot south from the north end of the guardrail; a chiseled cross.

USGS RM No. 2 Gaging Station Lake Gage Lime Lake
In Steuben County, in the NW ¼ Sec. 25, T. 38 N., R. 12 E., 2nd PM, about 2.0 miles southwest of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles generally west to a north-south crossroad (675 West Road), thence 0.7 mile south to a northwest-southeast crossroad (Orland Road), thence 0.3 mile southeast to a Troad south-southwest, thence 0.1 mile south-southwest to a bridge over the outlet channel for Lake Gage; set in the top of the south end of the east stone guardrail, 13.0 feet east from the center line of the road, 3.3 feet above the roadway, 0.8 foot north from the south end of the guardrail; a chiseled cross.

USGS RM No. 4 Gaging Station Lake Gage Lime Lake In Steuben County, in the NW ¼ Sec. 35, T. 38 N., R. 12 E., 2nd PM, about 2.0 miles southwest of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles generally west to a north-south crossroad (675 West Road), thence 0.7 mile south to a northwest-southeast crossroad (Orland Road), thence 0.3 mile southeast to a Troad south-southwest, thence 0.1 mile south-southwest to a bridge over the outlet channel for Lake Gage; set in the top of a concrete lake level monument on the west side of the road, 13.7 feet north from the north end of the bridge, 13.0 feet west from the center line of the road, 1.7 feet above the ground; a U.S. Geological Survey gaging station tablet, stamped.

988.249

987.055

USGS RM No. 3 Gaging Station Lake George Crooked Creek
In Steuben County, in the SE ¼ Sec. 15, T. 38 N., R. 13 E., 2nd PM, at Jamestown; at the Lake George Road bridge over Crooked Creek at Jamestown; set in the top of a concrete lake level monument, 11.7 feet east from the northeast corner of the bridge, 7.8 feet northeast from the center line of the road, 1.2 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

988.969

USGS TM No. 4 Gaging Station Lake George Crooked Creek
In Steuben County, in the SE ¼ Sec. 15, T. 38 N., R. 13 E., 2nd PM, at Jamestown at Lake
George Road bridge over Crooked Creek at Jamestown; set in the top of the southeast
end of the northeast concrete guardrail base of the bridge, 7.6 feet northeast from the
center line of the road, 0.1 foot northwest from the southeast end of the guardrail base,
0.1 foot southwest from the northeast face of the guardrail base; a chiseled square.

USGS RM No. 7 Gaging Station Lake George Crooked Creek
In Steuben County, in the SE ½ Sec. 15, T. 38 N., R. 13 E., 2nd PM, at Jamestown; at the
Lake George Road bridge over Crooked Creek at Jamestown; set in the top of the
northeast concrete retaining wall of a dam northeast of the bridge, 19.3 feet northeast
from the center line of the road, 6.5 feet northwest from the southeast end of the retaining

DNR BM STE 65 1977 Lake George Crooked Creek

wall, 0.5 foot below the roadway; a chiseled cross.

In Steuben County, in the SE ¼ Sec. 15, T. 38 N., R. 13 E., 2nd PM, at Jamestown; at the Lake George Road bridge over Crooked Creek at Jamestown; set in the top of the northeast concrete wingwall of the bridge, 17.7 feet northeast from the center line of the road, 10.5 feet northwest from the southeast end of the wingwall, 0.5 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 65 1977"

DNR TBM SLK 210 1977 Lake George

In Steuben County, in the <u>SW ¼ Sec. 14, T. 38 N., R. 13 E., 2nd PM</u>, about 0.55 mile east of <u>Jamestown</u>; 0.55 mile east along Lake George Road from its junction with 150 West Road at Jamestown to an abandoned drive south; set in the top of a rivet head in the east end of a 1-foot steel pipe culvert under the driveway, 150 feet west from the center line of a T-road north (South Shore Road), 15.0 feet south from the center line of the road, 10.7 feet east from the center line of the drive, 0.05 foot west from the east end of the culvert; a filed cross.

USC&GS Triangulation Station GEORGE 1946 Lake George In Steuben County, in the S½ Sec. 14, T. 38 N., R. 13 E., 2nd PM, about 1.05 miles east of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27) thence 0.18 mile south to an abandoned T-road east; set in the top of a concrete post in the northeast quarter of the junction, 72 feet east from the center line of the north-south road, 48.0 feet north from the center line of the T-road east, 21.6 feet northeast from a power pole, 8.0 feet above the roadway, 2.8 feet southeast from a steel reference mark sign, flush with the ground; a U.S. Coast and Geodetic Survey triangulation tablet, stamped "GEORGE 1946."

USC&GS Azimuth Station George 1946 Lake George
In Steuben County, in the N½ Sec. 23, T. 38 N., R. 13 E., 2nd PM, about 1.15 miles southeast of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 0.98 mile south to a T-fence line west; set in the top of a concrete post in the southwest quarter of the junction, 400 feet northeast from the northeast corner of the Redwood Motel building, 40.8 feet south from the T-fence corner, 38.0 feet west from the center line of the road, 7.0 feet above the roadway, 2.1 feet south from a metal witness post sign, 1.7 feet east from a fence line, 0.2 foot above the ground; a U.S. Coast and Geodetic Survey azimuth mark tablet, stamped "GEORGE 1946".

USGS RM. No. 4 Gaging Station Lake James (Middle Basin) Jimmerson Lake In Steuben County, in the NW ¼ Sec. 4, T. 37 N., R. 13 E., 2nd PM, at Lake James; at the 300 West Road bridge over the channel between James Lake and Jimmerson Lake at Lake James; set in the top of the west end of the south bridge abutment, 14.6 feet west from the center line of the road, 0.1 foot south from the north face of the abutment, level with the roadway; a chiseled square.

USGS RM No. 5 Gaging Station Lake James (Middle Basin) Jimmerson Lake In Steuben County, in the NW ¼ Sec. 4, T. 37 N., R. 13 E., 2nd PM, at Lake James; at the 300 West Road bridge over the channel between James Lake and Jimmerson Lake at Lake James; set in the top of the east end of the north bridge abutment, 14.4 feet east from the center line of the road, 0.5 foot north from the south face of the abutment, level with the roadway; a U.S. Geological Survey gaging station tablet, not stamped.

970.620

USGS RM No. 7 Gaging Station Lake James (Middle Basin) Jimmerson Lake In Steuben County, in the NW ¼ Sec. 4, T. 37 N., R. 13 E., 2nd PM, at Lake James; at the 300 West Road bridge over the channel between James Lake and Jimmerson Lake at James Lake; set in the wingwall, 14.5 feet east from the center line of the road, 5.4 feet northwest from the southeast end of the wingwall, 1.2 feet above the wingwall; a U.S. Geological gaging station tablet, not stamped.

Reported DEST. by Local Surveyor 2-24-98 RWW 971.792

DNR TBM SLK 11 1976 Lake James (Upper Basin) (Middle Basin)
In Steuben County, in the SW ¼ Sec. 33, T. 38 N., R. 13 E., 2nd PM, at Lake James; 0.55 mile north along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at a five-way junction; set in the south side of a 20-inch oak tree, 110 feet east from the intersection center lines of the junction, 66 feet southwest from power pole #475/785, 11.0 feet north from the intersecting center lines of the junction, 0.6 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 11 1976."

DNR TBM SLK 12 1976 Lake James (Upper Basin)

In Steuben County, in the N $\frac{1}{2}$ Sec. 33, T. 38 N., R. 13 E., 2^{nd} PM, at Lake James; 0.55 mile north along 300 West Road from the bridge over the channel between Lake James and Jimmerson Lake at Lake James to an east-west crossroad, thence 0.35 mile east to a five-way junction, thence 0.12 mile northeast to a large house; set in the north side of a 24-inch oak tree, 102 feet west from the edge of Lake James, 28.5 feet east from the east corner of the house, 8.8 feet south from the center line of a small channel, 1.4 feet above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 12 1976."

DNR TBM JL 13 1972 Lake James (Upper Basin)

In Steuben County, in the NE ¼ Sec. 32, T. 38 N., R. 13 E., 2nd PM, about 0.96 mile north of Lake James; 0.96 mile north along 300 West Road from the bridge over the channel between Jimmerson Lake and Lake James at Lake James to a gravel T-road west; set in the top of a 2.25-inch pipe in the northwest quarter of the junction, 29.5 feet west from the center line of the road, 20.0 feet north from the center line of the T-road west, 1.3 feet above the ground; the center of two filed notches.

Destroyed 1012.607

DNR TBM SLK 9 1976 Lake James (Lower Basin)

In Steuben County, in the NW ¼ Sec. 11, T. 37 N., R. 13 E., 2nd PM, about 3.3 miles north of Angola; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Intersection 69), thence 4.45 miles north to an east-west crossroad bridge over the intersection (275 North Road); set in the top of the south headwall of an 18-inch pipe culvert, 65 feet south from the center line of east-west road, 30.5 feet east from the center line of the north-bound lane of the interstate, 1.3 feet east from the west face of the headwall, 1.0 foot below the interstate; a chiseled triangle.

DNR TBM SLK 10B 1976 Lake James (Lower Basin)

In Steuben County, in the <u>SW ¼ Sec. 2, T. 37 N., R. 13 E., 2nd PM</u>, about 3.85 miles north of <u>Angola</u>; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (Interstate 69), thence 5.05 miles north to a Pokagon State Park Next Right sign on the east side of the road; set in the top of the east concrete foundation post for the sign, 34.0 feet east from the center line of the north-bound lane of the interstate, 3.0 feet below the interstate, 0.6 foot west from the east foundation post; a chiseled triangle.

DNR TBM SLK 206 1977 Lake Pleasant

In Steuben County, in the NE ¼ Sec. 23, T. 38 N., R. 12 E., 2nd PM, about 3.1 miles east-northeast of Orland; 3.15 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road north (650 West Road); set in the top at the center of the north headwall of a 1.5 foot culvert under the highway, 58 feet east from the center line of the T-road, 24.0 feet north of from the center line of the highway; 1.9 feet below the highway; a chiseled triangle.

USGS RM Gaging Station Lime Lake

In Steuben County, in the NW ¼ Sec. 35, T. 38 N., R. 12 E., 2nd PM, about 2.1 miles southwest of Nevada Mills; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles west to a north-south crossroad (675 West Road), thence 0.7 mile west to a northwest-southwest crossroad (Orland Road), thence 0.1 mile northwest to an outlet channel for Lime Lake; set in the top of the northeast wingwall of a dam on the south side of the road in the outlet channel, 48.5 feet southwest from the center line of the roads, 17.0 feet east from the center line of a 6-foot metal pipe culvert, 0.7 foot above the ground, 0.4 foot south from the northeast face of the wingwall; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 208 1977 Lime Lake Chair Factory Lake

In Steuben County, in the <u>NW ¼ Sec. 35, T. 38 N., R. 12 E., 2nd PM</u>, about 2.1 miles southwest of <u>Nevada Mills</u>; 0.1 mile south along a paved road from its junction with Nevada Mills Road at Nevada Mills to an east-west crossroad (Bachelor Road), thence 1.85 miles west to a north-south crossroad (675 West Road), thence 0.7 mile south to a northwest-southeast crossroad (Orland Road), thence 0.1 mile northwest to a 6-foot steel pipe culvert under the road in the outlet channel for Lime Lake; set in the top of the south end of the culvert, 25.8 feet south from the center line of the road, 0.6 foot below the roadway; the center of two filed notches.

DNR TBM SLK 103 1978 Little Center Lake

In Steuben County, in the NW ¼ Sec. 26, T. 37 N., R. 13 E., 2nd PM, in Angola; 0.25 mile north along State Road 127 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (Mill Street), thence 0.35 mile west to a T-road north (Wohlert Street), thence 0.15 mile north to an entrance T-road east leading to a City Park landfill; set in the top of the north end of a 3.5-foot steel pipe culvert under the entrance road, 41.3 feet east from the center line of the street, 9.8 feet north from the center line of the entrance road, 2.0 feet below the road; the center of two filed notches.

1027.839

DNR BM STE 76 1978 Little Center Lake

In Steuben County, in the NW ¼ Sec. 26, T. 37 N., R. 13 E., 2nd PM, in Angola; 0.25 mile north along State Road 127 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (Mill Street), thence 0.35 mile west to a T-road north (Wohlert Street), thence 0.15 mile north to a entrance T-road leading to a City Park landfill; set in the top of a concrete post in the southeast quarter of the junction, 30.0 feet east from the center line of the road, 17.0 feet south from the center line of the T-road east, 2.2 fee west from a fence line, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 76 1978".

USGS BM TT27T 1937 Little Center Lake Middle Center Lake

In Steuben County, in the <u>SW ½ Sec. 26, T. 37 N., R. 13 E., 2nd PM</u>, in <u>Angola</u>; at the intersection of main line track of the New York Central Railroad and West Maumee Street in Angola; set in the top of a concrete post on railroad property in the southwest quarter of the intersection, 300 feet north from the north end of a freight depot, 43 feet south from the center line of the road, 31.0 feet west from the center line of the main line tracks, 15.0 feet west from a west rail; a U.S. Geological Survey bench mark tablet, stamped "TT 27 T 1937 105."

DNR TBM SLK 13 1979 Little Otter Lake Follette Creek

In Steuben County, in the SW ¼ Sec. 26, T. 38 N., R. 13 2nd PM, about 2.3 miles south-southeast of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 2.0 miles south to a 15-foot concrete box culvert in Follette Creek; set in the top of the south end of the west headwall, 26.0 feet west from the center line of the highway, 0.5 foot north from the south end of the headwall, 0.3 foot below the highway; a chiseled triangle.

USGS RM Gaging Station Little Otter Lake Follette Creek

In Steuben County, in the <u>SW ½ Sec. 26, T. 38 N., R. 13 E., 2nd PM</u>, about 2.1 miles south-southeast of <u>Jamestown</u>; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 2.0 miles south to a T-road west leading to Little Otter Lake, thence 0.3 mile west to a Boat Rental Shed; set in the top of a concrete lake level monument, 80.5 feet southeast corner of the shed, 71.2 feet southwest from power pole #489/199 with transformer, 59 feet northeast from the southwest edge of the lake, 2.4 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

USGS RM No. 1 Gaging Station Little Otter Lake Follette Creek
In Steuben County, in the SW ¼ Sec. 26, T. 38 N., R. 13 E., 2nd PM, about 2.1 miles south-southeast of Jamestown; 1.0 mile east along Lake George Road from its junction with 150 West Road at Jamestown to a north-south crossroad (Old U.S. Highway 27), thence 2.0 miles south to a T-road west leading to Little Otter Lake, thence 0.3 mile west to a Boat Rental Shed; set in the top of a concrete lake level monument, 80.5 feet south from the southeast corner of the shed, 71.2 feet southwest from power pole #489/199 with transformer, 108 feet southwest from the southeast corner of the shed, 20.0 feet northeast from the southwest edge of the lake; a chiseled square.

ISHC BM F 22 STEU Loon Lake

In Steuben County, in the SW ¼ Sec. 16, T. 37 N., R. 13 E., 2nd PM, about 2.6 miles northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.1 miles west to an Intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.1 miles west to an Interstate 69 overpass bridge; set in the top of the west end of the north concrete bridge sidewalk; an Indiana State Highway Commission bench mark tablet, stamped "F 22 STEU."

DNR TBM LL 4 1969 Loon Lake

In Steuben County, in the NE ¼ Sec. 20, T. 37 N., R. 13 E., 2nd PM, about 2.95 miles northwest of Angola; 1.15 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.5 miles west to a T-road south leading to Loon Lake Public Fishing Site; set in the top of a right-of-way marker in the southeast quarter of the junction, 21.0 feet south from the center line of the road, 18.0 feet east from the center line of the T-road south, 1.5 feet above the ground; a chiseled triangle.

USGS RM No. 3 Gaging Station Loon Lake

In Steuben County, in the NE ¼ Sec. 20, T. 37 N., R. 13 E., 2nd PM, about 2.9 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.5 miles west to a T-road south leading to Loon Lake Public Fishing Site, thence 0.05 mile south to Loon Lake; set in the top of a concrete post, 143 feet north from the north edge of the lake, 50.2 feet west from the center line of the road, 18.6 feet southwest from a fence corner post, 1.8 feet south from a fence line, flush with the ground; a U.S. Geological Survey gaging station tablet, not stamped.

USGS RM NO. 4 Gaging Station Loon Lake

In Steuben County, in the NE ¼ Sec. 20, T. 37 N., R. 13 E., 2nd PM, about 2.9 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.5 miles west to a T-road south leading to Loon Lake Public Fishing Site, thence 0.05 mile south to Loon Lake; set in the top of a concrete post, 143 feet north from the north edge of the lake, 30.5 feet west from the center line of the road, 2.0 feet southwest from a fence post, flush with the ground; a U.S. Geological Survey gaging station tablet, not stamped.

1019.089

USGS RM No. 6 Gaging Station Loon Lake

In Steuben County, in the NE ¼ Sec. 20, T. 37 N., R. 13 E., 2nd PM, about 2.9 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 2.5 miles west to a T-road south leading to Loon Lake Public Fishing Site, thence 0.05 mile south to Loon Lake; set in the top of a concrete lake level monument, 82 feet southwest from a fence corner post, 75 feet west from the center line of the road, 46.0 feet north from the north edge of the lake, 1.2 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

DNR BM STE 83 1978 Loon Lake

In Steuben County, in the <u>SE ½ Sec. 21, T. 37 N., R. 13 E., 2nd PM</u>, about 2.5 miles west-northwest of <u>Angola</u>; 2.5 miles west along U.S. Highway 20 from its intersection with State Road 127 in Angola to a north-south crossroad (Interstate 69), thence 0.95 mile generally north to a 3-foot pipe culvert under the interstate; set in the top of the south end of the west headwall of the culvert, 275 feet south from mile marker #149, 58 feet west from the center line of the south-bound lane, 14.0 feet east from a fence line, 10 feet below the roadway, 0.6 foot north from the south end of the headwall; a Department of Natural Resources brass control station tablet, stamped "STE 83 1978."

1020.659

ISHC BM STEU F 14 Mud Lake

In Steuben County, in the W½ Sec. 28, T. 37 N., R. 13 E., 2nd PM, about 2.5 miles west of Angola; 2.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to the U.S. Highway 20 bridge over Interstate 69; set in the top of the west end of the north concrete sidewalk of the bridge, 40.6 feet north from the center line of the highway, 0.8 foot above the highway, 0.7 foot east from the west end of the sidewalk; an Indiana State Highway Commission bench mark tablet, stamped "STEU F 14."

DNR TBM SLK 86 1978 Mud Lake Silver Lake

In Steuben County, in the NW ¼ Sec. 29, T. 37 N., R. 13 E., 2nd PM, about 3.2 miles west of Angola; 3.2 miles west of Angola; 3.2 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (375 West Road); set in the north side of a 20-inch elm tree in the northwest quarter of the junction, 118 feet west from the center line of the T-road south, 23.6 feet north from the center line of the highway, 4.0 feet below the highway, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 86 1978."

USGS UE Pigeon Creek

In Steuben County in the <u>SE ½ Sec. 15, T. 37 N., R. 12 E., 2nd PM,</u> about 0.6 mile northnortheast of <u>Flint;</u> 0.55 mile generally north along Flint Road from its intersection with 50 North Road at Flint to a T-road east (100 North Road), thence 0.25 mile east to T-road north (700 West Road); set in the top of a concrete headwall of a culvert in the northwest quarter of the junction, 260 feet west from the center line of the T-road north; a chiseled square.

DNR TBM SLK 28 1977 Pigeon Creek

In Steuben County, in the W½ Sec. 23, T. 37 N., R. 12 E., 2nd PM, about 0.3 mile east of Flint; 0.5 mile generally east along Creek Bank Road from its junction with Flint Road at Flint to a turn south; set in the east side of a 50-inch cottonwood tree, 144 feet south from the bend in the road, 13.5 feet east from the center line of the road, 1.1 feet above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 28 1977."

DNR BM STE 25 1977 Pigeon Creek

In Steuben County, in the NE ¼ Sec. 26, T. 37 N., R. 12 E., 2nd PM, about 1.1 miles southeast of Flint; 1.25 miles east and southeast along Creek Bank Road from its junction with Flint Road at Flint to an east-west crossroad on a 65-foot concrete bridge over Pigeon Creek; set in the top of the northeast wingwall of the bridge, 106 feet east from the center line of the north-south road, 14.0 feet north from the center line of the east-west road, 3.3 feet west from the east end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 25 1977."

958.148

USGS RM No. 1 Gaging Station Pigeon River Bass Lake

In Steuben County, in the NE ¼ Sec. 26, T. 37 N., R. 12 E., 2nd PM, about 5.9 miles west of Angola; 5.9 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a single span concrete bridge over Pigeon Creek; set in the top of the south end of the west bridge abutment, 23.0 feet south from the center line of the highway, 0.7 foot above the highway, 0.6 foot west from the east face of the abutment; a U.S. Geological Survey gaging station tablet, not stamped.

USGS RM No. 2 Pigeon Creek Bass Lake

In Steuben County, in the <u>SE ¼ Sec. 26, T. 37 N., R. 12 E., 2nd PM,</u> about 5.9 miles west of <u>Angola</u>; 5.9 miles west along U.S. Highway 20 from its intersection with U.S. 27 in Angola to a single span concrete bridge over <u>Pigeon Creek</u>; set in the top of the south end of the east bridge abutment, 23.0 feet south from the center line of the highway, 0.7 foot above the highway, 0.6 foot east from the west face of the abutment; a U.S. Geological Survey gaging station tablet, not stamped.

ISHC BM F 6 STB Pigeon Creek Bass Lake

In Steuben County, in the NE ¼ Sec. 26, T. 37 N., R. 12 E., 2nd PM, about 5.9 miles west of Angola; 5.9 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a single span concrete bridge over Pigeon Creek; set in the top of the north end of the west bridge abutment, 23.0 feet north from the center line of the highway, 0.7 foot above the highway, 0.6 foot west from the east face of the abutment; an Indiana State Highway Commission bench mark tablet, stamped "F 6 STB."

961.060

DNR BM STE 8 1975 Pigeon Creek Hogback Lake *May be unstable 5-82 R.W.W.* In Steuben County, in the <u>SW ¹/₄ Sec. 25, T. 37 N., R. 12 E., 2nd PM,</u> about 5.6 miles west of <u>Angola</u>; 5.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road), thence 0.5 mile south to triple 10-foot corrugated metal pipe culverts under the road in <u>Pigeon Creek</u>; set in the top of a concrete post, 52 feet north from the center line of the culverts, 17.2 feet east from the center line of the road, 10.1 feet south from the center line of a private drive east, 2.0 feet south from a telephone pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 8 1975."

961.237

DNR BM STE 84 1978 Round Lake

In Steuben County, in the N½ Sec. 12, T. 37 N., R. 12 E., 2nd PM, about 6.0 miles northwest of Angola; 5.35 miles west along U.S. Highway 20 from its intersection with State Road 127 in Angola to a north-south crossroad (600 West Road), thence 3.55 miles north to an east-west crossroad (300 North Road), thence 0.5 mile east to a T-road north (550 West Road); set in the top of a concrete post in the southwest quarter of the junction, 16.5 feet west from the extended center line of the T-road, 14.8 feet south from the center line of the east-west road, 1.6 feet east from a guy-wired power pole, 1.3 feet north from a fence line, 0.1 foot above the ground; a Department of Natural Resources bench mark tablet, stamped "STE 84 1978."

DNR TBM JL 3 1972 Round Lake

In Steuben County, in the S ½ Sec. 1, T. 37 N., R. 12 E., 2nd PM, about 6.0 miles northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.35 miles west to a north-south crossroad (600 West Road), thence 2.0 miles north to an east-west crossroad (300 North Road), thence 0.5 mile east to a T-road north (550 West Road); set in the northwest side of a 30-inch maple tree in the northwest quarter of the junction, 27 feet north from the center line of the east-west road, 22.5 feet west from the center line of the north-south road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 3 1972."

USGS RM No. 6 Gaging Station Silver Lake

In Steuben County, in the E½ Sec. 30, T. 37 N., R. 13 E., 2nd PM, about 3.58 miles west of Angola; 3.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a private road south leading to Silver Lake Court, thence 0.05 mile south to an east-west crossroad; set in the top of a concrete lake level monument in the southeast quarter of the junction, 175 feet south from the center line of the east-west road, 94 feet north from the north edge of Silver Lake, 54 feet east from the extended center line of the north-south road, 22.0 feet below the roadway, 1.5 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

963.695

DNR BM STE 54 1977 Silver Lake

In Steuben County, in the <u>NW ¼ Sec. 31, T. 37 N., R. 13 E., 2nd PM,</u> about 4.3 miles west-southwest of <u>Angola</u>; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.5 mile south to a turn east, thence 0.3 mile east to a turn south and a private drive east; set in the top of a concrete post in the northeast quarter of the junction, 9.4 feet north from the center line of the private drive, 3.4 feet west from a telephone pole gate post, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 54 1977."

DNR TBM SLK 22 1977 Silver Lake

In Steuben County, in the NW ¼ Sec. 31, T. 37 N., R. 13 E., 2nd PM, about 4.3 miles west-southwest of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.5 mile south to a turn east, thence 0.3 mile east to a turn south and a private drive east; set in the op of the south end of a 4-foot steel pipe culvert under the drive in the southeast quarter of the junction, 136 feet east from the extended center line of the north-south tangent of ht road, 14.5 feet south from the center line of the private drive, 0.5 foot below the roadway; the center of two filed notches.

DNR TBM SLK 23 1977 Silver Lake

In Steuben County, in the <u>NW ¼ Sec. 31, T. 37 N., R. 13 E., 2nd PM</u>, about 4.3 miles west-southwest of <u>Angola</u>; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.5 mile south to a turn east, thence 0.3 mile east to a turn south and a private drive east; set in the top of the north end of a 4-foot steel pipe culvert under the drive, 14.5 feet north from the center line of the private drive, 0.5 foot below the driveway; the center of two filed notches.

DNR TBM SLK 24 1977 Silver Lake

In Steuben County, in the NW ¼ Sec. 31, T. 37 N., R. 13 E., 2nd PM, about 4 miles west-southwest of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.5 mile south to a turn east, thence 0.3 mile east to a turn south and a private drive east; set in the east side of a power pole in the northeast quarter of the junction, 186 feet east from the center line of the north-south road tangent, 300 feet north from the center line of the private drive, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 24 1977."

DNR BM STE 44 1977 Tamarack Lake Chair Factory Lake In Steuben County, in the \underline{E} ½ Sec. 27, \underline{T} . 38 N., \underline{R} . 12 \underline{E} ., $\underline{2}^{nd}$ PM, about 2.1 miles southeast of Orland; 1.7 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a north-south crossroad (800 West Road), thence 1.4 miles south to a \underline{T} -road east (525 North Road), thence 1.0 mile east to a 4-foot steel pipe culvert under the road; set in the top of a concrete post on the south side of the road; 186 feet west from the center line of the culvert, 22.0 feet south from the center line of the road, 1.5 feet west from power pole #483/991, 1.5 feet north from an east-west fence; a Department of Natural Resources brass control station tablet, stamped "STE 44 1977."

DNR TBM JL 1 1972 Unnamed lake Grass Lake

In Steuben County, in the NW ¼ Sec. 13, T. 37 N., R. 12 E., 2nd PM, about 5.9 miles northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.35 miles west to a north-south crossroad (600 West Road), thence 1.0 mile north to an east-west crossroad (200 North Road); set in the northwest side of a 15-inch walnut tree in the southeast quarter of the intersection, 232 feet south from the center line of the east-west road, 17 feet east from the center line of the north-south road, 3.2 feet west from a fence line, 0.3 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 1 1972."

DNR BM STE 79 1978 unnamed lake

In Steuben County, in the <u>SW ¼ Sec. 12, T. 37 N., R. 12 E., 2nd PM</u>, about 5.6 mils west-northwest of <u>Angola</u>; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.35 miles west to a north-south crossroad (600 West Road), thence 1.0 mile north to an east-west crossroad (200 North Road), 0.4 mile east and northeast to a power pole on the southeast side of the road; set in the top of a concrete post, 400 feet northeast from a turn northeast in the road, 29.0 feet southwest from the power pole, 18.8 feet southeast from the center line of the road, 2.3 feet northwest from a guy-wire anchor bolt for the power pole, 1.0 foot below the roadway, 0.2 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 79 1978."

DNR TBM SLK 115 1978 unnamed lake

In Steuben County, in the SW ¼ Sec. 12, T. 37 N., R. 12 E., 2nd PM, about 5.6 miles west-northwest of Angola; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.35 miles west to a north-south crossroad (600 West Road), thence 1.0 mile north to an east-west crossroad (200 North Road), thence 0.4 mile east and northeast to a power pole on the southeast side of the road; set in the west side of a power pole, 420 feet northeast from a turn west, 37.2 feet southeast from the center line of the road, 8.0 feet blow the roadway, 1.3 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 115 1978".

DNR TBM JL 2 1972 unnamed lake Round lake

In Steuben County, in the <u>SE ¼ Sec. 2, T. 37 N., R. 12 E., 2nd PM</u>, about 6.4 miles northwest of <u>Angola</u>; 1.5 miles north along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (100 North Road), thence 5.35 miles west to a north-south crossroad (600 West Road), thence 2.0 mile north to an east-west crossroad (300 North Road); set in the east side of a 15-inch oak tree in the northwest quarter of the junction, 97 feet west from the center line of the north-south road, 19 feet north from the center line of the east-west road, 0.6 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM JL 2 1972."

992.767

DNR BM STE 88 1985

In Steuben County, Angola West Quad, NE ¼ Sec. 21, T. 38 N., R. 13 E, about 5.0 miles north of Angola near the north end of Snow Lake, 0.3 mile south along Bay Drive (deadend) from its junction with S.R. 120 and a gravel road north (225 W. Road) set in the top of a concrete post. 72.0 feet northwest from a residence mailbox #709. 16.0 feet west from the centerline of the east drive of the turn around. 4.5 feet north from a power pole, (Steuben Co. REMC) pole has transformer on top. 2.0 feet east from a steel fence post. (Witness Post) 2.0 feet east from a steel fence post. (Witness Post) Painted red and green. 0.1 foot above the roadway, level with the ground. An Indiana Department of Natural Resources bench mark tablet, stamped "STE 88 1985"

FOUND 9-8-99 BC 984.452

Ashley Quadrangle

DNR BM STE 6 1975 Black Lake

In Steuben County, in the <u>SE ¼ Sec. 2, T. 26 N., R. 12 E., 2nd PM</u>, about 5.3 miles northwest of <u>Ashley</u>; about 4.62 miles north along State Road 727 from its intersection with State Road 4 in Ashley to a T-road west (Lake Valley Road), thence 1.8 miles generally west to a north-south crossroad (600 West Road); set in the top of a concrete post in the northwest quarter of the junction, 22.5 feet west from the center line of the north-south junction, 22.5 feet west from the center line of the north-south road, 22.2 feet north from the extended center line of the T-road east, 2.3 feet north from a power pole, 1.2 feet east from a fence line, 0.3 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 6 1975."

USGS RM No. 11 Gaging Station Bower Lake Tamarack Lake
In Steuben County, in the SW ¼ Sec. 5 T. 36 N., R. 13 E., 2nd PM, about 3.0 miles
northwest of Pleasant Lake; 1.95 miles generally west along 500 South Road from its
junction with 150 West Road at Pleasant Lake to a north-south crossroad (325 West
Road), thence 2.1 miles generally north to a northeast-southwest crossroad (Golden Lake
Road), thence 0.2 mile northeast to an entrance road leading to a public fishing site for
Bower Lake; set in the top of a concrete lake level monument, 66 feet east from the
center line of the road, 40.0 feet south from the center line of the entrance road, 39.0 feet
west from the end of a concrete boat ramp, 2.5 feet above the ground; a U.S. Geological
Survey gaging station tablet, not stamped.

DNR TBM SLK 704 A 1978 Fox Lake

In Steuben County, in the NE ¼ Sec. 34, T. 37 N., R. 13 E., 2nd PM, about 0.9 mile southwest of Angola; 0.75 mile south along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to a T-road west (Fox Lake Road), thence 0.5 mile west to a wooden bridge over the New York Central Railroad; set in the west side of a 5-inch tree in the northwest quarter of the crossing, 163 feet north from the center line of the bridge, 14.0 feet west from the west rail, 1.0 foot above the ground, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 704A 1978."

1060.830

DNR TBM SLK 82 1978 Fox Lake

In Steuben County, in the NE ¼ Sec. 37 N., R. 13 E., 2nd PM, about 3.34 miles north of Pleasant Lake; 3.4 miles generally north along 150 West Road from its intersection with Main Street at Pleasant Lake to a culvert under the road in the outlet channel for Fox Lake; set in the northwest side of power pole #471/068, 72.4 feet northeast from the center line of the road, 1.5 feet above the ground; a railroad spike.

USGS RM Gaging Station Fox Lake *Recovered RST 5-24-88* In Steuben County, in the NE ¼ Sec. 34, T. 37 N., R. 13 E., 2nd PM, about 3.34 miles north of <u>Pleasant Lake</u>; 3.4 miles generally north along 150 West Road from its intersection with Main Street at Pleasant Lake to a culvert under the road in the outlet channel for Fox Lake, set in the top of a concrete lake level monument, 79 feet west and across the road from power pole #471/068, 18.3 feet northwest from the center line of the road, 7.1 feet northeast from the center line of the culvert, 1.7 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

DNR BM STE 81 1978 Fox Lake *Recovered in excellent condition RST 5-24-88* In Steuben County, in the NW ¼ Sec. 34, T. 37 N., R. 13 E., 2nd PM, about 3.25 miles north of Pleasant Lake; 3.2 miles north along 150 West Road from its intersection with Main Street at Pleasant Lake to a T-road west (Fox Lake Road), set in the top of a concrete post in the northwest quarter of the junction at a Public Access Site for Fox Lake, 125 feet west from the center line of the road, 94 feet north from the center line of the T-road west, 25 feet south from the south edge of the lake, 1.7 feet east from a fence line, flush with the ground; a Department of Natural Resources brass control station tablet, stamped "STE 81 1978."

USC&GS BM C22 1934 Fox Lake

In Steuben County, in the \underline{W} ½ Sec. 2, \underline{T} . 36 N., \underline{R} . 13 E., $\underline{2}^{nd}$ PM, about 2.22 miles north of Pleasant Lake; 2.22 miles generally north along the New York Central Railroad from its intersection with State Road 727 at Pleasant Lake to an east-west farm lane; set in the top of a concrete post in the southeast quarter of the intersection, 675 feet north from milepost #38, 23.4 feet southeast from the intersection of the farm lane center line and the east rail, 21.0 feet east from the east rail, 14.6 feet east from the north concrete base of a rail support, level with the track surface; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "C22 1934."

DNR BM STE 27 1977 Golden Lake Boer Lake

In Steuben County, in the <u>SW ½ Sec. 8, T. 36 N., R. 13 E., 2nd PM</u>, about 2.75 miles northwest of <u>Pleasant Lake</u>; 1.95 miles generally west along 500 South Road from its junction with 150 West Road at Pleasant Lake to a north-south crossroad (325 West Road), thence 2.1 miles generally north to a southwest-northeast crossroad (Golden Lake Road), thence 0.1 mile northeast to a concrete bridge over the channel between Bower and Golden Lakes; set in the top of the east end of the first pier south from the north end of the bridge, 35.6 feet south from the north end of the bridge, 14.0 feet east from the center line of the road, 2.4 feet below the roadway, 0.7 feet west from the east face of the pier; a Department of Natural Resources brass control station tablet, stamped "STE 27 1977."

DNR TBM SLK 35 1977 Gravel Pit Lake

In Steuben County, in the NW ¼ Sec. 14, T. 36 N., R. 13 E., 2nd PM; about 3.3 miles south of Angola; 3.5 miles south along U.S. Highway 27 from its intersection with U.S. 20 in Angola to an east-west crossroad (400 South Road); set in the top of a concrete highway right-of-way marker in the southeast quarter of the intersection, 50 feet east from the center line of the highway, 24.0 feet south from the center line of the road, 0.9 foot above the ground; a painted chiseled corner.

DNR TBM SLK 29 1977 Hogback Lake

In Steuben County, in the NE ¼ Sec. 1, T. 36 N., R. 12 E., 2nd PM, about 5.5 miles west-southwest of Angola; 6.5 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (600 West Road), thence 1.5 miles south to a 4-foot steel pipe culvert under the road; set in the top of the south end of the culvert, 18.0 feet south from the center line of the road, 3.5 feet below the roadway; the center of two filed notches.

DNR BM STE 7 1975 Hogback Lake

In Steuben County, in the <u>SW ¼ Sec. 36, T. 37 N., R. 12 E., 2nd PM</u>, about 6.4 miles northwest of <u>Ashley</u>; 3.1 miles north along State Road 272 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road), thence 1.8 miles west to a north-south crossroad (600 West Road), thence 3.0 miles north to a T-road east (200 South Road); set in the top of a concrete base of a fence post in the southeast quarter of the junction, 79 feet east from the center line of the north-south road, 21.1 feet south from the center line of the T-road east, 0.4 foot north from the fence post; a Department of Natural Resources brass control station tablet, stamped "STE 7 1975." 967.942

DNR TBM SLK 3 1975 Johnson Ditch

In Steuben County, in the NE ¼ Sec. 33, T. 36 N., R. 13 E., 2nd PM, about 2.0 miles northeast of Ashley; 1.0 mile north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (700 South Road), thence 1.75 miles east to a north-south crossroad (225 West Road); set in the top of a 3-foot concrete culvert in the southwest quarter of the intersection, 127 feet south from the center line of the east-west road, 13.5 feet west from the north-south road, 0.1 foot west from the east face of the culvert, 0.1 foot south from the north face of the culvert; a chiseled triangle.

983.863

DNR TBM 12 1971 Johnson Ditch

In Steuben County, in the <u>NW ¼ Sec. 33, T. 36 N., R. 13 E., 2nd PM</u>, about 1.5 miles northeast of <u>Ashley</u>; 1.0 mile north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (700 South Road), thence 1.2 miles east to a 16-foot concrete bridge over <u>Johnson Ditch</u>; set in the top of the east end of the south concrete headwall, 12.8 feet south from the center line of the road, 0.9 foot above the roadway, 0.5 foot west from the east end of the headwall; a chiseled triangle.

DNR BM STE 1 1975 Johnson Ditch

In Steuben County, in the NW ¼ Sec. 33, T. 36 N., R. 13 E., 2nd PM, about 1.5 miles northeast of Ashley; 1.0 mile north along State Road 727 from its intersection with State Road 4 in Ashley to a 16-foot concrete bridge over Johnson Ditch; set in the top of the concrete base of the southwest wingwall, 16.0 feet south from the center line of the road, 6.7 feet below the roadway, 1.4 feet northeast from the southwest end of the concrete base of the wingwall, 0.6 foot northwest from the southeast face of the wingwall; a Department of Natural Resources brass control station tablet, stamped "STE 1 1975."

ISHC BM STEU F 15 Johnson Ditch

In Steuben County, in the <u>SW ½ Sec. 29, T. 36 N., R. 13 E., 2nd PM,</u> about 1.15 miles northeast of <u>Ashley</u>; 1.0 mile north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (700 South Road), thence 0.4 mile east to an Interstate Highway 69 overpass bridge; set in the top of the west end of the north concrete curbing of the bridge, 16.3 feet north from the center line of the road, 1.2 feet east from the west end of the curbing, 0.9 foot above the roadway; an Indiana State Highway Commission bench mark tablet, stamped "STEU F 15."

DNR TBM 14 1971 Johnson Ditch

In Steuben County, in the <u>SE ¼ Sec. 30, T. 36 N., R. 13 E., 2nd PM</u>, about 1.0 mile north of <u>Ashley</u>; 1.0 mile north along State Road 727 from its intersection with County Line Road in Ashley to an east-west crossroad (700 South Road); set in the top of the concrete base of a steel pipe fence post in the northwest quarter of the intersection, 60 feet west from the center line of the highway, 27 feet north from the center line of the east-west road; a chiseled triangle.

DNR BM STE 2 1975 Johnson Ditch

In Steuben County, in the NW ¼ Sec. 32, T. 36 N., R. 13 E., 2nd PM, about 1.0 mile north of Ashley; 1.0 mile north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (700 South Road); set in the top of a concrete post in the northwest quarter of the intersection, 74 feet north from the center line of the east-west road, 38.0 feet west from the center line of the north-south road, 1.0 foot east from a power pole; a Department of Natural Resources brass control station tablet, stamped "STE 2 1975."

DNR BM STE 3 1975 Johnson Ditch

In Steuben County, in the <u>SW ¼ Sec. 20, T. 36 N., R. 13 E., 2nd PM,</u> about 2.0 miles north of <u>Ashley</u>; 2.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (600 South Road); set in the top of a concrete post in the northeast quarter of the intersection, 36.7 feet east from the center line of the north-south road, 24.5 feet north from the center line of the east-west road, 1.4 feet north from power pole #475/946, 1.3 feet west from a fence line, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 3 1975."

USGS BM W 7 1968 Johnson Ditch

In Steuben County, in the NE ¼ Sec. 19, T. 36 N., R. 13 E., 2nd PM, about 3.0 miles north of Ashley; 3.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road); set in the top of a concrete post in the southwest quarter of the intersection, 93 feet south from the center line of the east-west road, 42.1 feet west from the center line of the north-south road, 0.6 foot southeast from a concrete fence corner post, flush with the ground; a U.S. Geological Survey bench mark tablet, stamped "W 7 1968 1011."

DNR TBM SLK 33 1977 Johnson Ditch Mud Lake

In Steuben County, in the NE ¼ Sec. 20, T. 36 N., R. 13 E., 2nd PM, about 1.7 miles west of Pleasant Lake; 1.8 miles west along 500 South Road from its junction with 150 West Road at Pleasant Lake to a concrete bridge over Johnson Ditch; set in the top of the west end of the north concrete curb, 18.5 feet north from the center line of the road, 0.85 foot east from the west end of the curb, 0.80 feet above the roadway; a chiseled triangle.

966.480

USGS BM W44 1937 Johnson Lake Silver Lake

In Steuben County, in the W½ Sec. 32, T. 37 N., R. 13 E., 2nd PM, about 3.5 miles southwest of Angola; 2.6 miles west along U.S Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (300 West Road), thence 1.0 mile south to a T-road west (150 South Road), thence 0.75 mile west to an over grown private drive south; set in the top of a concrete post, 20.0 feet west from the center line of the private drive, 15.0 feet south from the center line of the road, 4.0 feet north from a fence corner; a U.S. Geological Survey bench mark tablet, stamped "W44 1937 966." 996.401

DNR BM STE 82 1978 Little Turkey Lake

In Steuben County, in the NE ¼ Sec. 35, T. 35 N., R. 12 E., 2nd PM, about 1.3 miles west-northwest of Hudson; 0.77 mile north along Main Street (500 West Road) from its intersection with the Wabash Railroad in Hudson to an east-west crossroad (700 South Road), thence 1.25 miles west to a T-road south leading to a Public Fishing Site for Little Turkey Lake, thence 0.35 mile south to a concrete boat ramp; set in the top of a concrete post, 130 feet north from the north end of a concrete boat ramp, 27.2 feet west from the center line of the road, 1.8 feet east from a fence line; a Department of Natural Resources brass control station tablet, stamped STE 82 1978.

DNR TBM SLK 108 1978 Little Turkey Lake

In Steuben County, in the NE ¼ Sec. 35, T. 35 N., R. 12 E., 2nd PM, about 1.3 miles west-northwest of Hudson; 0.77 mile north along Main Street (500 West Road) from its intersection with the Wabash Railroad in Hudson to an east-west crossroad (700 South Road), thence 1.25 miles west to a T-road south leading to a Public Fishing Site for Little Turkey Lake, thence 0.35 mile south to a concrete boat ramp; set in the south side of a 12-inch cotton wood tree on the east side of the road, 110 feet north from the north end of the boat ramp, 21.9 feet east from the center line of the road, 1.6 feet west from a fence line, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 108 1978."

DNR TBM 16 1971 Little Turkey Lake *Recovered RST 5-17-89*In Steuben County, in the NE ½ Sec. 35, T. 36 N., R. 12 E., 2nd PM, about 1.4 miles west-northwest of Hudson; 0.6 mile north along 500 West Road from its intersection with 760 South Road in Hudson to an east-west crossroad (700 South Road), thence 1.3 miles west to a T-road south leading to Little Turkey Lake; set in the top of an eye bolt protruding from a concrete fence corner post in the southwest quarter of the junction, 25.5 feet west from the center line of the T-road south, 17.5 feet south from the center line of the road, 1.5 feet above the ground; a filed V.

982.436

DNR BM STE 4 1975 Little Turkey Lake

In Steuben County, in the <u>SW ¼ Sec. 18, T. 36 N., R. 13 E., 2nd PM</u>, about 3.2 miles northwest of <u>Ashley</u>; 3.1 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road), thence 0.8 mile west to a north-south crossroad (500 West Road); set in the top of a concrete post in the northeast quarter of the intersection, 108 feet east from the center line of the north-south road, 27.2 feet north from the center line of the east-west road, 3.0 feet above the roadway, 1.9 feet south from the telephone pole #2783, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 4 1975."

1030.329

USC&GS Triangulation Station HUDSON 1946 Little Turkey Lake In Steuben County, in the SE ¼ Sec. 14 T. 36 N., R. 12 E., 2nd PM, about 3.5 miles northwest of Ashley; 3.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road), thence 1.9 miles west to a farm drive north; set in the top of a concrete post in the northeast quarter of the junction, 77 feet north from the center line of the road, 68 feet west from the southwest corner of a farmhouse, 58 feet northeast from the west end of a stone embankment, 30.6 feet east from the center line of the farm drive, flush with the ground; a U.S. Coast and Geodetic Survey triangulation station tablet, stamped "HUDSON 1946."

1085.208

USC&GS RM HUDSON No. 1 1946 Little Turkey Lake

In Steuben County, in the <u>SE ½ Sec. 14, T. 36 N., R. 12 E., 2nd PM</u>, about 3.5 miles northwest of <u>Ashley</u>; 3.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road), thence 1.9 miles west to a farm drive north; set in the top of a concrete post in the northeast quarter of the junction, 163 feet north from the center line of the road, 91 feet east from the center line of the driveway, 50 feet northwest from the northwest corner of a farmhouse, flush with the ground; a U.S. Coast and Geodetic Survey reference mark tablet, stamped "HUDSON No. 1 1946."

USC&GS GM HUDSON No. 2 1946 Little TurkeyLake

In Steuben County, in the <u>SE ¹/₄ Sec. 14, T. 36 N., R. 12 E., 2nd PM,</u> about 3.5 miles northeast of <u>Ashley</u>; 3.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to an east-west crossroad (500 South Road), thence 1.9 miles west to a farm drive north; set in the top of a concrete post in the northeast quarter of the junction, 182 feet north from the center line of the road, 9.9 feet east from the center line of the drive north, 2.0 feet southeast from the southwest corner of a barn, flush with the ground; a U.S. Coast and Geodetic Survey reference mark tablet, stamped "HUDSON No. 2 1946."

DNR BM STE 5 1975 Little Turkey Lake

In Steuben County, in the NE ¼ Sec. 14, T. 36 N., R. 12 E., 2nd PM; about 4.4 miles northwest of Ashley; 4.0 miles north along State Road 727 from its intersection with State Road 4 in Ashley to a T-road west (400 South Road), thence 1.8 miles west to a north-south crossroad (600 West Road); set in the top of a concrete post in the southwest quarter of the intersection, 52 feet south from the center line of the east-west road, 25.4 feet west from the center line of the north-south road, 2.1 feet southeast from a power pole, 0.2 foot above the ground; a Department of Natural Resources brass control Station tablet, stamped "STE 5 1975."

DNR BM STE 54A 1977 Long Lake Gravel Pit Lake *Recovered* 21 Sept. 88 LJS In Steuben County, in the NW ¼ Sec. 16, T. 36 N., R. 13 E., 2nd PM, about 0.9 mile northwest of Pleasant Lake; 0.25 mile north along 150 West Road from its intersection with Bellefontaine Road at Pleasant Lake to a T-road northwest (450 South Road), thence 0.75 mile generally northwest to a store owned by Mr. Slacks; set in the top of a concrete post in the back yard of the store grounds, 125 feet south from the center line of the road, 73 feet north from the north shore of the lake, 56.3 feet southwest from the southeast corner of the store, 9.5 feet east from an outhouse, 2.2 feet south from a power pole, 0.05 foot below the ground; a Department of Natural Resources brass control station tablet, stamped "STE 54A 1977."

USGS RM Gaging Station Long Lake Gravel Pit Lake
In Steuben County, in the NW 1/4 Sec. 16, T. 36 N., R. 13 E., 2nd PM, about 0.9 mile northwest of Pleasant Lake; 0.25 mile north along 150 West Road from its intersection with Bellefontaine Road at Pleasant Lake to a T-road northwest (450 South Road), thence 0.75 mile generally northwest to a store owned by Mr. Slacks; set in the southeast side of a 30-inch sycamore tree, 155 feet south from the center line of the road, 55.4 feet southeast from a power pole, 43.9 feet north from the north shore of the lake, 0.6 foot above the ground; a lag screw.

DNR TBM SLK 34 1977 Long Lake Pleasant Lake

In Steuben County, in the <u>SE ½ Sec. 16, T. 36 N., R. 13 E., 2nd PM</u>, about 0.8 mile west of <u>Pleasant Lake</u>; 0.8 mile generally west along 500 South Road from its junction with 150 West Road at Pleasant lake to a 6-foot steel pipe culvert under the road; set in the top of the south end of the culvert, 46.0 feet east from power pole #478/257, 41.0 feet south from the center line of the road, 7.0 feet below the roadway; the center of two chiseled notches.

DNR TBM SLK 240 1977 Meserve Lake

In Steuben County, in the <u>SW ½ Sec. 14, T. 36 N., R. 13 E., 2nd PM</u>, about 0.35 mile east of <u>Pleasant Lake</u>; 0.2 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to a T-road east, thence 0.4 mile east to a north-south crossroad, thence 0.01 mile north to a 10-foot steel pipe culvert in the outlet channel for Meserve Lake; set in the top of the east end of the culvert, 14.0 feet east from the center line of the road, 1.0 foot below the roadway, 0.4 foot west from the east end of the culvert; a filed cross.

DNR BM STE 49 1977 Mud Lake

In Steuben County, in the NE ¼ Sec. 17, T. 36 N., R. 13 E., 2nd PM, about 1.95 mile northwest of Pleasant Lake; 1.95 miles generally west along 500 South Road from its junction with 150 West Road at Pleasant Lake to a north-south crossroad (325 West Road), thence 0.9 mile north to power pole #E B176 SPPH 635 on the west side of the road; set in the top of a concrete post, 324 feet south from the center line of an entrance drive to Favorite Farms, 21.0 feet west from the center line of the road, 2.0 feet south from the power pole; a Department of Natural Resources brass control station tablet, stamped "STE 49 1977."

DNR TBM SLK 30 1977 Pigeon Creek Golden Lake Mink Lake In Steuben County, in the S½ Sec. 31, T. 37 N., R. 13 E., 2nd PM, about 4.2 miles west-southwest of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.8 mile south and east to a turn south (450 West Road), thence 0.95 mile south to a concrete bridge over Pigeon Creek; set in the top of the east end of the first pier south from the north end of the bridge, 17.8 feet south from the north end of the bridge, 15.0 feet east from the center line of the road, 1.1 feet below the roadway; a chiseled triangle.

DNR BM STE 26 1977 Pigeon Creek Golden Lake Mink Lake In Steuben County, in the SW ¼ Sec. 31, T. 37 N., R. 13 E., 2nd PM, about 4.2 miles west-southwest of Angola; 4.4 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (500 West Road), thence 0.8 mile south and east to a turn south (450 West Road), thence 0.95 mile south to a concrete bridge over Pigeon Creek; set in the of the southwest wingwall of the bridge, 16.5 feet south from the center line of the road, 9.8 feet north from the south face of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 26 1977."

ISHC BM STEU F 12 Pigeon Creek Little Bower Lake

In Steuben County, in the NE ¼ Sec. 8, T. 36 N., R. 13 E., 2nd PM, about 2.5 miles northwest of Pleasant Lake; 1.95 miles generally west along 500 South Road from its junction with 150 West Road at Pleasant Lake to a north-south crossroad (325 West Road), thence 1.6 miles generally north to an overpass bridge over Interstate 69; set in the top of the west end of the north concrete curb of the bridge, 15.0 feet north from the center line of the road, 2.5 feet east from the west end of the bridge curb, 0.7 foot above the roadway; an Indiana State Highway Commission bench mark tablet, stamped "STEU F 12."

DNR BM STE 28 1977 Pigeon Creek Little Bower Lake In Steuben County, in the NE ¼ Sec. 8, T. 36 N., R. 13 E., 2nd PM, about 3.8 miles southwest of Angola; 2.5 mile west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad interchange (Interstate 69), thence 2.7 miles generally south to twin highway bridges over Pigeon Creek; set in the top of the south end of the west guardrail of the south-bound bridge, 20.3 feet west from the center line of the highway, 0.7 foot above the highway, 0.3 foot north from the south end of the guardrail; a Department of Natural Resources brass control station tablet, stamped "STE 28 1977."

DNR BM STE 29 1977 Pigeon Creek Long Lake

In Steuben County, in the SE ¼ Sec. 15, T. 36 N., R. 13 E., 2nd PM, at Pleasant Lake; 0.1 mile north along an abandoned New York Central Railroad from its intersection with Bellefontaine Road (Main Street) at Pleasant Lake to a railroad trestle bridge over Pigeon Creek; set in the top of the southeast end of the southwest bridge abutment, 7.8 feet southeast from the southeast rail, 1.2 feet below the rails, 1.0 foot southwest from the northeast face of the abutment; a Department of Natural Resources brass control station tablet, stamped "STE 29 1977."

DNR BM STE 30 1977 Pigeon Creek

In Steuben County, in the SW ¼ Sec. 14, T. 36 N., R. 13 E., 2nd PM, about 0.3 miles along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to a concrete bridge over Pigeon Creek; set in the top of the east end of the south bridge abutment, 19.9 feet east from the center line of the road, 0.5 foot south from the north face of the abutment, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 30 19977."

USC&GS BM D 22 1934 Pleasant Lake

In Steuben County, in the <u>SE ¼ Sec. 15, T. 36 N., R. 13 E., 2nd PM</u>, at <u>Pleasant Lake</u>; at the intersection of 500 South Road and the abandoned New York Central Railroad; set in the top of a concrete post, 234 feet south from the center line of the road, 90 feet north from the north end of a railroad station, 17.8 feet east from the east rail, 0.5 foot above the ground; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "D 22 1934."

976.369

USGS RM No. 6 Gaging Station Pleasant Lake

In Steuben County, in the SW ¼ Sec. 14, T. 36 N., R. 13 E., 2nd PM, at Pleasant Lake; at the intersection of U.S. Highway 27 and Bellefontaine Road; set in the top of a concrete lake level monument, 250 feet northwest from the center line of the highway, 250 feet southwest from the center line of the road, 25.0 feet southwest from the southwest corner of a brown shingle cabin, 21.4 feet northeast from the northeast edge of the lake, 2.3 feet northwest from a white wooden picket fence, 1.8 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 706 1977 Reed Lakes

In Steuben County, in the E $\frac{1}{2}$ Sec. 10, T. 38 N., R. 13 E., 2^{nd} PM, about 1.3 miles north of Pleasant Lake; 1.4 miles generally north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to a gravel T-road west (350 South Road), thence 0.1 mile west to a north-south railroad crossing (New York Central Railroad); set in the top of a wooden railroad tie centered between the rails, 30.0 feet south from the center line of the road; a painted railroad spike.

DNR TBM SLK 31 1977 Silver Lake

In Steuben County, in the \underline{E} ½ Sec. 32, T. 37 N., R. 13 E., 2^{nd} PM, about 2.8 miles southwest of Angola; 2.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a T-road south (300 West Road), thence 1.0 mile south to a T-road west (150 South Road); set in the southwest side of a twin trunk walnut tree, 52 feet west from the center line of the road, 20.0 feet south from the center line of the T-road west, 1.5 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "TBM SLK 31 1977."

DNR TBM 15 1971 Smathers Ditch Little Turkey Lake

In Steuben County, in the <u>SE ½ Sec. 25, T. 36 N., R. 12 E., 2nd PM</u>, about 7.6 mile north of Hudson; 0.76 mile north along 500 West Road from its intersection with the Wabash Railroad in Hudson to an east-west crossroad (700 South Road); set in the top of the northeast wingwall of a bridge over <u>Smathers Ditch</u>, 33 feet north from the center line of the east-west road, 15 feet west from the center line of the north-south road, 1.0 foot south from the north face of the wingwall; a chiseled triangle.

983.254

DNR TBM SLK 32 1977 Tamarack Lake

In Steuben County, in the <u>NW ¼ Sec. 4, T. 37 N., R. 13 E., 2nd PM</u>, about 2.2 miles southwest of <u>Angola</u>; 2.6 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in <u>Angola</u> to a T-road south (300 West Road), thence 1.75 miles south to a T-road east (West Fox Lake Road) and twin highway bridges over West Fox Lake Road for Interstate 69; set in the top of the northeast corner of a concrete headwall of a culvert under the T-road, 48.0 feet east from the center line of the north-South Road, 27.0 feet west from a northwestern most concrete pier, 20.5 feet north form the center line of the T-road, 2.0 feet below the roadway; a chiseled corner.

DNR TBM SLK 99 1977 Turkey Creek Little Turkey Lake

In Steuben County, in the NE ¼ Sec. 34, T. 36 N., R. 12 E., 2nd PM, about 2.3 miles west-northwest of Hudson; 0.6 mile north along 500 West Road from its intersection with 760 South Road in Hudson to an east-west crossroad (700 South Road), thence 2.25 miles west to a north-south crossroad (725 West Road), thence 0.25 mile south to a concrete bridge over Turkey Creek; set in the top of the northwest wingwall, 12.7 feet west from the center line of the road, 1.0 foot north from the south end of the wingwall, 0.1 foot below the road; a chiseled triangle.

DNR BM STE 75 1977 Turkey Creek Little Turkey Lake

In Steuben County, in the NE ¼ Sec. 34, T. 36 N., R. 12 E., 2nd PM, about 2.3 miles west-northwest of Hudson; 0.6 mile north along 500 West Road from its intersection with 760 South Road in Hudson to an east-west crossroad (700 South Road), thence 2.25 miles west to a north-south crossroad (725 West Road), thence 0.25 mile south to a concrete bridge over Turkey Creek; set in the top of the northeast wingwall of the bridge, 14.0 feet east from the center line of the road, 1.0 foot southwest from the northeast end of the wingwall, 0.5 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 75 1977."

DNR TBM HL 1 1972 unnamed lakes

In Steuben County, in the <u>SW ¼ Sec. 26, T. 36 N., R. 13 E., 2nd PM</u>, about 2.15 miles south of <u>Pleasant Lake</u>; 2.15 miles south along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (700 South Road); set in the top of the north end of a culvert in the northwest quarter of the junction, 60 feet north from the center line of the east-west road, 21 feet west from the center line of the highway, 1.7 feet south from the north end of the culvert; a chiseled triangle.

1006.245

USC&GS BM E 22 1934 unnamed lakes

In Steuben County, in the NW ¼ Sec. 34, T. 36 N., R. 13 E., 2nd PM, about 0.7 mile north of Steubenville; 0.7 mile north along the New York Central Railroad from its intersection with the Wabash Railroad at Steubenville to an east-west crossroad (700 South Road); set in the top of a concrete post, 50 feet south from the center line of the road, 36.0 feet east from the east rail, level with the tracks; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "E 22 1934."

USC&GS BM F 22 1934 unnamed lakes

In Steuben County, in the <u>NW ¼ Sec. 34, T. 36 N., R. 13 E., 2nd PM</u>, at <u>Steubenville</u>; at the intersection of the New York Central and Wabash Railroads; set in the top of the Northwest corner of a signal block base, 495 feet north from the center line of the eastwest tracks, 6.2 feet west from the west rail of the north-south tracks, 2.0 feet above the tracks; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "F 22 1934."

DNR TBM SLK 2 1975 unnamed lakes

In Steuben County, in the SW ¼ Sec. 34, T. 36 N., R. 13 E., 2nd PM, about 2.1 mils east of Ashley; 2.0 miles east along State Road 4 from its intersection with 400 West Road in Ashley to a north-south crossroad (200 West Road); set in the top of the northeast end of a right-of-way marker in the northeast quarter of the intersection, 90 feet north from the center line of the highway, 26.7 feet east from the center line of the road, 8.7 feet west from a fence line, 2.3 feet above the ground; a painted chiseled triangle.

988.574

DNR TBM SLK 1 1975 unnamed lakes

In Dekalb County, in the <u>SE ½ Sec. 4., T. 35 N., R. 13 E., 2nd PM</u>, about 2.2 miles southeast of <u>Ashley</u>; 2.0 miles east along State Road 4 from its intersection with 400 West Road in Ashley to a north-south crossroad (200 West Road), thence 0.6 mile south to a private driveway east; set in the southeast side of power pole #478/164 in the southwest quarter of the junction, 36.4 feet south from the extended center line of the driveway, 20.1 feet west from the center line of the road, 0.65 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 1 1975."

993.420

USC&GS BM G 22 1934 unnamed lakes

In Dekalb County, in the <u>SW ¼ Sec. 3, T. 35 N., R. 13 E., 2nd PM,</u> at <u>Summit</u> (Dekalb County); at the intersection of the abandoned New York Central Railroad and an eastwest crossroad; set in the top of a concrete post in the northwest quarter of the intersection, 48.0 feet north from the center line of the road, 33.0 feet west from the west rail, 4.0 feet above the tracks; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "G 22 1934."

Bronson South Quadrangle

DNR TBM LLK 213 1977 Fawn River

In Lagrange County, in the W½ Sec. 13, T. 38 N., R. 11 E., 2nd PM, about 0.5 mile east of Greenfield Mills; 0.5 mile east along 750 North Road from its junction with 1050 East Road at Greenfield Mills to a north-south crossroad (1100 East Road); set in the north side of a 36-inch wild cherry tree in the southeast quarter of the intersection, 62 feet south from the center line of the east-west road, 23.0 feet east from the center line of the north-south road, 3.0 feet east from a fence line, 0.6 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM LLK 213 1977."

DNR TBM SLK 212 1977 Lime Lake

In Steuben County, in the W½ Sec. 18, T. 38 N., R. 12 E., 2nd PM, about 1.77 miles east of Greenfield Mills (Lagrange County); 1.77 miles east along 750 North Road from its junction with 1050 East Road at Greenfield Mills to a turn south (Lime Lake Road); set in the south side of power pole #484/289 in the northwest quarter of the turn, 350 feet west from the north-south center line tangent of the road, 20.0 feet north from the east-west center line tangent of the road, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 212 1977."

California Quadrangle

DNR TBM SLK 69 1978 Cedar Lake

In Brach County, Michigan, in the SW ¼ Sec. 21, T. 8 S., R. 5 W., Michigan Meridian, about 2.62 miles northeast of Fremont; 1.98 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road east (State Line Road), thence 1.69 miles east to a northeast-southwest crossroad (500 East Road); set in the south side of a 38-inch oak tree in the northeast quarter of the intersection, 205 feet east from the center line of the northeast-southwest road, 15.0 feet north from the center line of the east-west road, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 69 1978."

DNR TBM SLK 70 1978 Cedar Lake

In Steuben County, in the NE ¼ Sec. 14, T. 38 N., R. 14 E., 2nd PM, about 0.61 mile east of Ray; 0.61 mile east along State Line Road from its intersection with Del Mar Road at Ray to north-south crossroad (575 East Road); set in the north side of a 22-inch oak tree located on the west side of a group of trees in the southeast quarter of the intersection, 500 feet east from the center line of the north-south road, 19.7 feet south from the center line of the east-west road, 0.7 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 70 1978."

USGS BM TT 24T 1937 Fish Lake

In Steuben County, in the NW ¼ Sec. 16, T. 38 N., R. 14 E., 2nd PM, about 1.97 miles north of Fremont; 1.98 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road east (State Line Road); set in the top of a concrete post in the southwest quarter of the junction, 24.6 feet west from the center line of the north-south road, 2.7 feet east from a fence corner post, 0.2 foot above the ground, about on the extended center line of the T-road east; a U.S. Geological Survey bench mark tablet, stamped "TT 24T 1937."

DNR TBM SLK 68 1978 Fish Lake

In Steuben County, in the NE ¼ Sec. 16, T. 38 N., R. 14 E., 2nd PM, about 2.03 miles north of Fremont; 1.98 miles north along Wayne Street from its intersection with State Road 120 in Fremont to a T-road east (State Line Road), thence 0.5 mile east to a T-road north; set in the side of an 8-inch oak tree in the southwest quarter of the junction, 78 feet west from the extended center line of the T-road north, 14.8 feet south from the center line of the east-west road, 1.5 feet north from a fence line, 0.6 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 68 1978."

1067.365

DNR BM STE 35 1977 Walters Lake

In Steuben County, in the \underline{E} ½ Sec. 18, T. 38 N., R. 14 E., 2^{nd} PM, about 1.9 miles northwest of Fremont; 1.4 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road north (200 East Road, Walters Road), thence 1.54 miles north to a T-road west; set in the top of a concrete post in the southwest quarter of the junction, 22.5 feet south from the center line of the T-road west, 21.0 feet west from the center line of the road, 10.8 feet southeast from a wooden fence corner post, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 35 1977."

DNR TBM SLK 77 1978 Walters Lake

In Steuben County, in the E½ Sec. 18, T. 38 N., R. 14 E., 2nd PM, about 1.9 miles northwest of Fremont; 1.4 miles west along State Road 120 from its intersection with State Road 827 in Fremont to a T-road north (200 East Road, Walters Road), thence 1.54 miles south to a T-road west, set in the east side of the south trunk of a triple-trunk wild cherry tree in the northwest quarter of the junction, 62 feet west from the center line of the road, 15.8 feet north from the center line of the T-road, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 77 1978."

1039.802

Camden Quadrangle

DNR TBM SLK 71 1978 Cedar Lake

In Steuben County, in the <u>NW ¼ Sec. 13, T. 38 N., R. 14 E., 2nd PM</u>, about 0.45 mile south of <u>Ray</u>; 0.46 mile south along Del Mar Road from its intersection with State Line Road at Ray to an east-west crossroad (Ray Clear Lake Road); set in the south side of a power pole in the northeast quarter of the junction, 69 feet north from the center line of the east-west road, 15.3 feet east from the center line of the T-road north, 0.8 foot above the ground; a railroad spike.

USGS RM No. 3 Gaging Station Mud Lake

In Steuben County, in the <u>SW ¼ Sec. 17, T. 38 N., R. 15 E., 2nd PM</u>, about 1.78 miles east-southeast of <u>Ray;</u> 0.45 mile south along Del Mar Road from its intersection with State Line Road at Ray to an east-west crossroad (Ray Clear Lake Road), thence 1.7 miles generally east to an 18-foot bridge over the channel between Mud and Clear Lakes; set in the top of a concrete lake level monument on the southeast concrete wingwall of the bridge, 17.0 feet south from the center line of the road, 7.3 feet north from the south end of the wingwall, 0.7 foot above the wingwall; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 73 1978 Mud Lake

In Steuben County, in the NE ¼ Sec. 18, T. 38 N., R. 15 E., 2nd PM, about 1.25 miles east-southeast of Ray; 0.45 mile south along Del Mar Road from its intersection with State Line Road at Ray to an east-west crossroad (Ray Clear Lake Road), thence 1.17 miles east to a fence line north; set in the south side of a power pole, 250 feet southwest from the southwest corner of a two-story, brown shingle house, 19.8 feet north from the center line of the road, 2.3 feet west from the fence line, 0.9 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 73 1978."

1101.873

DNR TBM SLK 72 1978 Round Lake Mud Lake

In Steuben County, in the NW ¼ Sec. 13, T. 38 N., R. 14 E., 2nd PM, about 0.76 mile southeast of Ray; 0.45 mile south along Del Mar Road from its intersection with State Line Road at Ray to an east-west crossroad (Ray Clear Lake Road), thence 0.61 mile east to a north-south crossroad (700 East Road); set in the south side of a 25-inch pine tree in the northwest quarter of the intersection, 89 feet west from the center line of the north-south road, 20.3 feet north from the center line of the east-west road, 0.3 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 72 1978."

USC&GS BM L 112 1934 Mud Lake

In Branch County (Michigan), in the SE 1/4 Sec. 22, T. 8 S., R. 5 W., Michigan Meridian, at Ray; at the intersection of State Line Road and the New York Central Railroad at Ray; set in the top of a concrete post in the northwest quarter of the intersection, 48.0 feet north from the center line of State Line Road, 22.0 feet east from the center line of an entrance drive, 3.0 feet southeast from a railroad right-of-way fence, 0.2 foot above the ground; a U.S. Coast and Geodetic Survey bench mark tablet, stamped "L 112 1934."

Clear Lake Quadrangle

USGS RM No. 4 Gaging Station Clear Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 18, T. 38 N., R. 15 E., 2nd PM,</u> in <u>Clear Lake</u>; at the Lake Drive 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake; set in the top at the center of the south concrete guardrail of the bridge, 19.0 feet northeast from the northeast corner of a USGS water-stage recorder shelter, 11.0 feet south from the center line of the road, 2.2 feet above the roadway; a U.S. Geological Survey gaging station tablet, not stamped.

DNR TBM SLK 74 1978 Clear Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 17, T. 38 N., R. 15 E., 2nd PM</u>, about 0.7 mile east of <u>Clear Lake</u>; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 0.67 mile generally east to a north-south crossroad (875 East Road); set in the south side of power pole #475/888 in the northeast of the intersection, 36.4 feet north from the center line of east-west road, 16.2 feet east from the center line of the north-south road, 0.9 foot above the ground; a railroad spike.

1052.549

DNR TBM SLK 300 1978 Clear Lake

In Steuben County, in the N½ Sec. 29, T. 38 N., R. 15 E., 2^{nd} PM, about 1.5 miles south-southeast of Clear Lake; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 0.67 mile generally east to a north-south crossroad (875 East Road, Outer Drive), thence 1.7 mile generally south and west to a north-south crossroad (850 East Road); set in the north side of a 42-inch oak tree in the southeast quarter of the junction, 69 feet east from the center line of the north-south road, 19.3 feet south from the center line of the east-west road, 1.4 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 300 1978."

1071.412.

DNR TBM SLK 301 1978 Clear Lake

In Steuben County, in the <u>S ½ Sec. 29</u>, <u>T. 38 N., R. 15 E., 2nd PM</u>, about 1.9 miles south-southeast of <u>Clear Lake</u>; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 0.67 mile generally east to a north-south crossroad (875 East Road, Outer Drive), thence 1.7 mile generally south and west to a north-south crossroad (850 East Road), thence 0.45 mile south to a northwest-southwest crossroad (State Road 120); set in the west side of a 20-inch oak tree in the northeast quarter of the intersection, 73 feet north from the center line of the highway, 20.1 feet east from the centerline of the road, 0.9 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 301 1978."

DNR TBM SLK 302 1978 Clear Lake

In Steuben County, in the NE ¼ Sec. 30, T. 38 N., R. 15 E., 2nd PM, about 1.52 miles south of Clear Lake; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 0.67 mile generally east to a north-south crossroad (875 East Road, Outer Drive), thence 1.7 mile generally south and west to a north-south crossroad (850 East Road), thence 0.45 mile south to a northwest-southeast crossroad (State Road 120), thence 0.85 mile northwest to a T-road north (800 East Road); set in the south side of power pole #484/769 in the northwest quarter of the junction, 48.6 feet north from the center line of the highway, 29.8 feet west from the center line of the T-road north, 0.9 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 302 1978."

DNR TBM SLK 303 1978 Clear Lake

In Steuben County, in the NW ¼ Sec. 30, T. 38 N., R. 15 E., 2nd PM, about 1.6 miles southwest of Clear Lake; 0.73 mile generally southwest along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a T-road west (675 North Road), thence 0.55 mile west to a north-south road (700 East Road), thence 0.8 mile south to a northwest-southeast crossroad (State Road 120); set in the south side of a 26-inch hickory tree in the southeast quarter of the junction, 39.6 feet east from the extended center line of the road, 33.2 feet south from the center line of the highway, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 303 1978."

DNR BM STE 32 1977 Lake Ann Clear Lake

In Steuben County, in the <u>SE ¼ Sec. 20, T. 38 N., R. 15 E., 2nd PM,</u> in <u>Clear Lake</u>; at the Clear Lake Road (Outer Drive) 30-foot bridge over the outlet channel for Clear Lake; set in the top of a concrete post, 88 feet south from the center line of the bridge, 25.8 feet east from the center line of the road, 0.8 foot north from a power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 32 1977."

DNR BM STE 33 1977 Long Lake Mirror Lake

In Steuben County, in the NE ½ Sec. 21, T.38 N., R. 15 E., 2nd PM, about 1.3 miles east-southeast of Clear Lake; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 1.25 miles generally east to north-south crossroad (925 East Road), thence 0.15 mile south to a 13-foot concrete bridge over the channel between Long and Mirror Lakes; set in the top of the north end of the east concrete guardrail base of the bridge, 18.3 feet east from the center line of the road, 2.6 feet south from the north end of the bridge, 1.9 feet below the roadway, 0.5 foot south from the north end of the guardrail; a Department of Natural Resources brass control station tablet, stamped "STE 33 1977."

USGS RM No. 2 Gaging Station Long Lake Mirror Lake

In Steuben County, in the NE ¼ Sec. 21, T. 38 N., R. 15 E., 2nd PM, about 1.3 miles east-southeast of Clear Lake; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 1.25 miles generally east to north-south crossroad (925 East Road), thence 0.15 mile south to a 13-foot concrete bridge over the channel between Long and Mirror Lakes; set in the top of the north end of the east concrete guardrail base of an abandoned bridge on the west side of the road, 33.9 feet west from the center line of the road, 9.5 feet east from the center line of the abandoned bridge, 1.6 feet above the abandoned roadway, 0.1 foot south from the north end of the guardrail base, 0.1 foot west from the east face of the guardrail base; a chiseled square.

USGS RM No. 1 Gaging Station Mirror Lake Long Lake

In Steuben County, in the NE ¼ Sec. 21, T. 38 N., R. 15 E., 2nd PM, about 1.3 miles east-southeast of Clear Lake; 0.1 mile east along Lake Drive from the 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake to a northwest-southeast crossroad (Clear Lake Road), thence 1.25 miles generally east to north-south crossroad (925 East Road), thence 0.15 mile south to a 13-foot concrete bridge over the channel between Long and Mirror Lakes, set in the top of the north end of the west concrete guardrail base of an abandoned bridge on the west side of the road, 52.9 feet west from the center line of the road, 9.5 feet west from the center line of the abandoned bridge, 1.4 feet above the roadway, 0.1 foot south from the north end of the guardrail base, 0.1 foot west from the east face of the guardrail base; a chiseled square.

1044.403

USGS RM No. 5 Gaging Station Round Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 18, T. 38 N., R. 15 E., 2nd PM, in Clear Lake</u>; at the Lake Drive 12-foot concrete bridge over the channel between Clear and Round Lakes in Clear Lake; set in the top at the center of the north concrete guardrail of the bridge, 13.5 feet north from the center line of the road, 1.2 feet above the roadway; a chiseled square.

1041.890

Hamilton Quadrangle

DNR BM STE 72 1977 Ball Lake Fish Creek

In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 14 E., 2nd PM, about 1.3 miles west of Hamilton; 1.4 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Ball Lake Road), thence 0.23 mile southwest to a northwest-southeast crossroad, thence 0.1 mile southeast to a bridge over Fish Creek; set in the top of the northeast headwall of the bridge, 17.1 feet northeast from the center line of the road, 0.8 foot northwest from the southeast end of the headwall, 0.5 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 72 1977."

USGS RM No. 3 Gaging Station Ball Lake Fish Lake
In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 14 E., 2nd PM, about 1.3 miles west
of Hamilton; 1.4 miles northwest along Bellefontaine Road from its intersection with
State Road 427 in Hamilton to a T-road southwest (Ball Lake Road), thence 0.23 mile
southwest to a northwest-southeast crossroad, thence 0.1 mile south-east to a bridge over
Fish Creek; set in the top of a concrete post, 27.0 feet south from the center line of the
road, 17.4 feet west from the center line of the bridge, 3.3 feet northwest from power pole
#429-51, 0.5 foot below the ground; a U.S. Geological Survey gaging station tablet, not
stamped.

Good Looks Stable 897.937

USGS RM No. 6 Gaging Station Ball Lake Fish Creek

In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 14 E., 2nd PM, about 1.3 miles west of Hamilton; 1.4 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Ball Lake Road), thence 0.23 mile southwest to a northwest-southeast crossroad, thence 0.1 mile southeast to a bridge over Fish Creek; set on the top of the northeast headwall of the bridge, 17.0 feet northeast from the center line of the road, 3.8 feet southwest from the northwest end of the headwall, 0.5 foot below the roadway; a chiseled square.

USGS RM No. 7 Gaging Station Ball Lake Fish Creek

In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 14 E., 2nd PM, about 1.3 miles west of Hamilton; 1.4 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Ball Lake Road), thence 0.23 mile southwest to a northwest-southeast crossroad, thence 0.1 mile southeast to a bridge over Fish Creek; set in the west side of power pole #429-35, 144 feet southeast from the center line of the bridge, 20.2 feet east from the center line of the road, 0.7 foot above the ground; the top of a nut on a threaded end of a bolt.

DNR TBM SLK 141 1977 Ball Lake Fee Lake

In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 14 E., 2nd PM, about 1.4 miles west-northwest of Hamilton; 1.4 miles north-west along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Ball Lake Road); set in the northeast side of power pole #5426-25 in the southwest quarter of the junction, 63 feet southwest from the center line of the T-road southwest, 1.4 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 141 1977".

DNR TBM HL 4 1972 Ball Lake

In Steuben County, in the N½ Sec. 31, T. 36 N., R. 14 E., 2nd PM, about 2.45 miles west-northwest of Hamilton; 2.0 miles north-west along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 0.8 mile southwest and west to a 4-foot steel pipe culvert under the road; set in the top of the south end of the culvert, 180 feet east from the center line of a T-road south (170 East Road), 25.6 feet south from the center line of the road, 3.8 feet below the roadway, 0.3 foot north from the south end of the culvert; a filed cross.

DNR TBM HL 7 1972 Fee Lake Fish Creek

In Steuben County, in the NW ¼ Sec. 33, T. 36 N., R. 14 E., 2nd PM, about 0.87 mile northwest of Hamilton; 0.87 mile northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road south (300 East Road); set in the north side of a power pole in the southwest quarter of the junction, 55 feet south from the center line of the road, 25.0 feet west from the center line of the T-road south, 0.4 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM HL 7 1972."

DNR TBM HL 5 1972 Fish Creek Ball Lake

In Steuben County, in the NE ¼ Sec. 31, T. 36 N., R. 14 E., 2nd PM, about 2.35 miles west of Hamilton; 2.0 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 0.82 mile southwest and west to a T-road south (170 East Road), thence 0.3 mile south to a 5-foot pipe culvert in Fish Creek; set in the east end of the culvert, 30 feet north from the center line of a T-road east, 18.0 feet east from the center line of the road, 0.2 foot west from the east end of the culvert; a filed cross.

DNR TBM HL 6 1972 Fish Creek Ball Lake

In Steuben County, in the NE ¼ Sec. 31, T. 36 N., R. 14 E., 2nd PM, about 2.2 miles west of Hamilton; 2.0 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 0.82 mile southwest and west to a T-road south (170 East Road), thence 0.4 mile south to a T-road east, thence 0.15 mile east to a T-road north leading to a Public Fishing Site, thence 0.05 mile north to a cul-de-sac; set in the east side of a 13-inch trunk of a twin trunk tree, 60 feet west from the west edge of Ball Lake, 60 feet north from the center of the cul-de-sac, 0.4 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM HL 6 1972."

DNR BM STE 45 1977 Gooseneck Lake Meserve Lake

In Steuben County, in the NE ¼ Sec. 23, T. 36 N., R. 13 E., 2nd PM, about 0.65 mile east-southeast of Pleasant Lake; 0.5 mile southeast along Bellefontaine Road from its intersection with U.S. Highway 27 at Pleasant Lake to a T-road east (500 South Road), thence 0.2 mile east to a field road south; set in the top of a concrete post in the southwest quarter of the junction, 300 feet east from the outlet culvert for Gooseneck Lake, 32.4 feet south from the center line of the road, 20.4 feet southwest from the west end of a steel guardrail, 20.4 feet west from the center line of the field road, 2.8 feet north from a power pole; a Department of Natural Resources brass control station tablet, stamped "STE 45 1977."

USGS RM No. 7 Gaging Station Hamilton Lake

In Steuben County, in the SE ½ Sec. 33, T. 36 N., R. 14 E., 2nd PM, in Hamilton; 0.03 mile north along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a 50-foot bridge over the outlet channel for Hamilton Lake; set in the top of an I beam, 150 feet north from the center line of an east-west road (Bellefontaine Road), 50 feet west from the center line of the highway, 15.0 feet south from the north face of the bridge, 2.5 feet west from the west face of the bridge; a filed notch.

902.913

USGS RM No. 6 Gaging Station Hamilton Lake

In Steuben County, in the \underline{W} ½ Sec.34, T. 36 N., R. 14 E., 2^{nd} PM, in Hamilton; 0.15 mile north along State Road 247 from its intersection with Bellefontaine Road in Hamilton to a T-road northwest (Circle Park Road), thence 0.05 mile northwest to the northern outlet for Hamilton Lake; set in the top of a concrete lake level monument on the west side of the road, 22.0 feet west from the center line of the road, 15.0 feet south from the center line of the outlet; a U.S. Geological gaging station tablet, not stamped.

901.327

DNR TBM HL 8 1973 Hamilton Lake

In Steuben County, in the SW ½ Sec. 27, T. 36 N., R. 14 E., 2nd PM, about 0.8 mile north of Hamilton; 0.15 mile north along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a T-road northwest (Circle Park Road), thence 0.72 mile northwest and north to a 6-inch pipe culvert under the road; set in the north side of a 48-inch twin trunk oak tree, 50 feet north from the center line of the culvert, 25.2 feet east from the center line of the road, 0.4 foot above the ground; a 60d nail.

DNR TBM HL 9 1973 Hamilton Lake

In Steuben County, in the <u>SW ½ Sec. 27, T. 36 N., R. 14 E., 2nd PM</u>, about 1.1 miles north of <u>Hamilton</u>; 0.8 mile north and northwest along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a T-road north (State Road 1), thence 0.35 mile north to a T-road west (Circle Park Road), thence 0.4 mile generally west and north to a 1-foot pipe culvert under the road; set in the southeast side of an 11-inch hickory tree, 40.0 feet northwest from the center line of the culvert, 22.6 feet southeast from the center line of a dirt road, 18.3 feet southwest from the center line of the road, 0.3 foot above the ground; a 60d nail.

DNR TBM HL 10 1973 Hamilton Lake

In Steuben County, in the <u>SW ½ Sec. 27, T. 36 N., R. 14 E., 2nd PM</u>, about 1.1 miles north of <u>Hamilton</u>; 0.8 mile north and northwest along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a T-road north (State Road 1), thence 0.35 mile north to a T-road west (Circle Park Road), thence 0.4 mile generally west and north to a 1-foot pipe culvert under the road; set in the south side of a 19-inch willow tree, 100 feet southeast from the center line of the culvert, 21.5 feet southwest from the center line of the road, 0.7 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM HL 10 1973."

DNR RP 2 1973 Hamilton Lake

In Steuben County, in the SW ¼ Sec. 27, T. 36 N., R. 14 E., 2nd PM, about 1.1 miles north of Hamilton; 0.8 mile north and northwest along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a T-road north (State Road 1), thence 0.35 mile north to a T-road west (Circle Park Road), thence 0.4 mile generally west and north to a 1-foot pipe culvert under the road; set in the streamward face of a wooden sea wall on the east side of the road, 15.0 feet north from the center line of the culvert; a 30d nail.

DNR RP 3 1973 Hamilton Lake

In Steuben County, in the <u>SW ½ Sec. 27, T. 36 N., R. 14 E., 2nd PM</u>, about 1.1 miles north of <u>Hamilton</u>; 0.8 mile north and northwest along State Road 427 from its intersection with Bellefontaine Road in Hamilton to a T-road north (State Road 1), thence 0.35 mile north to a T-road west (Circle Park Road), thence 0.4 mile generally west and north to a 1-foot pipe culvert under the road; set in the top of the west end of the culvert; a filed notch.

DNR BM STE 46 1977 Jackson Lake Ball Lake

In Steuben County, in the <u>SW ¼ Sec. 29, T. 36 N., R. 14 E., 2nd PM</u>, about 2.0 miles west-northwest of <u>Hamilton</u>; 2.0 miles north-west along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 0.17 mile southwest to a 2-foot steel pipe culvert under the road; set in the top of a concrete post, 21.5 feet northeast from the center line of the culvert, 14.5 feet southeast from the center line of the road, 1.0 foot north from a power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 46 1977."

DNR TBM SLK 142 1977 Jackson Lake Ball Lake

In Steuben County, in the <u>SW ¼ Sec. 29, T. 36 N., R. 14 E., 2nd PM,</u> about 2.0 miles west-northwest of <u>Hamilton</u>; 2.0 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 0.17 mile southwest to a 2-foot steel pipe culvert under the road; set in the top of the southeast end of the culvert, 23.0 feet southeast from the center line of the road, 7.0 feet below the roadway; the center of two filed notches.

DNR TBM SLK 42 1977 Johnson Ditch Johnson Ditch

In Steuben County, in the NW ¼ Sec. 17, T. 36 N., R. 14 E., 2nd PM, about 3.0 miles east of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 2.0 miles east to a turn south (100 East Road), thence 0.2 mile south to a T-road east (Johnson Lake Road), thence 0.9 mile east to a T-road south (200 East Road); set in the west side of a 30-inch hickory tree in the southeast quarter of the junction, 109 feet east of the center line of the T-road south, 22.5 feet south from the center line of the east-west road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 42 1977."

DNR TBM SLK 45 1977 Johnson Ditch

In Steuben County, in the NE ¼ Sec. 17, T. 36 N., R. 14 E., 2nd PM, about 3.5 miles south-southwest of Ellis; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 3.1 miles south to a 3-foot steel pipe culvert in Johnson Ditch; set in the top of the east end of the culvert, 53 feet southeast from telephone pole #23, 15.6 feet east from the center line of the road, 2.5 feet below the road; the center of two filed notches.

DNR BM STE 34 1977 Johnson Lake

In Steuben County, in the NE ¼ Sec. 17, T. 36 N., R. 14 E., 2nd PM, about 3.5 miles south-southwest of Ellis; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 3.1 miles south to a 3-foot steel pipe culvert in Johnson Ditch; set in the top of a concrete post on the west side of the road, 317 feet south from the center line of the culvert, 19.3 feet west from the center line of the road, 1.0 foot south from a telephone pole, 0.5 foot below the roadway, flush with the ground; a Department of Natural Resources brass station tablet, stamped "STE 34 1977."

DNR TBM SLK 43 1977

In Steuben County, in the NW ¼ Sec. 17, T. 36 N., R. 14 E., 2nd PM, about 3.7 miles east of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 2.0 miles east to a turn south (100 East Road), thence 0.2 mile south to a T-road east (Johnson Lake Road), thence 1.7 miles generally east to a north-south crossroad (275 East Road); set in the south side of a 42-inch wild cherry tree in the northeast quarter of the intersection, 57 feet east from the center line of the north-south road, 20 feet north from the center line of the east-west road, 0.3 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 43 1977."

989.802

DNR TBM SLK 39 1977 Mud Creek Mud Lake

In Steuben County, in the S½ Sec. 1, T. 36 N., R. 13 E., 2nd PM, about 2.6 miles northeast of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west road (400 South Road), thence 1.0 mile east to a T-road north (Meridian Road), thence 1.2 miles north to a T-road east (275 South Road), thence 0.55 mile east to a steel pipe culvert under the road in Mud Creek; set in the top of the north end of the culvert, 19.0 feet north from the center line of the road, 1.8 feet below the roadway; the center of two filed notches.

DNR TBM SLK 38 1977 Mud Creek Mud Lake

In Steuben County, in the SW ¼ Sec. 1, T. 36 N., R. 13 E., 2nd PM, about 2.5 miles northeast of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from the intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 1.0 mile east to a T-road north (Meridian Road), thence 1.2 miles north to a T-road east (275 South Road); set in the top of a concrete headwall in the southeast quarter of the intersection, 260 feet south from the center line of the T-road east, 14.0 feet east from the center line of the north-south road, 1.5 feet south from the north end of the concrete, level with the roadway; a painted chiseled triangle.

DNR TBM HL 3 1972 Perfect Lake

In Steuben County, in the <u>NW ¼ Sec. 31, T. 36 N., R. 14 E., 2nd PM</u>, about 2.85 miles west-northwest of <u>Hamilton</u>; 2.0 miles northwest along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 1.2 miles southwest and west to a 3-foot steel pipe culvert under the road; set in the top of the south end of the culvert, 225 feet east from the center line of a north-south crossroad (100 East Road), 22.4 feet south from the center line of the road, 1.6 feet below the roadway, 0.3 foot north from the south end of the culvert; a filed cross.

919.671

DNR BM STE 47 1977 Perfect Lake Fish Creek

In Steuben County, in the NE ¼ Sec. 36 T. 36 N., R. 13 E., 2nd PM, about 2.95 miles west-northwest of Hamilton; 2.0 miles north-west along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 1.3 miles southwest and west to a north-south crossroad (100 East Road); set in the top of a concrete post in the southwest quarter of the intersection, 41.0 feet south from the center line of the east-west road, 39.0 feet west from the center line of the north-south road, 1.5 feet north from a guy-wire power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 47 1977."

928.767

DNR TBM HL 2 1972 Perfect Lake

In Steuben County, in the NE ¼ Sec. 36, N., R. 13 E., 2nd PM, about 3.9 miles west-northwest of Hamilton; 2.0 miles north-west along Bellefontaine Road from its intersection with State Road 427 in Hamilton to a T-road southwest (Lemon Road), thence 2.3 miles southwest and west to a T-road north (Meridian Road); set in the top of the south end of a 3-foot pipe culvert under the road in the southwest quarter of the junction, 125 feet west from the center line of the T-road north, 20 feet south from the center line of the road, 6.0 feet below the roadway, 0.2 foot north from the south end of the culvert; a filed cross.

DNR BM STE 50 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 11, T. 36 N., R. 13 E., 2nd PM, about 0.9 mile northeast of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 0.6 mile east to a 40-foot concrete bridge over Pigeon Creek; set in the top of the north end of the west bridge abutment, 16.9 feet north from the center line of the road, 0.8 foot northeast from the northwest corner of the north guardrail, 0.7 foot below the roadway, 0.5 foot west from the east face of the abutment; a Department of Natural Resources brass control station tablet, stamped "STE 50 1977."

DNR TBM SLK 36 1977 Pigeon Creek

In Steuben County, In the SE ¼ Sec. 11, T. 36 N., R. 13 E., 2nd PM, about 3.0 miles south of Angola; 3.5 miles south along U.S. Highway 27 from its intersection with U.S. Highway 20 in Angola to an east-west crossroad (400 South Road), thence 1.0 mile east to a T-road north (Meridian Road); set in the north side of a 24-inch hickory tree, 400 feet north from the center line of the east-west road, 25.5 feet west from the center line of the T-road north, 0.2 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 36 1977."

DNR BM STE 51 1977 Pigeon Creek

In Steuben County, in the NE ¼ Sec. 11, T. 36 N., R. 13 E., 2nd PM, about 1.75 miles northeast of Pleasant Lake, 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 1.0 mile east to a T-road north (Meridian Road), thence 1.0 mile east to a T-road north (Meridian Road), thence 0.7 mile north to a 60-foot concrete bridge of Pigeon Creek; set in the top of the southwest wingwall of the bridge, 14.6 feet west from the center line of the road, 4.1 feet north from the south end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 51 1977."

DNR TBM SLK 37 1977 Pigeon Creek

In Steuben County, in the NE ½ Sec. 11, T. 36 N., R. 13 E., 2nd PM, about 1.75 miles northeast of Pleasant Lake, 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 1.0 mile east to a T-road north (Meridian Road), thence 0.7 mile north to a 60-foot concrete bridge of Pigeon Creek; set in the top of the northeast wingwall of the bridge, 13.6 feet east from the center line of the road, 1.5 feet south from the north end of the concrete wingwall, level with the roadway; a painted chiseled triangle.

979.048

DNR TBM SLK 41 1977 Pigeon Creek

In Steuben County, in the NW ¼ Sec. 18, T. 36 N., R. 14 E., 2nd PM, about 2.2 miles east of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 2.0 miles east to a turn south (100 East Road), thence 0.2 mile south to a T-road east (Johnson Lake Road); set in the north side of guy wire pole #29X, 45.8 feet east from the center line of the north-south road, 2.0 feet below the roadway; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 41 1977." 981.325

DNR TBM SLK 40 1977 Pigeon Creek

In Steuben County, in the NE ½ Sec. 13, T. 36 N., R. 13 E., 2nd PM, about 2.4 miles northeast of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), thence 1.7 miles east to a T-road north (Bill Deller Road); set in the top of the south end of a 16-inch steel pipe culvert under the road, 275 feet east from the center line of the T-road north, 14.5 feet south from the center line of the east-west road, 0.5 foot below the roadway; the center of two filed notches.

DNR BM STE 52 1977 Pigeon Creek Mud Lake

In Steuben County, in the NE ¼ Sec. 12, T. 36 N., R. 13 E., 2nd PM, about 2.3 miles northeast of Pleasant Lake; 0.9 mile north along U.S. Highway 27 from its intersection with Bellefontaine Road at Pleasant Lake to an east-west crossroad (400 South Road), 1.8 miles east to a T-road north (Bill Deller Road), thence 0.8 mile north to a 60-foot concrete bridge over Pigeon Creek; set in the top of the northeast bridge wingwall, 13.7 feet east from the center line of the road, 1.9 feet south from the north end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 52 1977."

DNR BM STE 55 1977 Pigeon Creek

In Steuben County, in the <u>SE ¹/₄ Sec. 5, T. 36 N., R. 14 E., 2nd PM,</u> about 2.4 miles south-southwest of <u>Ellis</u>; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 2.1 miles south to a T-road northwest (Hanselman Road), thence 0.25 mile northwest to a 60-foot concrete bridge over <u>Pigeon Creek</u>; set in the top of the southeast corner of the bridge floor, 12.7 feet southwest from the center line of the road, 1.1 feet northeast from the southwest face of the bridge, 0.7 foot northwest from the northeast end of the bridge; a Department of Natural Resources brass control station tablet, stamped "STE 55 1977."

990.046

DNR BM STE 56 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 5, T. 36 N., R. 14 E., 2nd PM, about 2.15 miles south-southwest of Ellis; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 1.8 miles south to a 50-foot concrete bridge over Pigeon Creek; set in the top of the southeast bridge wingwall, 13.5 feet east from the center line of the road, 4.5 feet north from the south end of the wingwall, level with the road; a Department of Natural Resources brass control station tablet, stamped "STE 56 1977."

DNR TBM SLK 47 1977 Pigeon Creek

In Steuben County, in the NE ¼ Sec. 5, T. 37 N., R. 14 E., 2nd PM, about 1.7 miles southwest of Ellis; 1.25 miles west along U.S. Highway 20 from its intersection with State Road at Ellis to a T-road south (275 South Road), thence 1.3 miles south to a jog in the road and a field lane west; set in the south side of an 18-inch walnut tree in the southwest quarter of the junction, 29.0 feet west from the center line of the road, 20.0 feet south from the center line of the field lane west, 0.3 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 47 1977."

1001.052

DNR TBM SLK 48 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 32, T. 37 N., R. 14 E., 2nd PM, about 1.5 miles south-southwest of Ellis; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 0.8 mile south to a base of a hill; set in the west side of a 10-inch ash tree on the east side of the road, 250 feet north from the base of the hill, 21.4 feet south from an underground cable sign, 17.5 feet east from the center line of the road, 2.5 feet above the road, 0.1 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 48 1977."

DNR TBM SLK 49 1977 Pigeon Creek

In Steuben County, in the <u>SW ½ Sec. 33, T. 37 N., R. 14 E., 2nd PM</u>, about 1.1 miles southwest of <u>Ellis</u>; 1.05 mile south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to an east-west crossroad (Metz Road), thence 0.8 mile generally northwest to a twin 18-foot steel pipe culvert in <u>Pigeon Creek</u>; set in the top of the threaded end of a bolt on the northeast end of the west steel pipe culvert, 24.9 feet northeast from the center line of the road, 6.3 feet southeast from the northwest end of the culvert, 4.5 feet below the roadway, 1.0 foot northeast from a concrete retaining wall; a filed cross.

DNR TBM SLK 50 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 33, T. 37 N., R. 14 E., 2nd PM, about 1.05 miles south of Ellis; 1.05 miles south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to an east-west crossroad (Metz Road); set in the north side of REA Co-op pole #33 in the southwest quarter of the intersection, 40.0 feet west from the center line of the highway, 26.8 feet south from the road, 0.6 foot above the ground; a railroad spike.

DNR BM STE 41 1977 Round Lake Johnon Lake

In Steuben County, in the N½ Sec. 16, T. 36 N., R. 14 E., 2nd PM, about 3.2 miles south-southwest of Ellis; 3.1 miles south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to a turn east and a T-road southwest (Johnson Lake Road), thence 0.6 mile generally southwest to a 3-inch telephone pole on the south side of the road; set in the top of a concrete post, 414 feet northeast from the center line of Thomas R. Cool's driveway, 18.0 feet south from the center line of the road, 2.4 feet north from a fence, 2.2 feet northeast from the telephone pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 41 1977."

1028.348

DNR TBM SLK 44 1977 Round Lake

In Steuben County, in the NW ¼ Sec. 16, T. 38 N., R. 14 E., 2nd PM, about 3.2 miles southwest of Ellis; 3.1 miles south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to a northeast-southwest crossroad (Johnson Lake Road), thence 0.75 mile southwest to a T-fence corner northwest by a large red barn; set in the west side of an 11-inch walnut tree on the north side of the road, 57 feet west from a T-fence corner, 40.0 feet east from a 24-inch walnut tree, 20.0 feet north from the road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 44 1977."

DNR BM STE 57 1977 unnamed lake Pigeon Creek

In Steuben County, in the NW ¼ Sec. 33, T. 37 N., 14 E., 2nd PM, about 1.05 miles southwest of Ellis; 1.05 mile south along State Road 1 from its intersection with U.S. Highway 20 at Ellis to an east-west crossroad (Mentz Road), thence 0.7 mile generally northwest to a private entrance road south; set in the top of a concrete post in the southeast quarter of the junction, 43.6 feet east from the center line of the entrance road south, 20.9 feet south from the center line of the road, 1.5 feet east from telephone pole #11, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 57 1977."

DNR TBM SLK 46 1977 unnamed lake Pigeon Creek

In Steuben County, in the <u>SE ¹/₄ Sec. 5, T. 36 N., R. 14 E., 2nd PM,</u> about 2.4 miles south-southwest of <u>Ellis</u>; 1.25 miles west along U.S. Highway 20 from its intersection with State Road 1 at Ellis to a T-road south (275 South Road), thence 2.1 miles south to a T-road northwest (Hanselman Road); set in the west side of a 22-inch ash tree in the northwest quarter of the junction, 22.0 feet north from the extended center line of the T-road, 19.5 feet east from the center line of the north-south road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 46 1977."

Kinderhook Quadrangle

DNR BM STE 71 1977 Lake Pleasant

In Steuben County, in the <u>SW ½ Sec. 13, T. 38 N., R. 12 E., 2nd PM</u>, about 3.95 miles northeast of <u>Orland</u>: 3.15 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road north (650 West Road), thence 0.8 mile north to a T-road east (760 North Road), thence 0.75 mile east to a T-road north; set in the top of the west end of the north headwall of a 5-foot concrete pipe culvert under the east-west road, 64 feet east from the center line of the T-road north, 22.6 feet north from the center line of the road, 0.7 foot east from the west end of the headwall; a Department of Natural Resources brass control station tablet, stamped "STE 71 1977."

Recovered RST 5-24-88 980.169

USGS RM No. 9 Gaging Station Lake Pleasant

In Steuben County, in the NW ¼ Sec. 13, T. 38 N., R. 12 E., 2nd PM, about 3.9 miles northeast of Orland; 3.15 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road north (650 North Road), thence 0.8 mile north to a T-road east (760 North Road), thence 0.75 mile east to a T-road north, thence 0.2 mile north to a turn west, thence 0.1 mile west to a turn north, thence 0.1 mile north to a T-road west, thence 0.05 mile west to a bridge over a boat channel; set in the top of the northeast wingwall of the bridge, 8.8 feet north from the center line of the road, 1.5 feet southwest from the northeast end of the wingwall, 0.6 foot below the roadway; a chiseled square.

USGS RM No. 4 Gaging Station Lake Pleasant

In Steuben County, in the NW ¼ Sec. 13, T. 38 N., R. 12 E., 2nd PM, about 3.9 miles northeast of Orland; 3.15 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road north (650 West Road), thence 0.8 mile north to a T-road east (760 North Road), thence 0.75 mile east to a T-road north, thence 0.2 mile north to a turn west, thence 0.05 mile west to a boat ramp on the north side of the road; set in the top of a concrete lake level monument, 51 feet north from the center line of the road, 38.0 feet east from the center line of the boat ramp, 13.4 feet northeast from a gasoline pump, 2.5 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

Destroyed New Monument Set in its place DST 5-24-88 964.649

DNR TBM SLK 214 1977 Lake Pleasant

In Steuben County, in the NW ¼ Sec. 14, T. 38 N., R. 12 E., 2nd PM, about 3.35 miles northeast of Orland: 3.15 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a T-road north (650 West Road), thence 0.7 mile north to a drive west leading to a toll road station; set in the west side of a 27-inch maple tree in the northwest quarter of the junction, 104 feet north from the center line of the drive, 24.0 feet west from the center line of the road, 5.0 feet east from a fence line, 0.6 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 214 1977."

Destroyed RST 5-24-88 DNR TBM**

SLK-214 RESET 1987 Recovered. It is a R.R. spike there Al. Tag in E. side of a tree on W. side of 650 W. Road and across from 760 N. Road intersection 985.439

DNR BM LAG 98 1975 Beaverdam Lake

In Lagrange County, in the NE ¼ Sec. 1, T. 37 N., R. 11 E., 2nd PM, about 2.7 miles southwest of Orland (Steuben County); 1.55 miles generally west along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (1200 East Road), thence 2.1 miles generally south to an east-west crossroad (400 North Road), thence 0.2 mile east to a turn south and a road east leading to a public fishing site at Beaverdam Lake; set in top of a concrete post in the southeast quarter of the junction, 240 feet east from the center line of the turn south, 105 feet west from the west edge of the lake, 26.3 feet south from the center line of the public fishing site road, 2.1 feet northwest from a wooden fence corner post, 0.2 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "LAG 98 1975."

DNR TBM LLK 86 1976 Beaverdam Lake

In Steuben County, in the NE ¼ Sec. 6, T. 37 N., R. 12 E., 2nd PM, 2.65 miles southwest of Orland; 2.7 miles south along State Road 327 from its intersection with State Road 120 in Orland to a T-road west (350 North Road), thence 0.75 mile west to a T-road south (1025 West Road); set in the southwest side of a 52-inch elm tree in the northeast quarter of the junction, 139 feet east from the extended center line of the T-road south, 16.0 feet north from the center line of the east-west road, 0.7 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM LLK 86 1976."

976.081

DNR TBM LLK 87 1976 Beaverdam Lake

In Steuben County, in the NE ¼ Sec. 6, T. 37 N., R. 12 E., 2nd PM, about 2.85 miles southwest of Orland; 2.7 miles south along State Road 327 from its intersection with Sat Road 120 in State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (350 North Road), thence 1.25 miles west to a 4-foot steel pipe culvert under the road; set in the top of the north end of the culvert, about 528 feet east from a T-road south, 16.3 feet north from the center line of the road, 0.3 foot below the roadway; the center of two filed notches.

ISHC BM F 28 Crooked Creek

In Steuben County, in the <u>SW ½ Sec .21, T. 38 N., R. 12 E., 2nd PM</u> about 0.92 mile east of Orland; 0.92 mile east along State Road 120 from its intersection with State Road 327 in Orland to a concrete bridge over <u>Crooked Creek</u>; set in the top of the northwest wingwall of the bridge, 23.4 feet north from the center line of the highway, 3.1 feet west from the east face of the northwest wingwall, 0.5 foot below the highway; an Indiana State Highway Commission bench mark tablet, stamped "F 28." 954.213

DNR TBM SLK 105 1978 Crooked Creek

In Steuben County, in the <u>SW ¼ Sec. 21, T. 38 N., R. 12 E., 2nd PM</u>, about 0.92 mile east of <u>Orland</u>; 0.92 mile east along State Road 120 from its intersection with State Road 327 in Orland to a concrete bridge over <u>Crooked Creek</u>; set in top of the northeast concrete wingwall of the bridge, 23.7 feet north from the center line of the highway, 3.6 feet west from the east face of the wingwall, 1.0 foot below the highway; a chiseled triangle.

954.212

DNR BM STE 67 1977

In Steuben County, in the <u>SW ¼ Sec. 22, T. 38 N., R. 12 E., 2nd PM,</u> about 1.55 miles east of <u>Orland</u>: 1.65 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a north-south crossroad (800 West Road), thence 0.35 mile south to a concrete bridge over <u>Crooked Creek</u>; set in the top of the northeast wingwall of the bridge, 15.8 feet east from the center line of the road, 0.5 foot north from the south face of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 67 1977."

DNR TBM SLK 106 1978 Crooked Creek

In Steuben County, in the SE ¼ Sec. 22, T. 38 N., R. 12 E., 2nd PM, about 1.55 miles east of Orland; 1.65 miles east along State Road 120 from its intersection with State Road 327 in Orland to a north-south crossroad (800 West Road), thence 0.3 mile south to a dim Troad east; set in the west side of a 24-inch oak tree, 43.4 feet east and across the road from power pole #481/619, 29.0 feet east from the center line of the road, 6.0 feet south from the T-road; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 106 1978."

DNR BM STE 12 1975 Deep Lake Shallow Lake

In Steuben County, in the NW ¼ Sec. 7, T. 37 N., R. 12 E., 2nd PM, about 3.3 miles southwest of Orland; 3.2 miles south along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (300 North Road), thence 1.2 miles west to a 16-inch steel pipe culvert at the outlet channel at Deep Lake; set in the top of a concrete post about 528 feet east from a north-south crossroad, 480 feet west from the center of the culvert, 22.5 feet south from the center line of the road, 1.5 feet north from a T-fence corner post, 0.3 foot above the ground, a Department of Natural Resources brass control station tablet, stamped "STE 12 1975."

USGS BM W 47 1937 Deep Lake

In Steuben County, in the SE ½ Sec. 6, T. 37 N., R. 12 E., 2nd PM, about 3.3 miles southwest of Orland; 3.2 miles south along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (300 North Road), thence 0.75 mile west to a T-road north (1025 West Road); set in the top of a concrete post in the northwest quarter of the junction, 31.1 feet north from the center line of the east-west road, 15.9 feet west from the center line of the T-road north, 2.4 feet east from a fence line, 0.3 foot above the ground; a U.S. Geological Survey bench mark tablet, stamped "W 27 985 1937."

DNR BM STE 68 1977 Fawn River

In Steuben County, in the NE ¼ Sec. 20, 39 N., R. 12 E., 2nd PM, about 0.75 mile north of Orland; 0.75 mile north along State Road 327 from its intersection with State Road 120 in Orland to a concrete bridge over Fawn River; set in the top of the north end of the east concrete bridge curb, 18.6 feet east from the center line of the road, 2.2 feet south from the north end of the curb, 0.8 foot above the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 68 1977." 954.803

DNR BM STE 70 1977 Fawn River

In Steuben County, in the SE ¼ Sec. 20, T. 38 N., R. 12 E., 2nd PM, about 0.3 mile east of Orland; 0.3 mile east along State road 120 from its intersection with State Road 327 in Orland to a concrete pipe culvert under the road; set in the top of the west end of the culvert, 24.0 feet north from the center line of the highway, 10.3 feet northeast from an Orland City Limits sign, 2.0 feet below the roadway, 0.8 foot east from the west end of the headwall; a Department of Natural Resources brass control station tablet, stamped "STE 70 1977."

DNR BM STE 14 1975 Green Lake

In Steuben County, in the <u>SW ¼ Sec. 29, T. 37 N., R. 12 E., 2nd PM</u>, about 2.8 miles east of <u>Brushy Prairie</u> (Lagrange County); 2.8 miles east along U.S. Highway 20 from its junction with 925 East Road at Brushy Prairie to a T-road north (Green Lake Road); set in the top of a concrete post in the northeast quarter of the junction, 47.2 feet north from the center line of the highway, 43.0 feet east from the center line of the road, 6.5 feet southeast from a wooden fence corner post, 0.2 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 14 1975." 959.837

959.851 **RWW 11-27-00**

DNR BM STE 69 177 Lime Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 18, T. 38 N., R. 12 E., 2nd PM,</u> about 1.35 miles north-northwest of <u>Orland</u>; 0.95 mile north along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (700 North Road), thence 0.8 channel for Lime Lake; set in the top of a concrete gate post, 175 feet northwest from the center line of the culvert, 42.5 feet northeast from the center of the road, 7.0 feet southeast from the center line of a private drive northeast, 3.7 feet above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 69 1977."

944.638

DNR TBM SLK 98 1977 Lime Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 18, T. 38 N., R. 12 E., 2nd PM</u>, about 1.35 miles north-northwest of <u>Orland</u>; 0.95 mile north along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (700 North Road), thence 0.8 mile generally east to a 2-foot steel pipe culvert in the outlet channel for Lime Lake; set in the top of the northeast end of the culvert, 42.5 feet north and across the roadway from power pole #484/294, 18.0 feet northeast from the center line of the road, 3.5 feet below the roadway; the center of two filed notches.

DNR BM STE 9 1975 Mud Lake

In Steuben County, in the NW ¼ Sec. 19, T. 38 N., R. 12 E., 2nd PM, about 1.3 miles northwest of Orland; 0.4 mile north along State Road 327 from its intersection with State Road 120 in Orland to a T-road west (650 North Road), thence 1.1 miles west to a north-south crossroad (1200 East Road), thence 0.2 mile north to a turn west, thence 0.15 mile west to the outlet dam of Mud Lake; set in the top of the west concrete wingwall of the dam, 47.7 feet south from the center line of the road, 20.6 feet east from the southeast corner of a parking lot, 0.8 foot west from the east face of the west wingwall of the dam, a Department of Natural Resources brass control station tablet, stamped "STE 9 1975."

942.289

USGS RM No. 5 Gaging Station Mud Lake Wall Lake

In Steuben County, in the NW ¼ Sec. 19, T. 38 N., R. 12 E., 2nd PM, about 1.3 miles northwest of Orland; 0.4 mile north along State road 327 from its intersection with State Road 120 in Orland to a T-road west (650 North Road), thence 1.1 miles west to a north-south crossroad (1200 East Road), thence 0.2 mile north to a turn west, thence 0.15 mile west to the outlet dam of Mud Lake; set in the top of a concrete lake level monument, 47.7 feet south from the center line of the road, 4.0 feet east from the east end of the east wingwall of an outlet dam, 1.7 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

USGS BM W 43 1937 Mud Lake

In Steuben County, in the S½ Sec. 27, T. 37 N., R. 12 E., 2nd PM, about 7.2 miles southwest of Angola; 7.0 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a north-south crossroad (750 West Road), thence 0.5 mile south to a T-road east; set in the top of a concrete post in the northwest quarter of the junction, 33.0 feet north from the center line of the T-road east, 23.9 feet west from the center line of the T-road east, 23.9 feet west from the center line of the north-south road, 3.6 feet southeast from a 36-inch hickory tree, 2.0 feet above the roadway, 0.4 foot above the ground; a U.S. Geological Survey bench mark tablet, stamped "W 43 1937."

1016.744

USC&GS Triangulation Station FLINT 1946 Mud Lake Otter Lake In Steuben County, in the NE ¼ Sec. 27, T. 37 N., R. 12 E., 2nd PM, about 6.75 miles west of Angola; 6.75 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a parking area on the north side of the road; set in the top of a concrete post, 89 feet north from the center line of the highway, 63 feet northwest from power pole #469/619, 0.2 foot above the ground; a U.S. Coast and Geodetic Survey triangulation station tablet, stamped "FLINT 1946."

USC&GS RM FLINT No. 1 1946 Mud Lake Otter Lake

In Steuben County, in the NE ¼ Sec. 27, T. 37 N., R. 12 E., 2nd PM, about 6.75 miles west of Angola; 6.75 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a parking area on the north side of the highway; set in the top of a concrete post, 51 feet north from the center line of the highway, 41.3 feet east from power pole #469/619, 0.3 foot above the ground; a U.S. Coast and Geodetic Survey reference mark tablet, stamped "FLINT No. 1 1946."

US&GS RM FLINT No. 2 1946 Mud Lake Otter Lake

In Steuben County, in the NE ¼ Sec. 27, T. 37 N., R. 12 E., 2nd PM, about 6.75 miles west of Angola; 6.75 miles west along U.S. Highway 20 from its intersection with U.S. Highway 27 in Angola to a parking area on the north side of the road; set in the top of a concrete post, 86 feet west from power pole #469/619, 51 feet north from the center line of the highway, 0.5 foot above the ground; a U.S. Coast and Geodetic Survey reference mark tablet, stamped "FLINT No. 2 1946."

USGS RM No. 6 Gaging Station Otter Lake *Destroyed RST 5-24-88* In Steuben County, in the S½ Sec. 20, T. 37 N., 12 E., 2nd PM, about 6.0 miles south of Orland; 6.0 miles south along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (U.S. Highway 20), thence 0.3 mile east to an entrance road south to Otter Lake Public Fishing Site; set in the top of a concrete post, 470 feet south from the center line of the highway, 58 feet east from the center line of the entrance road south, 2.0 feet above the ground; a U.S. Geological Survey gaging station tablet, not stamped.

DNR BM STE 21 1977 Otter Lake Pigeon Creek *Recovered RST 1/98* In Steuben County, in the SE ½ Sec. 20, T. 27 N., R. 12 E., 2nd PM, 2.1 miles west-southwest of Flint; 1.0 mile south along Flint Road (750 West Road) from its junction with 50 North Road at Flint to an east-west crossroad (U.S Highway 20), thence 2.23 miles generally west to a 5-foot concrete box culvert in the inlet channel for Otter Lake; set in the west end of the south headwall of the culvert, 19.0 feet south from the center line of the highway, 1.5 feet below the highway, 0.9 foot east from the west end of the headwall; a Department of Natural Resources brass control station tablet, stamped "STE 21 1977."

DNR TBM SLK 25 1977 Otter Lake

In Steuben County, in the SE ¼ Sec. 19, T. 37 N., R. 12 E., 2nd PM, about 6.0 miles south of Orland: 6.0 miles south along State Road 327 from its intersection with State Road 120 in Orland to an east-west crossroad (U.S. Highway 20), thence 0.25 mile west to an east-west crossroad (U.S. Highway 20), thence 0.25 mile west to a T-road south (1000 West Road); set in the north side of a 20-inch oak tree in the northeast quarter of the junction, 24.0 feet north from the center line of the highway, 11.0 feet east from the extended center line of the highway, 11.0 feet east from the extended center line of the T-road south, 0.7 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM SLK 25 1977."

USGS RM No. 1 Gaging Station Otter Lake

In Steuben County, in the NW ¼ Sec. 29, T. 37 N., R. 12 E., 2nd PM, about 6.5 miles south of Orland; 6.5 miles south along State Road 327 from its intersection with State Road 120 in Orland to a T-road east, thence 0.2 mile east to Otter Lake; set in the southeast side of a 24-inch oak tree, 80 feet south from the center line of the road, 70 feet west from the west edge of the lake, 0.3 foot above the ground; an iron telephone pole step.

USGS BM W 42 1937 Otter Lake Green Lake

In Steuben County, in the NW ¼ Sec. 31, T. 37 N., R. 12 E., 2nd PM, about 3.2 miles east-southeast of Brushy Prairie; 1.0 mile south along 925 East Road from its junction with U.S. Highway 20 at Brushy Prairie to an east-west crossroad (100 South Road), thence 3.05 miles west to a T-road south (1050 West Road); set in the top of a concrete post in the southeast quarter of the junction, 26.3 feet south from the center line of the east-west road, 19.2 feet east from the center line of the T-road south, 1.7 feet west from a north-south fence line, 0.5 foot above the ground; a U.S. Geological Survey bench mark tablet, stamped "W 42 1937 1004."

DNR TBM SLK 7 1975 Otter Lake

In Steuben County, in the <u>SW ¼ Sec. 29, T. 37 N., R. 12 E., 2nd PM</u>, about 4.0 miles east-southeast of <u>Brushy Prairie</u>; 1.0 mile south along 925 East Road from its junction with U.S. Highway 20 at Brushy Prairie to an east-west crossroad (100 South Road), thence 4.0 miles east to a north-south crossroad (State Road 327); set in the southwest side of power pole #REA Co-op 31 in the northwest quarter of the intersection, 93 feet west from the center line of the highway, 22.0 feet north from the center line of the road, 2.0 feet above the roadway, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 7 1975." *Destroyed RST 5-24-88* 1004.173

USGS UE 1003 Otter Lake

In Steuben County, in the S½ Sec. 29, T. 37 N., R. 12 E., 2nd PM, about 4.1 miles east-southeast of Brushy Prairie (Lagrange County); 1.0 mile south along 925 East Road from its junction with U.S. Highway 20 at Brushy Prairie to an east-west crossroad (100 South Road), thence 4.05 miles east to a north-south crossroad; set in the top of a painted boulder in the northwest quarter of the intersection, 40.0 feet west from the center line of the north-south road, 18.0 feet north from the center line of the east-west road; a dim chiseled square.

Destroyed RST 5-24-88 1002.834**

DNR BM STE 191 1975 Otter Lake

In Steuben County, in the <u>SE ¹/₄ Sec. 29, T. 37 N., R. 12 E., 2nd PM</u>, about 3.4 miles southwest of <u>Flint</u>; 1.1 miles south along 750 West Road (Flint Road) from its intersection with 50 North Road at Flint to an east-west crossroad (U.S. Highway 20), thence 0.5 mile west to a north-south crossroad (800 West Road), thence 1.3 miles west to a 3.5-foot steel pipe culvert under the road in the inlet to Otter Lake; set in the top of the east concrete wingwall of the culvert, 35.0 feet north from the east concrete wingwall of the culvert, 35.0 feet north from the center line of the road, 22.0 feet below the roadway, 3.5 feet east from the center line of the culvert; a Department of Natural Resources brass control station tablet, stamped "STE 191 1975."

DNR TBM SLK 6 1975 Otter Lake

In Steuben County, in the NE ¼ Sec. 32, T.37 N., 12 E., 2nd PM, about 4.7 miles east-southeast of Brushy Prairie; 1.0 miles south along 925 East Road at Brushy Prairie from its junction with U.S> Highway 20 at Brushy Prairie to an east-west crossroad (100 South Road), thence 4.52 miles east to a T-road north tree in the southwest quarter of the junction, 32.8 feet west from the extended center line of the road, 2.5 feet below the roadway, 0.6 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 6 1975."

DNR TBM SLK 5 1975 Otter Lake

In Steuben County, in the SE ¼ Sec. 28, T. 37 N., R. 12 E., 2nd PM, about 1.7 miles southwest of Flint; 1.0 mile south along 750 West Road from its junction with 50 North Road at Flint to an east-west crossroad (U.S. Highway 20), thence 0.5 mile west to a north-south crossroad (800 West Road), thence 0.5 mile south to a T-road west (100 South Road), thence 0.2 mile west to a small lake on the north side of the road; set in the west side of a 26-inch walnut tree near the southwest corner of the lake, 64 feet east from the center line of a private lane leading to the lake, 48.5 feet southwest from the southwest corner of the lake, 24.0 feet north from the center line of the road, 3.5 feet south from an east-west fence line, 2.6 feet below the roadway, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 5 1975. 1021.398

DNR TBM SLK 4 1975 Otter Lake

In Steuben County, in the NE ¼ Sec. 28, T. 37 N., R. 12 E., 2nd PM, about 1.1 miles southwest of Flint; 1.0 mile south along County Road 750 West from its junction with 50 North Road at Flint to an east-west crossroad (U.S. Highway 20), thence 0.5 mile west to a north-south crossroad (800 West Road); set in the top of the west end of a 12-inch corrugated metal pipe, 67 feet north from the center line of the highway, 12.8 feet west from the center line of the road; the center of two filed notches.

DNR TBM LLK 84 1976 Pigeon Creek

In Steuben County, in the NW ¼ Sec. 18, T. 37 N., R. 12 E., 2nd PM, about 4.5 miles southwest of Orland; 4.35 miles south along State Road 327 from its intersection with State Road 120 in Orland to a T-road west (175 North Road), thence 1.3 miles west to a north-south crossroad (1200 East Road); set in the north side of a 31-inch oak tree in the northeast quarter of the intersection, 138 feet east from the center line of the north-south road, 18.0 feet north from the center line of the east-west road, 0.5 foot above the ground; a railroad spike driven through an aluminum tag, stamped "DNR TBM LLK 84 1976."

DNR BM STE 13 1975 Pigeon Creek

In Steuben County, in the <u>NW ¼ Sec. 18, T. 37 N., R. 12 E., 2nd PM</u>, about 4.5 miles southwest of Orland: 4.5 miles south along State Road 327 from its intersection with State Road 120 in Orland to a T-road west (175 North Road), thence 1.1 miles west to a 63-foot concrete bridge over <u>Pigeon Creek</u>; set in the top of the southeast corner of the bridge floor, 13.5 feet south from the center line of the road, 1.4 feet west from the east end of the bridge, 0.7 foot north from the south face of the bridge; a Department of Natural Resources brass control station tablet, stamped "STE 13 1975".

934.011

DNR BM STE 20 1977 Pigeon Creek

In Steuben County, in the NW ¼ Sec. 20, T. 37 N., R. 12 E., 2nd PM, about 2.4 miles west of Flint; 1.0 mile south along Flint Road from its junction with 50 North Road at Flint to an east-west crossroad (U.S. Highway 20), thence 2.6 miles west to a north-south crossroad (State Road 327), thence 0.45 mile north to a concrete arch bridge over Pigeon Creek; set in the top of the north end of the east concrete guardrail, 17.3 feet east from the center line of the road, 7.3 feet south from the north end of the guardrail, 4.0 feet above the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 20 1977."

DNR BM STE 22 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 20, T. 37 N., R. 12 E., 2nd PM, about 1.7 miles west-southwest of Flint; 1.6 miles west along 50 North Road from its junction with Flint Road (750 West Road) at Flint to a north-south crossroad (900 West Road), thence 0.17 mile south to a 75-foot concrete bridge over Pigeon Creek; set in the top of the west end of the north bridge seat, 15.5 feet west from the center line of the road, 4.6 feet below the roadway, 0.4 foot north from the center line of the road, 4.6 feet below the roadway, 0.4 foot north from the south face of the bridge seat, 0.3 foot east from the west face of the bridge seat; a Department of Natural Resources brass control station tablet, stamped "STE 22 1977."

DNR TBM SLK 26 1977 Pigeon Creek

In Steuben County, in the SE ¼ Sec. 20, T. 37 N., R. 12 E 2nd PM, about 1.65 miles west-southwest of Flint; 1.65 miles west along 50 North Road from its junction with Flint Road at Flint to a north-south crossroad (900 West Road), thence 0.2 mile south to a concrete bridge over Pigeon Creek; set in the top of the southwest concrete wingwall of the bridge, 16.5 feet west from the center line of the bridge, level with the roadway, a painted chiseled triangle.

DNR TBM L 1969 Pigeon Creek

In Steuben County, in the <u>SE ¼ Sec. 20, T. 37 N., R. 12 E., 2nd PM</u>, about 1.65 miles west-southwest of <u>Flint</u>; 1.65 miles west along 50 North Road from its intersection with Flint Road at Flint to a north-south crossroad (900 West Road), thence 0.2 mile south to a concrete bridge over <u>Pigeon Creek</u>; set in the top of the southwest wingwall of the bridge; a chiseled triangle.

DNR BM STE 23 1977 Pigeon Creek

In Steuben County, in the SW ¼ Sec. 21, T. 37 N., R. 12 E., 2nd PM, about 1.45 miles west of Flint; 1.45 miles west along 50 North Road from its junction with Flint Road at Flint to a 65-foot concrete bridge over Pigeon Creek; set in the top of the southeast wingwall of the bridge, 14.5 feet south from the center line of the road, 4.3 feet west from the east end of the wingwall, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 23 1977."

DNR TBM 2 1969 Pigeon Creek

In Steuben County, in the \underline{E} ½ Sec. 21, T. 37 N., R. 12 E., 2^{nd} PM, about 1.5 miles west of Flint; 1.5 miles west along 50 North Road from its junction with Flint Road at Flint to a concrete bridge over Pigeon Creek; set in the top of the southeast wingwall of the bridge; a chiseled triangle.

DNR BM STE 24 1977 Pigeon Creek

In Steuben County, in the NE ¼ Sec. 22, T. 37 N., R. 12 E., 2nd PM, about 0.28 mile north-northeast of Flint; 0.28 mile north-northeast along Flint Road from its junction with 50 North Road at Flint to a concrete bridge over Pigeon Creek; set in the top of the east end of the north bridge abutment, 15.5 feet east from the center line of the road, 0.5 foot north from the south face of the abutment, level with the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 24 1977."

953.524

DNR RP Pigeon Creek

In Steuben County, in the NE ¼ Sec. 22, T. 37 N., R. 12 E., 2nd PM. About 0.3 mile northeast of Flint; 0.3 mile northeast along Flint Road from its junction with 50 North Road at Flint to a concrete bridge over Pigeon Creek; set in the top of the north end of the west vertical steel guardrail post, 13.7 feet west from the center line of the road, 26.2 feet south from the north end of the guardrail, 2.6 feet above the roadway; a filed cross.

DNR BM STE 10 1975 Wall Lake Mud Lake

In Steuben County, in the SW ¼ Sec. 19, T. 38 N., R. 12 E., 2nd PM, about 1.25 miles west of Orland; 0.8 mile generally west along State Road 120 from its intersection with State Road 327 in Orland to a turn south and a T-road west (525 North Road), thence 0.5 mile west to a turn north (1200 East Road), thence 0.4 mile north to a T-road east (625 North Road); set in the top of a concrete post in the northeast quarter of the junction, 26.6 feet east from the center line of the north-south road, 18.4 feet north from the center line of the T-road east, 1.2 feet northeast from a power pole, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 10 1975."

DNR TBM LLK 90 1976 Wall Lake Mud Lake

In Steuben County, in the NW ¼ Sec. 30, T. 28 N., R. 12 E., 2nd PM, about 1.4 miles southwest of Orland; 1.55 miles generally west along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (1200 East Road); set in the northeast side of a 36-inch oak tree in the northeast quarter of the junction, 195 feet east from the extended center line of the north-south road 30.3 feet north from the center line of the highway, 0.7 foot above the ground, a railroad spike driven thru an aluminum tag, stamped "DNR TBM LLK 90 1976."

DNR BM STE 43 1977 Warner Lake Rhodes Lake

In Steuben County, in the SW ¼ Sec. 27, T. 38 N., R. 12 E., 2nd PM, about 2.9 miles southeast of Orland; 1.7 miles generally east along State Road 120 from its intersection with State Road 327 in Orland to a north-south crossroad (800 West Road), thence 1.4 miles south to a T-road east (525 North Road), thence 0.2 mile east to a telephone pole on the north side of the road; set in the top of a concrete post on the north side of the road, 17.0 feet north from the center line of the road, 2.0 feet south from a fence line, 1.5 feet north from the telephone pole; a Department of Natural Resources brass control station tablet, stamped "STE 43 1977."

DNR BM STE 11 1975 unnamed lake

In Steuben County, in the NW ¼ Sec. 31, T. 38 N., R. 12 E., 2nd PM, about 1.65 mile southwest of Orland; 1.55 miles generally west along State Road 120 from its intersection with State Road 327 in Orland to a T-road south (1200 East Road), thence 0.55 mile south to a field entrance road east; set in the top of a concrete post in the northeast quarter of the junction, 26.4 feet north from the center line of the field entrance road east, 16.3 feet east from the center line of the north-south road, 3.4 feet west from a fence line, 1.6 feet east from a telephone pole, 0.5 foot above the roadway, 0.1 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 11 1975."

USGS RM No. 10 Gaging Station Big Turkey Lake

In Steuben County, in the <u>SW ¼ Sec. 7, T. 36 N., R. 12 E., 2nd PM</u>, about 0.55 mile northeast of <u>Stroh</u> (Lagrange County; 0.45 mile north along 1175 East Road from its intersection with 425 South Road at Stroh to a T-road east, thence 0.4 mile generally east to a private drive east (Roy Cully's residence); set in the top of a concrete lake level monument, 200 feet east from the center line of the road, 75 feet southeast from the southeast corner of Cully's house, 18.0 feet west from the west bank of Big Turkey Lake, on the extended center line of the private drive; a U.S. Geological gaging station tablet, not stamped.

DNR BM STE 57A 1977 Henry Lake Big Turkey Lake

In Steuben County, in the SE ¼ Sec. 18, T. 36 N., R. 12 E., 2nd PM, about 2.2 miles west-southwest of Salem Center; 2.0 miles west along 400 South Road from its intersection with 800 West Road at Salem Center to a north-south crossroad (1000 West Road) thence 0.75 mile south to a turn west (475 South Road), thence 0.06 mile west to a 25-foot concrete bridge over Mud Creek; set in the top of the southwest wingwall of the bridge, 62 feet west from the center line of a T-road south, 11.8 feet south from the center line of the east-west road, 2.8 feet southwest from the southwest corner of the south concrete guardrail, 1.2 feet below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 57A 1977."

DNR BM STE 10A 1975 Lake of the Woods McClihs Lake In Steuben County, in the SW ¼ Sec. 30, T. 36 N., R. 12 E., 2nd PM, about 2.4 miles southeast of Stroh (Lagrange County); 0.8 mile west along 425 South Road from its intersection with 1175 East Road at Stroh to a T-road south (1100 East Road), thence 1.15 miles east to a 12-foot steel pipe culvert in the outlet of Lake of the Woods; set in the top of a concrete post, 34.0 feet west from the center line of a T-road south, 21.0 feet south from the center line of the road, 1.0 foot north from a fence line, 0.7 foot west from power pole #489/225, 0.3 foot above the ground; a Department of Natural Resources brass control station tablet, stamped, "STE 10A 1975."

DNR TBM LLK 120 1976 Lake of the Woods McClish Lake In Steuben County, in the SW 1/4 Sec. 30 T. 36 N., R. 12 E., 2nd PM, about 0.55 mile northeast of Stroh (Lagrange County); 0.45 mile north along 1175 East Road from its intersection with 425 South Road at Stroh to a T-road east, thence 0.4 mile generally east to a private drive east (Roy Cully's residence); set in the top of a concrete lake level monument, 200 feet east from the center line of the road, 75 feet southeast from the southeast corner of Cully's house, 18.0 feet west from the west bank of Big Turkey Lake, on the extended center line of the private drive; a U.S. Geological Survey gaging station tablet, not stamped.

DNR BM STE 57A 1977 Henry Lake Big Turkey Lake In Steuben County, in the SE ½ Sec. 18, T. 36 N., R. 12 E., 2nd PM, about 2.2 miles west-southwest of Salem Center; 2.0 miles west along 400 South Road from its intersection with 800 West Road at Salem Center to a north-south crossroad (1000 West Road), thence 0.75 mile south to a turn west (475 South Road), thence 0.06 mile west to a 25-foot concrete bridge over Mud Creek; set in the top of the southwest wingwall of the bridge, 62 feet west from the center line of a T-road south, 11.8 feet south from the center line of the east-west road, 2.8 feet southwest from the southwest corner of the south concrete guardrail, 1.2 feet below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 57A 1977."

DNR BM STE 10A 1975 Lake of the Woods McClish Lake
In Steuben County, in the SW ¼ Sec. 30, T. 36 N., R. 12 E., 2nd PM, about 2.4 miles southeast of Stroh (Lagrange County); 0.8 mile west along 425 South Road from its intersection with 1175 East Road at Stroh to a T-road south (1100 East Road), thence 2.2 miles south to an east-west crossroad (650 South Road), thence 1.15 miles east to a 12-foot steel pipe culvert in the outlet of Lake of Woods; set in the top of a concrete post, 34.0 feet west from the center line of a T-road south, 21.0 feet south from the center line of the road, 1.0 foot north from a fence line, 0.7 foot west from power pole #489/225, 0.3 foot above the ground; a Department of Natural Resources brass control station tablet, stamped "STE 10A 1975."

DNR TBM LLK 120 1976 Lake of the Woods McClish Lake In Steuben County, in the SW ¼ Sec. 30, T. 36 N., R. 12 E. ,2nd PM, about 2.4 miles south of Stroh (Lagrange County); 0.8 mile west along 425 South Road from its intersection with 1175 East Road at Stroh to a T-road south (1100 East Road), thence 2.2 miles south to an east-west crossroad (650 South Road), thence 1.15 miles east to a 12-foot steel pipe culvert in the outlet channel for Lake of the Woods; set in the top of the north end of the culvert, 94 feet west from the center line of a T-road south, 20.2 feet north from the center line of the road, 1.0 foot below the roadway; the center of two filed notches.

DNR TBM SLK 203 1977 Limekiln Lake

In Steuben County, in the <u>NW ¼ Sec. 27, T. 36 N., R. 12 E., 2nd PM,</u> about 2.4 miles south of <u>Salem Center</u>; 2.4 miles south along 800 West Road from its intersection with 400 South Road at Salem Center to a 5-foot steel pipe culvert under the road; set in the west side of a 24-inch walnut tree, 89 feet south from the center line of the culvert, 14.8 feet east from the center line of the road, 1.1 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 203 1977."

958.050

DNR TBM SLK 201 1977 Limekiln Lake

In Steuben County, in the NE ¼ Sec. 32, T. 36 N., R. 12 E., 2nd PM, about 0.8 mile north-northeast of Helmer; 0.75 mile north along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road east (700 South Road), thence 0.25 mile east to a 20-inch ash tree on the south side of the road; set in the north side of the tree, 17.5 feet south from the center line of the road, 2.6 feet north from a fence line, 0.6 foot above the ground; a railroad spike.

961.215

DNR TBM 21 1971 Limekiln Lake

In Steuben County, in the <u>SW ¼ Sec. 29, T. 36 N., R. 12 E., 2nd PM</u>, about 0.75 mile north of <u>Helmer</u>; 0.75 mile north along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road east (700 South Road); set in the northwest quarter of the junction, 45 feet north from the extended center line of the T-road, 36 feet west from the center line of the highway, 0.2 foot above the ground; a railroad spike.

DNR TBM SLK 205 1977 Mud Creek unnamed lake

In Steuben County, in the SE ¼ Sec. 16, T. 36 N., R. 12 E., 2nd PM, about 1.0 mile south of Salem Center; 1.0 mile south along 800 West Road from its intersection with 400 South Road at Salem Center to an east-west crossroad (500 South Road); set in the south side of power pole #464694 in the northwest quarter of the intersection, 203 feet west from the center line of the north-south road, 19.4 feet north from the center line of the east-west road, 0.5 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 205 1977."

DNR BM STE 58 1977 Mud Creek Henry Lake

In Steuben County, in the N $\frac{1}{2}$ Sec. 20, T. 36 N., R. 12 E., 2^{nd} PM, about 2.05 miles southwest of Salem Center; 1.5 miles west along 400 South Road from its intersection with 800 West Road at Salem Center to a north-south crossroad (State Road 327), thence 1.45 mile south to a 20-foot bridge over Mud Creek; set in the top of the north end of the west concrete curb of the bridge, 17.5 feet west from the center line of the highway, 2.0 feet south from the north end of the curb, 0.8 foot above the highway; a Department of Natural Resources brass control station tablet, stamped "STE 58 1977."

939.167

DNR TBM LK 204 1977 Mud Creek

In Steuben County, in the SE ¼ Sec. 21, T. 36 N., R. 12 E., 2nd PM, about 1.7 miles south of Salem Center; 1.7 miles south along 800 West Road from its intersection with 400 South Road at Salem center to a T-road west (575 South Road); set in the north side of a 27-inch walnut tree in the southwest quarter of the junction, 31.8 feet south from the center line of the T-road west, 22.6 feet west from the center line of the road, 0.8 foot above the ground; a railroad spike driven thru an aluminum tag, stamped "DNR TBM SLK 204 1977."

DNR BM STE 31 1971 Mud Creek unnamed lake

In Steuben County, in the SE ¼ Sec. 16, T. 36 N., R. 12 E., 2nd PM, about 1.0 mile south of Salem Center; 1.0 mile south along 800 West Road from its intersection with 400 South Road at Salem Center to an east-west crossroad (500 South Road); set in the top of a concrete post in the northwest quarter of the intersection, 70 feet west from the center line of the north-south road, 25.3 feet north form the center line of the east-west road, 2.0 feet east from power pole #467/644, 0.1 foot below the ground; a Department of Natural Resources brass control station tablet, stamped "STE 31 1977." 989.274

DNR TBM 2A 1971 Turkey Creek Big Turkey Lake

In Steuben County, in the <u>SW ½ Sec. 18, T. 36 N., R. 12 E., 2nd PM</u>, about 0.6 mile southeast of Stroh (Lagrange County); 0.75 mile south along 1175 East Road from its intersection with 425 South Road at Stroh to an east-west crossroad (500 South Road), thence 0.22 mile east to a north-south road (1100 West Road), thence 0.25 mile north to a T-road east (475 South Road); set in the northwest side of a power pole, 180 feet south from the center line of the T-road east, 17.0 feet east from the center line of the north-south road, 0.8 foot above the ground; a railroad spike.

DNR TBM SLK 200 1977 Turkey Creek Big Turkey Lake

In Steuben County, in the S ½ Sec. 18, T. 36 N., R. 12 E., 2nd PM, about 2.5 miles west-southwest of Salem Center; 2.0 miles west along 400 South Road from its intersection with 800 West Road at Salem Center to a north-south crossroad (1000 West Road), thence 0.75 mile south to a turn west (475 South Road), thence 0.35 mile west to twin 8-foot steel pipe culverts under the road in Turkey Creek; set in the top of the north end of the east steel pipe culvert, 25.0 feet north from the center line of the road, 3.0 feet below the roadway; the center of two filed notches.

DNR TBM 1A 1971 Turkey Creek Stump Ditch

In Steuben County, in the <u>SW ¼ Sec. 19, T. 36 N., R. 12 E., 2nd PM</u>, about 2.3 miles northwest of <u>Helmer</u>; 1.73 miles north along State Road 327 from its intersection with Wabash Railroad at Helmer to a T-road west (Turkey Creek Road); set in the southwest side of a 22-inch oak tree in the northwest quarter of the junction, 33 feet north from the center line of the east-west rod, 21 feet west from the extended center line of the T-road south, 0.2 foot above the ground; a railroad spike.

USGS BM W9 1938 Turkey Creek

In Steuben County, in the NW ¼ Sec. 29, T. 36 N., R. 12 E., 2nd PM, about 1.7 miles north of Helmer; 1.72 miles north along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road west; (Turkey Creek Road), thence 0.04 mile west to a T-road south; set in the top of a concrete post in the southeast quarter of the junction, 110 feet south from the center line of the east-west road, 17.5 feet east from the center line of the north-south road, 0.3 foot above the ground; a U.S. Geological Survey bench mark tablet, stamped "W4 1938 955."

DNR BM STE 59 1977 Turkey Creek Limekiln Lake

In Steuben County, in the <u>SW ½ Sec. 20, T. 36 N., 12 E., 2nd PM</u>, about 2.5 miles southwest of <u>Salem Center</u>; 1.5 miles west along 400 South Road from its intersection with 800 West Road at Salem Center to a north-south crossroad (State Road 327), thence 2.0 mile to a 30-foot bridge over <u>Turkey Creek</u>; set in the top of the northeast end of the southeast concrete curb, 16.1 feet southeast from the center line of the highway, 0.9 foot above the highway, 0.8 foot southwest from the northeast end of the curb, a Department of Natural Resources brass control station tablet, stamped "STE 59 1977."

945.282

DNR BM STE 73 1977 Turkey Creek Limekiln Lake

In Steuben County, in the SE ¼ Sec. 28, T. 36 N., R. 12 E., 2nd PM, about 1.45 miles northeast of Helmer; 0.75 mile north along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road east (700 South Road), thence 1.25 miles east to a 24-foot concrete bridge over Turkey Creek; set in the top of the northeast wingwall of the bridge, 15.8 feet north from the center line of the road, 1.3 feet southwest from the northeast end of the wingwall, 0.5 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 73 1977." 940.791

DNR TBM 20 Turkey Creek Limekiln Lake

In Steuben County, in the NE ¼ Sec. 33, T. 36 N., R. 12 E., 2nd PM, about 1.45 miles northeast of Helmer; 0.75 mile north along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road east (700 South Road), thence 1.25 miles east to a 24-foot concrete bridge over Turkey Creek; set in the top of the southeast concrete wingwall of the bridge, 15.5 feet south from the center line of the road, 1.7 feet northwest from the southeast end of the wingwall, 0.2 foot below the roadway, a painted chiseled triangle.

DNR TBM 19 1971 Turkey Creek

In Steuben County, in the NE ¼ Sec. 33, T. 36 N., R. 12 E., 2nd PM, about 1.78 miles northeast of Helmer; 0.25 mile south along State Road 327 from its intersection with the Wabash Railroad at Helmer to a T-road east (State Road 727), thence 1.62 mile east to a T-road north (800 West Road), thence 1.0 mile north to a bridge over Turkey Creek; set in the top of the south end of the west steel guardrail, 15 feet west from the center line of the road, 2.0 feet north from the south end of the guardrail, 2.0 feet above the roadway; a filed cross.

DNR TBM SLK 202 1977 Turkey Creek

In Steuben County, in the SW ¼ Sec. 27, T. 36 N., R. 12 E., 2nd PM, about 3.0 miles south of Salem Center; 3.0 miles south along 800 West Road from its intersection with 400 South Road at Salem Center to a bridge over Turkey Creek; set in the top of a vertical steel brace on the north end of the east guardrail, 25.8 feet south from the north end of the guardrail, 11.5 feet east from the center line of the road, 2.0 feet above the roadway; the center of two filed notches.

DNR BM STE 74 1977 Turkey Creek

In Steuben County, in the SW ¼ Sec. 27, T. 36 N., R. 12 E., 2nd PM, about 3.0 miles south of Salem Center; 3.0 miles south along 800 West Road from its intersection with 400 South Road at Salem Center to an east-west offset crossroad (700 South Road), thence 0.35 mile east to a 24-foot concrete bridge over Turkey Creek; set in the top of the northwest wingwall of the bridge, 14.4 feet north from the center line of the road, 1.0 foot southeast from the northwest end of the wingwall, 0.5 foot below the roadway; a Department of Natural Resources brass control station tablet, stamped "STE 74 1977."

DNR TBN 18 Turkey Creek

In Steuben County, in the <u>SW ½ Sec. 27, T. 36 N., R. 12 E., 2nd PM</u>, about 3.0 miles south of <u>Salem Center</u>; 3.0 miles south along 800 West Road from its intersection with 400 South Road at Salem Center to an east-west offset crossroad (700 South Road), thence 0.35 mile east to a 24-foot concrete bridge over <u>Turkey Creek</u>; set in the top of the west end of the concrete guardrail, 9.0 feet north from the center line of the road, 6.0 feet east from the west end of the guardrail, 3.7 feet above the roadway; a chiseled triangle.

949.831

IDOT BM F 30 STE

In Steuben County, Orland Quad, set in the NW ¼ of section 20, T.38 N., R.12 E., 2nd P.M. About 0.65 miles north of Orland. Set on top of the southwest corner of the bridge deck for the S. R. 327 bridge over the By Pass channel for Crooked Creek. ± 450 feet south of the S. R. 327 bridge over Crooked Creek, 0.5 foot west of the west aluminum guard rail for bridge, 0.3 foot north of the south face of concrete bridge deck, 0.35 foot east of the west face of the concrete bridge deck, 0.6 foot south of the southwest bolt of the aluminum guardrail support base plate, about level with the highway. A STATE HIGHWAY COMMISION OF INDIANA SURVEY bench mark tablet stamped "F 30 STE".

IDNR STA 7

In Steuben County, Orland Quad, set in the NE ¼ of section 20, T.38 N., R.12 E., 2nd P.M. About 0.6 miles north of Orland. Set at the Fawn River State Fish Hatchery. From the intersection of a gravel road leading to fish ponds and S. R. 327 proceed about 0.1 mile east along gravel road to the northwest ¼ of the intersection on the first four ponds east of S. R. 327. 44 feet north of the centerline of the gravel access road, 31.3 feet northwest of a metal manhole cover and concrete pad, 36.1 feet northwest of the northwest corner of the 1st step of the concrete steps leading down to the northeast pond, 28.3 feet northwest of a 6 inch metal water access cover and concrete pad, 40.3 feet northwest of the southwest corner of the concrete control structure of the northeast pond, 11.7 feet west of the centerline of grass berm between the north two ponds. About level with the ground and about 1 foot below the level of the berm. A 5/8 inch rebar with an aluminum cap stamped "7" 3rd Order 947.067 feet NGVD 1929

IDNR STA 8

In Steuben County, Orland Quad, set in the NE ¼ of section 20, T.38 N., R.12 E., 2nd P.M. About 0.6 miles north of Orland. Set at the Fawn River State Fish Hatchery. From the intersection of S. R. 327 and the first gravel road leading east on the north side of By Pass channel bridge, proceed about 0.25 mile east along gravel road to the northeast corner of the fish ponds and the confluence of Crooked Creek and Lake. 277.8 feet east of the southeast corner of a concrete pond inlet in crooked Creek, 36 feet west of a lone twin trunk willow tree on the bank of the lake, 10 feet north of the centerline of the gravel road, 6.5 feet south of the edge of water of lake, about level with the ground, and about level with the gravel road, A 5/8 inch rebar with an aluminum cap stamped "8"

3rd Order

950.094 feet NGVD 1929

IDOT BM F 28 STE

In Steuben County, Orland Quad, set in the SW ¼ of section 21, T.38 N., R.12 E., 2nd P.M. About 0.9 miles northeast of Orland. Set in the northwest corner of the S. R. 120 bridge over Crooked Creek. Set on top of the concrete bridge deck. 23.4 feet northwest of the centerline of S. R. 120, 1.2 feet northwest of the aluminum guardrail, 1.5 feet northeast of the expansion joint of the bridge, 0.5 foot southeast of the northwest face of the concrete bridge deck. A STATE HIGHWAY COMMISION OF INDIANA SURVEY bench mark tablet stamped. "F 28 STE".

3rd Order

954.207 feet NGVD 1929

IDNR TBM CCSC 1 2001

In Steuben County, Orland Quad, set in the SW ¼ of section 21, T.38 N., R.12 E., 2nd P.M. About 0.9 miles northeast of Orland. Set in top of the northeast concrete bridge abutment of the S. R. 120 bridge over Crooked Creek. 23.1 feet northwest of the centerline of S. R. 120, 1.1 feet northwest of the aluminum guardrail, 3.6 feet southwest of the northeast end of concrete abutment, 0.8 foot northeast of the expansion joint of bridge, 0.5 foot southeast of the northwest face of the abutment. A chiseled triangle.

3rd Order

954.200 feet NGVD 1929

IDNR STA9

In Steuben County, Orland Quad, set in the SW ¼ of section 21, T.38 N., R.12 E., 2nd P.M. About 0.75 miles northeast of Orland. From the intersection of S. R. 327 and S. R. 120 proceed northeast along S. R. 120 about 0.75 miles to the first power pole east of "Green Lawn Cemetery" with 3 guy wires to the west on the northwest side of S. R. 120. 107.5 feet east of a metal telephone pedestal, 56.4 feet northwest of the centerline of S. R. 120, 4.7 feet west of the power pole, 4.3 feet east of the anchor of the east most of 3 guy wires, about 2.5 feet above the centerline of S. R. 120, about flush with the ground, a 5/8 inch rebar and aluminum cap stamped "9" 3rd Order 957.471 feet NGVD 1929

IDNR STA 10

In Steuben County, Orland Quad, set in the SW ¼ of section 21, T.38 N., R.12 E., 2nd P.M. About 0.9 miles northeast of Orland. Set near the southeast corner of the S. R. 120 bridge over Crooked Creek. 101.4 feet southwest of the northeast most post for aluminum guardrail on the southeast side of S. R. 120, 25.7 feet southeast of the centerline of S. R. 120, 18.4 feet northeast of the northeast end of the southeast concrete abutment of bridge, 2.8 feet southeast of the aluminum guardrail, about 0.1 foot below the ground, a 5/8 inch rebar and aluminum cap stamped "10" 3rd Order 956.897 feet NGVD 1929

Steuben County Hamilton Quadrangle Fish Creek

DNR TBM FISH 19 1992 (Text and Elevation unverified)

In Steuben County, Hamilton Quadrangle, in the <u>SE ¼ of Sec. 33, T. 36 N., R. 14 E.</u> 2ndP.M. at the intersection of State Road 1 and State Road 427 in Hamilton, proceed 0.4 miles southwest along State Road 427 to a Power Pole # S 430-108, set in the east side of the pole, 21.5 feet northwest from the centerline of the highway, 30.0 feet southwest from the centerline of the drive way to the Tri-State propane Ind., 1.0 foot above the ground, a Railroad Spike driven thru an aluminum tag, stamped, "IDNR TBM Fish 19 1992".

3rd Order

896.891 feet NGVD 29

Steuben County Edon Quadrangle Fish Creek

DNR TBM FISH 26 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the SW ¼ of Sec. 31. T. 36 N. R. 15 E ,2nd P.M. at the intersection of County Road 4 A and County Road 700 East, thence 1.5mile north along County Road 700 E to bridge over Fish Creek, approximately 5.0 miles west of Edon. TBM is a chiseled triangle in the south east bridge decking; 15.5 feet east of the centerline of County Road 700 East; 42.0 feet north of bridge sign (east side of Rd.) 1.0 feet below iron guardrail; 5.9 feet north of south face, even with road surface, "Fish 26 1996".

DNR TBM FISH 27 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the NW ¼ of Sec. 31. T. 36 N. R. 15 E. 2nd P.M. at the intersection of State Road 427 and County Road 800 East, thence 1.4 miles south along CR 800 East to a CR 750 south, thence 0.5 miles west along CR 750 South to a bridge over Fish Creek, Approximately 4.5 miles west of Edon. TBM is 2 filed notches on top of "I" beam of guardrail on northwest corner of the bridge, 2nd "I" beam East of bridge sign on North side of road, 14.0 feet north of centerline of CR 750 south; 8.3 feet east of NW bridge sign; 2.4 feet above bridge surface; 0.8 feet east of west face of the bridge; "Fish 27, 1996." 3rd Order 899.059 NGVD 29

DNR TBM FISH 28 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the <u>SE ¼ of Sec. 30. T. 36 N. R. 15 E. 2nd P.M.</u> at the intersection of State Road 427 and County Road 800 East, thence 0.5 miles south along CR. 800 East to CR. 650 South, thence 0.1 mile west along CR. 650 south to a bridge over Fish Creek, TBM <u>is two filed notches</u> on top of "I" beam of quadrail on the northwest corner of the bridge, 4th "I" beam from the west. 14.9 feet north of center line of CR. 650 South; 6.0 feet east of the west edge of the bridge; 0.15 feet above the guardrail; 2.4 feet above the bridge surface; "Fish 28, 1996."

3rd Order **905.299 feet NGVD 29**

Steuben County Edon Quadrangle Fish Creek

SHCI BM F7 (Text and Elevation unverified)

In Steuben County, Edon Quad, in the SW ¼, Sec. 20, T. 36N., R. 15 E. 2nd PM. about 1.5 miles west of the Indiana-Ohio State line along State Road 427. 15.2 feet north of center line of Road, 0.2 feet east of west end of bridge, 0.8 feet above the roadway, 0.3 feet above the roadway. 0.3 feet south of concrete guardrail a standard tablet in concrete curbing and stamped SHCI F7 ST---. (Stamping Blurred).

3rd Order **911.877 feet NGVD 29**

DNR TBM FISH 29 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the NW ¼ of Sec. 20. T. 36 N. R. 15 E. 2nd P.M at the intersection of County Road 850 E and County Road 525 South thence north 20.0 feet to bridge over Fish Creek, Approximately 3.0 miles northwest of Edon. 14.0 feet west of the center line of CR. 525 South; 0.9 feet below the guardrail; 0.4 feet south of north face, a chiseled triangle, set in the north end of west concrete guardrail, "Fish 29 1996" 3rd Order **920.887 Feet NGVD 29**

DNR TBM FISH 36 1999 (Text and Elevation unverified)

In Steuben County, Edon Quad, north <u>center section 17, T 36 N., R. 15 E. 2nd P.M.</u> about 2.0 miles south of Metz, Indiana, to intersection of 400 south road and 800 East Road, thence east 0.5 mile to intersection of 850 East Road. 21.1 feet south of centerline of 400 south Road. 25.0 feet west of centerline of 850 East Road, 8.6 feet southeast of stop sign 6.8 feet northwest of power pole (no Numbers) 3.0 feet above ground. A chiseled triangle in top of concrete fence corner post. "FISH 36 1999"

3rd Order **950.621 feet NGVD 29**

DNR TBM FISH 30 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the NW ¼ of Sec. 16. T. 36 N. R. 15 E. 2nd P.M. at the intersection of County Road 850 East and County Road 400 South, thence 0.7 mile east along 400 South to a bridge over fish creek, approximately 2.5 miles northwest of Edon. 15.0 feet south of the center line of CR 400 South; 120.5 feet East of mailbox # 9309; 8.7 feet west of East face; 1.3 feet below guardrail; level with bridge surface, "Fish 30 1991, "set on southeast corner of bridge, a chiseled triangle.

3rd Order **925.136** feet NGVD **29**

Steuben County Edon Quadrangle Fish Creek

DNR TBM FISH 31 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the SW ¼ of Sec. 4/9. T. 36 N. R. 15 E. 2nd P.M. at the intersection of County Road 850 East and County Road 300 South, thence 0.6 miles east to a bridge over Fish Creek, Approximately 3.0 miles northwest of Edon. 14.0 feet north of the centerline of CR. 300 south; 3.1 feet east of west end of the bridge; 1.3 feet below the guardrail; even with bridge surface, A chiseled triangle at the northwest corner of the bridge. "Fish 31 1996."

3rd Order 935.574 feet NGVD 29

DNR TBM FISH 312 1996 (Text and Elevation unverified)

In Steuben County, Edon Quadrangle, in the NE ¼ of Sec. 5, T. 36 N, R. 15E. 2nd P.M at the intersection of Metz Road and County Road 800 East, thence 1.0 miles east along Metz Rd. to a bridge over Fish Creek, Approximately 1.0 mile East of Metz. set in north side of power pole # 30404, 20.8 feet south of the center line of Metz Rd., 8.7 feet south of southeast bridge sign; 37.5 feet west of telephone riser box; 2.2 feet above ground, a R.R. spike thru aluminum tag stamped "Fish 312 1996."

3rd order **943.204 feet NGVD 29**

Steuben County Clear Lake Quadrangle Fish Lake

DNR TBM TR 90-1 1999 (Text and Elevation unverified)

In Steuben County, Clear Lake Quad, NW ¼, 33, T. 37 N, R. 15 E 2nd P.M., set at CR 935 East bridge over toll Rd. 80 and 90, set at the SE Corner of the bridge, 15.6 feet east of the centerline of CR 935 East, 0.4 feet north of south end of east concrete guardrail 0.7 feet west of the east face of concrete guardrail 2.2 feet above the road, set in the SW most bolt of bolt to hold aluminum guardrail to concrete guardrail, a filed cross on top of bolt.

3rd Order 997.934 Feet NGVD 29

DNR TBM FISH 33 1996 (Text and Elevation unverified)

In Steuben County, Clear Lake Quadrangle, in the SE ¼ of Sec. 29, T. 37 N, R. 15 E. 2nd P.M. at the State Road 20 Bridge over Fish Creek, approximately 1.5 miles west of Columbia, Ohio, 21.5 feet north of center line of State Road 20, 2.7 feet above ground, 1.9 feet west of the east corner of north concrete guardrail, 0.6 feet south of north edge of north concrete guardrail, a chiseled triangle in the east end of the north concrete guardrail, IDNR TBM "Fish 33, 1986".

DNR TBM FISH 34 1996 (Text and Elevation unverified)

In Steuben County, Clear Lake Quadrangle, in the <u>NW ¼ of Sec. 28. T. 37 N. R. 15 E.</u> 2nd P.M. at the intersection of State Road 20 and County Road 925 East, thence north 0.6 miles to T-intersection with county Road 40 South, thence 0.2 miles west on County Road 40 south to a bridge over fish creek, approximately 1.5 miles west of Columbia, Ohio, 16.0 feet south of center line of County Road 40 South, 1.3 feet below east end of south guardrail, 0.6 feet north of south edge of the wingwall, 0.7 feet east of the west edge of the wingwall, about level with road, a chiseled "Δ" in the south east wingwall of County Road 40 south bridge over fish creek, "Fish 34 1996"

3rd Order **949.512 feet NGVD 29**

Steuben County Clear Lake Quadrangle Fish Lake

DNR TBM FISH 35 1996 (Text and Elevation unverified)

In Steuben County, Clear Lake Quadrangle, in the SE ¼ of Sec. 21, T. 37 N, R. 15 E, 2nd P.M., at the intersection of State Road 20 and County Road 935 East, thence north along County Road 935 East 0.6 miles to T-intersection with County Road 40 south, thence east 0.2 miles along C. R. 40 S., thence north 0.4 miles to County Road 950 East Culvert over Fish Creek, approximately 1.4 miles northwest of Columbia Ohio, 28.5 feet south of 14" diameter metal pipe leading to creek, 21.0' feet east of the centerline of County Road 950 East,12.5 feet south of the centerline of 72" metal culvert pipe, 0.45 feet west of east end of 72" metal pipe, a nut and bolt on the east end of the South 72" metal culvert pipe under County Road 950 East on fish creek, "Fish 35, 1996"

3rd Order **949.429 feet NGVD 29**

Steuben County Hamilton Quadrangle Hiram Sweet Ditch

BALL LAKE LAKE LEVEL MONUMENT (Text and Elevation unverified)
In Steuben County, Hamilton Quad, NE ¼ Sec 32, T 36 N., E. 14 E., 2nd PM, at the outlet of Ball Lake, Hiram Sweet Ditch, AKA Wally Dam. 30.9 feet south of the center line of the road, 16.5 feet west of the center line of ditch, 7.0 feet southeast of power pole, 1.0 feet of north of end of chain link fence, 1.5 feet above ground, set in a monolithic concrete pillar, straddling a corrugated steel sheet piling retaining wall. a standard Indiana Department of Natural Resources Control Station tablet not stamped.

2ND Order 274.099 meters NGVD 29 899.274 feet NGVD 29

DNR TBM HSD 1 1996 (Text and Elevation unverified)

In Steuben County, Hamilton Quadrangle, in the SW ¼ of Sec. 33, T. 36 N, R. 14 E, 2nd P.M. At the intersection of Belk fountain Rd and Homestead Rd., Approximately 1.0 mile west of Hamilton, thence south along Homestead Rd 0.3 miles to a bridge over Hiram Sweet Ditch. Set in the east side of Power pole # 5430-212 with a light. 25.5 feet west of centerline of Homestead Rd, 42.0 feet south of the center line of Hiram Sweet Ditch; 7.0 feet SW of end of iron guardrail, 1.3 feet above the ground, a RR spike thru aluminum tag stamped "HSD 1, 1996."

DNR TBM HSD 3 1996 (Text and Elevation unverified)

In Dekalb County, Hamilton Quadrangle, in the NW ¼ of Sec. 2, T. 35 N, R. 14 E. 2nd P.M. Approximately 1.4 miles East of Hamilton, at the intersection of County Road 775 south and County Road E 535 Rd, thence 0.4 miles south along E 535 Rd, to a bridge over Hiram Sweet Ditch, TBM is an old High Water Mark set in the north side of 70" triple trunk cottonwood, 130.8 feet west of the centerline of E 535 Rd, 29.0 feet south of the centerline of gravel drive to Kolcyski Residence; near the left edge of water, 2.3 feet above ground, a 20d nail thru bottle cap. 3rd Order 880.823 feet NGVD 29

Department of Natural Resources Division of Water Steuben County

DNR TBM PC 1, 1996 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the SW ¼ of Section 33, T. 36 N., R. 14 E., 2nd PM.; approximately 6.0 miles north of <u>Hamilton</u>; approximately 0.7 mile west along Metz Road from its intersection with 1996 State Road 1 to a pipe culvert over Pigeon Creek; set in the south side of a 24 inch Elm tree, 19.2 feet south of the centerline of Metz Road, 7.0 feet east of the east pipe, 5.8 feet south of the south guardrail, 2.3 feet above the ground; a railroad spike driven thru an aluminum tag, stamped "IDNR TBM PC 1, 1996".

Third Order

999.022 feet N.G.V.D. 1929 304.5025 meters N.G.V.D. 1929

DNR TBM PC 2, 1996 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the SE ¼ of Section 5, T. 36 N., R. 14 E., 2nd PM.; approximately 5.0 miles north of <u>Hamilton</u>; approximately 0.4 mile north along 275 East Road from its intersection with Shoughniss Road to the 275 East Road concrete bridge over Pigeon Creek; set in the west bridge abutment (wingwall), 13.5 feet west of the centerline of 275 East Road, 5.6 feet south of the north end of the west bridge abutment (wingwall), 5.5 feet east of a fence line, 2.1 feet north of the north guardrail post on the west side of the bridge, 0.7 foot north of the expansion joint at the north end of the bridge, about level with the road; a chiseled triangle.

Third Order

988.042 feet N.G.V.D. 1929

301.1558 meters N.G.V.D. 1929

DNR TBM PC 3, 1996 (Text and Elevation unverified)

In Steuben County, Angola West Quad., in the SW ¼ of Section 25, T. 37 N., R. 12 E., 2nd PM.; approximately 4.9 mile west of <u>Angola</u>; 600 West Road wood bridge over Pigeon Creek; set in the northeast wood wingwall of the bridge, 31.5 feet north of the centerline of Pigeon Creek, 18.0 feet east of the centerline of 600 West Road, 18.0 feet south of the south post of a farm access gate, 4.2 feet east of the east wood guardrail, 3.0 feet below the level of the road; a railroad spike driven thru an aluminum tag, stamped "IDNR TBM PC 3 1996".

Third Order

958.527 feet N.G.V.D. 1929 292.1596 meters N.G.V.D. 1929

USGS TT 35 T BM 1937 (Text and Elevation unverified)

In Steuben County, Hamilton Quad, set in the SE ¼ of section 14, T. 36 N. R. 14 E., 2nd P. M. About 2.25 miles northeast of Hamilton, IN. Set in the northeast ¼ of the intersection of 500 South Road and 550 East Road. Set in top of a concrete post, 35.5 feet north of the centerline of 500 South Road, 33 feet east of the centerline of 550 East Road, 36.2 feet northwest of a metal "STOP" sign post, 22.0 feet southeast of a power pole with guy wire, 3.5 feet north-northwest of a metal "GTE" telephone pedestal with a orange "warning buried telephone cable" sign post, about 2 feet below the intersection, set flush with the ground. A USGS BM tablet stamped "TT35T 1937 970"

2nd Order

969.774 feet NGVD 1929

DNR TBM SLK 300 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad, set in the SE ¼ of section 14, T. 36 N. R. 14 E., 2nd P. M. About 2.3 miles northeast of Hamilton, IN. Set in the northeast ¼ of the intersection of 500 South Road and Haughey Ditch pipe culvert under the road. Set in the west side of a power pole. 160.3 feet east of the north end of the Haughey Ditch pipe culvert, 57 feet northwest of the east end of a plastic pipe culvert under a gravel field entrance, 66.5 feet east of the centerline of the gravel field entrance, 45.5 feet north of the centerline of 500 North Road, about 0.5 foot above the road, about 1 foot above the ground. A double headed nail driven through an aluminum tag stamped "SCS"

2nd Order 90

963.591 feet NGVD 1929

DNR TBM SLK 301 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad, set in the SE ¼ of section 14, T. 36 N. R. 14 E., 2nd P. M. About 2.3 miles northeast of <u>Hamilton</u>, IN. Set in the northwest ¼ of the intersection of 500 South Road and Haughey Ditch pipe culvert under the road. Set in the south side of a power pole. 145.5 feet southeast of the southeast corner of a large metal barn, 121.8 feet west-northwest of the north end of the Haughey Ditch pipe culvert, 78.9 feet northwest of a 3 inch metal telephone pedestal, 144 feet east of the centerline of the gravel drive leading to the barn, 44 feet north of the centerline of 500 South Road, about 1 foot below the road, about 1.6 feet above the ground. A railroad spike through an aluminum tag stamped "DNR TBM SLK 301 2001"

2nd Order

964.695 feet NGVD 1929

DNR TBM SKL 302 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad, set in the NE ¼ of section 26, T. 36 N. R. 14 E., 2nd P. M. About 1.8 miles northeast of Hamilton, IN. Set in top of the southeast corner of the wood bridge deck of the 550 East road bridge over Black Creek. 19. 4 feet north of a "GTE" telephone pole # 30211/196, 12.8 feet east of the centerline of 550 East Road, 0.8 foot south of the south most wood guardrail support post, 0.5 foot east of the east wood wheel guard, 1 foot west of the east end of the wood bridge seat, about 0.1 foot below asphalt bridge deck. A 3 inch bolt head stamped "SLK 302"

2nd Order **948.748 feet NGVD 1929**

DNR TBM SLK 303 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad, set in the NE ¼ of section 26, T. 36 N. R. 14 E., 2nd P. M. About 1.0 miles northeast of <u>Hamilton</u>. Set at the intersection of S. R. 427 and 700 South Road. Set in the northwest side of power pole # S410/196 with a guy wire. 85.5 southeast of the centerline of S. R. 427, 62.3 feet northeast of the centerline of 700 South Road, 68 feet east of a metal "SR427/700S" road sign post, 11.7 feet north of a 3 inch pine tree, 1.8 feet above the ground. A railroad spike through an aluminum tag stamped "DNR TBM 303 2001" 2nd Order **917.682 feet NGVD 1929**

DNR TBM SLK 304, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NE ¼ of Section 32, T. 36 N., R. 14E., 2nd PM; about 0.4 mile northwest of <u>Hamilton</u>; at the "T" road intersection of BelleFountain Road and 300 East Road; set in the north side of power pole # ST 429/5 with a light and a guy wire to the south, 34.5 feet south of the centerline of Belle Fountain Road, 20.2 feet southwest of the "LAKERS FOOD & SPIRITS" sign post, 9.8 feet southwest of a metal road sign post, 13.5 feet west of the extended centerline of 300 East Road, 5.3 feet southwest of a metal telephone pedestal, 1.0 foot above the ground, about 2.0 foot above Belle Fountain Road; a railroad spike driven through an aluminum tag, stamped "IDNR TBM SLK 304, 2001".

DNR TBM SLK 305, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the SW ¼ of section 28, T. 36 N., R. 14 E., 2nd PM; about 1.0 mile northwest of <u>Hamilton</u>; about 0.5 mile north along 300 East Road from its intersection with Belle Fountain Road; set in the west side of a telephone pole #S409/245 #30205/154, with guy wire, 19.7 feet east of the centerline of 300 East Road, 51.2 feet south of a chain link fence corner post, 48.0 feet west of the southwest corner of a house # 6790 S., 1.5 feet north of a metal telephone pedestal, 1.0 feet above the ground, about 1.0 foot above the road; a railroad spike driven through an aluminum tag, stamped "IDNR TBM SLK 305 2001". 2nd Order <u>959.652 Feet NGVD 1929</u>

DNR TBM SLK 306 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NW ¼ of Section 28, T. 36 N., R. 14 E., 2nd PM; about 1.5 miles northwest of <u>Hamilton</u>; Set at the 300 East Road pipe Culvert over a small stream leading to Muskrat Bay and the south entrance to "Flegal Sand & Gavel. Set in the southeast side of power pole # S409/55 with a guy wire. About 135 feet north of the pipe culvert, 106.8 feet southwest of a metal gate post an the entrance to "Flegal Sand & Gravel, 38.4 feet east of the centerline of 300 East Road, 17.2 feet east of a telephone pole and metal telephone pedestal, 0.7 foot above the ground, about level with 300 East Road, a railroad spike driven through an aluminum tag, stamped "IDNR TBM SLK 306 2001".

DNR TBM SLK 307, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NW ¼ of Section 28, T. 36 N., R. 14 E., 2nd PM; about 1.5 miles northwest of <u>Hamilton</u>; at the south entrance to "FLEGAL SAND & GRAVEL" and 300 East Road; set in the north side of the 2nd power pole # S409/59 east of the "FLEGAL SAND & GRAVEL" entrance gate, 14.5 feet south of the centerline of the dirt & gravel entrance road, about 325 east of the aluminum gate post, 1.4 foot above the ground; a railroad spike driven through an aluminum tag, stamped "IDNR TBM SLK 307 2001".

DNR TBM SLK 308, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NW ¼ of Section 28, T. 36., R. 14 E., 2nd PM; about 1.5 miles northwest of <u>Hamilton</u>; at the intersection of 1.5 miles northwest of Hamilton; at the intersection of 300 East Road & the South entrance to "FLEGAL SAND & GRAVEL"; set in the south side of the 3rd power pole # S409/60 northeast of the "FLEGAL SAND & GRAVEL" entrance gate, 27.5 feet north of the centerline of the dirt & gravel entrance road, about 530 feet northeast of the metal gate post, 0.6 foot above the ground, about 2.5 feet above the level of the dirt & gravel road; a railroad spike driven through an aluminum tag, stamped "IDNR TBM SLK 308 2001".

2nd Order **910.310 feet NGVD 1929**

DNR FLEGAL 1, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NW ¼ of Section 28, T. 36N., R.14 E., 2nd PM; about 1.5 miles northwest of <u>Hamilton</u>; at the intersection of 300 East Road and the south entrance to FLEGAL SAND & GRAVEL; about 515 feet northeast of the aluminum gate post at the entrance to FLEGAL SAND & GRAVEL, 18.5 feet north of the centerline of the gravel entrance road, 17.6 feet southwest of power pole #S409/60 with a guy wire to the northeast (3rd power pole northeast of the aluminum gate post), about 515 feet northeast of power pole # S409/59, about 1 foot above the road; a 5/8 inch rebar and a aluminum cap stamped "FLEGAL 1".

2nd Order **906.477 Feet NGVD 1929**

DNR FLEGAL 2, 2001 (Text and Elevation unverified)

In Steuben County, Hamilton Quad., in the NW ¼ of Section 28, T. 36N., R. 14E., 2nd PM; about 1.5 miles northwest of <u>Hamilton</u>; at the intersection of the south entrance to FLEGAL SAND & GRAVEL and 300 East Road, 118 feet southwest of the aluminum gate post at the entrance to FLEGAL SAND & Gravel, 29.0 feet east of the centerline of 300 East Road, 11.6 feet southwest of power pole #S409/55 with a guy wire to the west, 12.8 feet southeast of a telephone pole with a metal telephone pedestal on the south side of the pole, 25.3 feet south of the top of a large boulder, about level with the road; a 5/8 inch rebar and aluminum cap, stamped "FLEGAL 2".

906.635 Feet NGVD 1929